



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBF 5757L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	BUCKLED	1,827.00	1,827.00
1	REAR BUMPER LH SIDE RETAINER	SERVICEABLE	125.00	-
1	REAR BUMPER RH SIDE RETAINER	SERVICEABLE	125.00	-
1	REAR BUMPER CENTER BRACKET	SERVICEABLE	380.00	-
1	REAR BUMPER LOWER COVER SPOILER	DENTED	340.00	305.00
1	REAR BUMPER CENTER CHROME STRIP	CRACKED	378.00	352.00
1	REAR BUMPER LH REFLECTOR	SERVICEABLE	90.00	-
1	REAR REINFORCEMENT	TO REPAIR SEE LABOUR	566.00	-
1	REAR EXHAUST PIPE TIP LH	DENTED	567.00	430.00
2	DISTANCE SENSOR @\$250.00	SERVICEABLE	500.00	-
4	DECOUPLING RING @\$15.00	NOT NECESSARY	60.00	-
15	BUMPER RIVETS @\$8.00	NECESSARY	120.00	120.00
	LESS 10% DISCOUNT		-507.80	-303.40
			4,570.20	2,730.60
<u>SPECIAL NETT ITEMS</u>				
1	BODY SEALANT (SN)	NOT NECESSARY	80.00	-
1	REAR NUMBER PLATE & HOLDER (SN)	SERVICEABLE	50.00	-
			130.00	-
<u>LABOUR</u>				
	TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS, INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS. INCLUSIVE OF THE REPAIR OF REAR REINFORCEMENT.		1,000.00	300.00
	TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC).	NOT NECESSARY	300.00	-
	TO APPLY ANTI RUST COATING.	NOT NECESSARY	150.00	-
	TO REMOVE, REFIT & UPHOLSTERY TO FACILITATE REPAIRS.	NOT NECESSARY	150.00	-
	TO REMOVE & REPLACE BUMPER SENSORS.		60.00	60.00
	TO CHECK & RECONNECT ALL NECESSARY WIRING.		80.00	20.00

Report Ref No. CS/AGI20009862/Kyf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY PAINT ON THE AFFECTED AREAS.		1,000.00	300.00
			2,740.00	680.00
GRAND TOTAL			7,440.20	3,410.60
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,650.00

Report Ref No. CS/AGI20009862/Kyf3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.