

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/AIG20009864/UTF3Q2

**Date:** 02/11/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100492479-03

**Claimant**

**Vehicle No :** SMQ7291L

**Insured Vehicle No :** SLJ7418M

Date of Loss: 12/09/2020

Nature of Claim: TP

Claim No: 1010393486SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMQ7291L**

Make & Model: HONDA ACCORD, 1.6 (M)

Engine No: CZCC06919

Reg. Date: 29/11/2019 (Man. Year: 2019)

Chassis No: WVVWZZZAUZKW213533

Colour: White

Odometer: 23088 km

Engine Capacity: 1395 cc

Market Value/New Car

Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size: 225/45 R17

Front Left Side: Pirelli 7 mm

Rear Left Side: Pirelli 7 mm

Front Right Side: Pirelli 7 mm

Rear Right Side: Pirelli 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,189.44	855.13	334.31	28.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,140.00	540.00	600.00	52.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>2,329.44</b>	<b>1,395.13</b>	<b>934.31</b>	<b>40.11</b>

### INSPECTION

Date of Assignment: 15/09/2020

Date Inspected: 21/09/2020 Inspected At:

Unimotor Co (HQ)  
NO 1 KAKI BUKIT AVE 6 #01-94  
Singapore 417883

Estimated Period of Repair: 2.0 days

**Adjuster:** MARCUS CHUA

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

Different 1 cents -Finalise confirm amount: \$1,395.12

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT R/H SIDE WIND MIRROR ASSY	Broken	1,321.60 FL	*950.14 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (S\$)					1,321.60	950.14
- List Item Discount on L Items 10.00/10.00% (S\$)					132.16	95.01
Total Parts (S\$)					1,189.44	855.13

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO PANE LBEAT DAMAGED PORTION AND RENEW PARTS	New	400.00	200.00
2	TO PUTTY AND RESPRAY DAMAGED PORTION	New	600.00	300.00
3	TO SPRAY UNDERCOATING IN REPAIR	New	60.00	0.00
4	TO REMOVE AND REFIX REAR INTERIOR TRIM ,GARNISH IN REPAIR	New	80.00	40.00
<b>Gross Labour Cost (\$)</b>			<b>1,140.00</b>	<b>540.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**