

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20009866/GTF3E2

Date: 02/10/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00050082001	
Claimant Vehicle No :	SMT2460H	Insured Vehicle No :	GBG1818R	
Date of Loss:	12/09/2020	Nature of Claim:	TP	Claim No: SNM20D203341/C02/LOWCT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMT2460H		
Make & Model:	TOYOTA NOAH HYBRID, 1.8 X CVT (A)	Engine No:	2ZR0F19298
Reg. Date:	01/04/2020 (Man. Year: 2020)	Chassis No:	ZWR800431163
Colour:	Black	Odometer:	7251 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Goodyear 8 mm	Rear Left Side:	Goodyear 8 mm
Front Right Side:	Goodyear 8 mm	Rear Right Side:	Goodyear 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,102.50	2,339.55	4,762.95	67.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,750.00	560.00	1,190.00	68.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,852.50	2,899.55	5,952.95	67.25
+ GST 7.00/7.00% (S\$)	619.68	202.97	416.71	67.25
Nett Amount (S\$)	9,472.18	3,102.52	6,369.66	67.25

INSPECTION

Date of Assignment:	15/09/2020	
Date Inspected:	18/09/2020 Inspected At:	BW Workshop Services Pte Ltd (HQ) 291 Kaki Bukit Avenue 1, Shun Li Industrial Park Singapore 416080
Estimated Period of Repair:	3.0 days	

Adjuster: XING GUO QIANG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Oct 2020)
Parts:	M1-MPV	TOYOTA NOAH HYBRID 1.8 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMT2460H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE WINDSCREEN	Smashed	1,500.00 F	*1,237.50 F
2	2		*REAR WINDSCREEN SPACER	Not Necessary	120.00 F	*- F
3	1		*REAR TAIL LAMP (RH)	Cracked	851.25 F	*592.05 F
4	1		*REAR THIRD BRAKE LIGHT	Not Necessary	330.75 F	*- F
5	1		*REAR WIPER MOTOR	Not Necessary	1,059.75 F	*- F
6	1		*REAR WIPER COVER	Not Necessary	45.00 F	*- F
7	1		*WEATHERSTRIP	Not Necessary	476.25 F	*- F
8	1		*REAR TAILGATE HARNESS	Not Necessary	1,050.00 F	*- F
9	1		*REAR TAILGATE SWITCH	Not Necessary	263.25 F	*- F
10	1		*REAR TAILGATE LOCK	Not Necessary	596.25 F	*- F
11	1		*REAR WINDSCREEN MOULDING	Necessary	160.00 FS	*120.00 FS
12	1		*REAR WINDSCREEN SEALANT	Necessary	180.00 FS	*40.00 FS
13	2		*REAR WINDSCREEN CLIP	Not Necessary	70.00 FS	*- FS
14	1		*FRONT & BACK RECORDER	Missing	400.00 FS	*350.00 FS
Total Parts (S\$)					7,102.50	2,339.55

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGH, REFIT AND TO RENEW AFFECTED PARTS	New	360.00	250.00
2	TO PUTTY AND RESPRAY ON AFFECTED PORTION	New	540.00	0.00
3	TO REMOVE AND RENEW REAR WINDSCREEN AND CONDUCT WATER LEAK TEST	New	150.00	0.00
4	TO CHECK AND REALIGNMENT ON DOOR CATCH	New	160.00	0.00
5	TO TRANSFER TAILGATES FITTINGS	New	80.00	0.00
6	TO FOCUS TAILLAMPS. TO CHECK WIRING AND LIGHTING OPERATION	New	80.00	30.00
7	TO REMOVE AND REFIT FRONT & BACK RECORDER	New	100.00	80.00
8	TO REMOVE AND REFIT REAR WIPER MOTOR AND MECHANISM	New	80.00	0.00
9	INSTALL REAR WINDSCREEN SOLAR FILM	New	200.00	200.00
Gross Labour Cost (S\$)			1,750.00	560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >