



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2104126

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 11/06/2021
Reference CC4/FCI20009870/R1ea3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SMH 4372D
Insured Veh. SHC 2868P
Claim No. D20003721MFSH
Policy No. D-20094922MFSH
Accident Date 13/09/2020
Inspection Date 06/10/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI20009870/R1ea3q2	
			Date: 11/06/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 2868P	Veh. Inspected	SMH 4372D	
Policy No.	D-20094922MFSH	Coverage (\$)	0.00	
Claim No.	D20003721MFSH	Excess (\$)	0.00	
Assign From	RACHEL WU	Assign Date	15/09/2020	
2. Vehicle Particulars & Condition				
Make & Model	KIA CERATO 1.6(A) SX	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	KNAF3416MK5027278	Colour	GREY	
Odometer	39072 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	KUMHO	6 mm	
L/H Front Tyre	225/45 R17	KUMHO	6 mm	
R/H Rear Tyre	225/45 R17	KUMHO	6 mm	
L/H Rear Tyre	225/45 R17	KUMHO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/09/2020	Inspection Date	06/10/2020	
Survey held at	CYCLE & CARRIAGE KIA PTE LTD 209 PANDAN GARDENS SINGAPORE 609339			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMH 4372D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SUNDRY (SN)	NECESSARY	20.00	20.00
1	MIRROR ASSY-OUTSIDE RR VIEW ,LH (SN)	CRACKED	559.00	559.00
1	PANEL ASSY -FRONT DOOR ,LH (SN)	BENT	1,277.00	1,277.00
1	PANEL ASSY -REAR DOOR ,LH (SN)	BENT	1,377.00	1,377.00
1	HANDLE ASSY -DOOR OUTSIDE ,LH (SN)	SERVICEABLE	164.00	-
1	PAD -FR DR O/S HDL HINGE ,LH (SN)	NOT NECESSARY	5.00	-
1	COVER -FR DR O/S HDL LH (SN)	NOT NECESSARY	14.00	-
1	PAD -FR DR O/S HDL COVER ,LH (SN)	NOT NECESSARY	5.00	-
1	HANDLE ASSY -DOOR OUTSIDE ,LH (SN)	SCRATCHED	58.00	58.00
1	BLACK TAPE-FR DR RR ,LH (SN)	NECESSARY	13.00	13.00
1	BLACK TAPE-RR DR RR ,LH (SN)	NECESSARY	13.00	13.00
1	BLACK TAPE-RR DR FRAME RR OTR (SN)	NECESSARY	8.00	8.00
1	FILM -ANTI CHIPPG LH (SN)	NECESSARY	27.00	27.00
1	MOULDING ASSY-FRT DR FRAME (ADDITIONAL) (SN)	NECESSARY	72.00	72.00
1	MOULDING ASSY -RR FR FRAME (ADDITIONAL) (SN)	NECESSARY	50.00	50.00
			3,662.00	3,474.00
	<u>LABOUR</u>			
	RENEW WINDMIRROR LH ,FRT DOOR LH ,REAR DOOR LH, REPAIR REAR FENDER LH.		1,680.00	1,375.00
	REMOVE & INSTALL FRT DOOR TRIMS AND GLASS .		200.00	160.00
	REMOVE & INSTALL REAR DOOR TRIMS AND GLASS .		200.00	160.00
	SPRAY PAINT FOR WINDMIRROR LH ,FRT DOOR LH ,REAR DOOR LH ,REAR FENDER LH.		2,100.00	1,470.00
	CHECK WIRING & ELECTRICAL SYSTEM.		30.00	30.00
	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST.		200.00	200.00
	APPLY SEALANT FOR FRT DOOR & REAR DOOR .		80.00	80.00
			4,490.00	3,475.00
	GRAND TOTAL		8,152.00	6,949.00



RECOMMENDED COST OF REPAIRS			6,949.00
-----------------------------	--	--	----------

Report Ref No. CC4/FCI20009870/R1ea3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMH 4372D

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMH 4372D

RE-INSPECTION

