



CLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
TAN SWEET KIAT	Cust No/Name /TAN SWEET KIAT
BLK 987A JURONG WEST ST 93	Reg No/Reg Date SMH4372D*KC17/ 23/01/201
#16-553	Date In/Mileage / 0
SINGAPORE 641987	Chassis No KNAF3416MK5027278
Contact No Mobile: 96236350	Engine No G4FGJH715956
	Make/Model KIA/CERATO 1.6 A SR SX G335
	Colour/Trim ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	14/09/2020/ 09:20	Bod	442 / CocoLu	21013			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								1375 1680.00
RENEW WINDMIRROR LH, FRT DOOR LH, REAR DOOR LH, REPAIR REAR FENDER LH								
E PNT88000								160 200.00
REMOVE & INSTALL FRT DOOR TRIMS AND GLASS								
E PNT88000								160 200.00
REMOVE & INSTALL REAR DOOR TRIMS AND GLASS								
E PNT98000								1470 2100.00
SPRAY PAINT FOR WINDMIRROR LH, FRT DOOR LH, REAR DOOR LH, REAR FENDER LH,								
A 90000001								30.00
CHECK WIRING & ELECTRICAL SYSTEM								
A 10028901								200.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								
M SUNDRY								80.00
APPLY SEALANT FOR FRT DOOR & REAR DOOR								
M SUNDRY								20.00
Sundry								
M MIRROR ASSY-OUTSIDE RR VIEW, LH Cch /					1.00	559.00	00.00	559.00
M PANEL ASSY-FRONT DOOR, LH bi /					1.00	1277.00	00.00	1277.00
M PANEL ASSY-REAR DOOR, LH bf /					1.00	1377.00	00.00	1377.00
HANDLE ASSY-DOOR OUTSIDE, LH scr /					1.00	164.00	00.00	164.00
PAD-FR DR O/S HDL HINGE, LH ?					1.00	5.00	00.00	5.00
COVER-FR DR O/S HDL LH ?					1.00	14.00	00.00	14.00
PAD-FR DR O/S HDL COVER, LH ?					1.00	5.00	00.00	5.00
HANDLE ASSY-DOOR OUTSIDE, LH scr /					1.00	58.00	00.00	58.00
BLACK TAPE-FR DR RR, LH ne /					1.00	13.00	00.00	13.00
BLACK TAPE-RR DR FR, LH ne /					1.00	13.00	00.00	13.00
BLACK TAPE-RR DR FRAME RR OTR, ne /					1.00	8.00	00.00	8.00
FILM-ANTI CHIPPG LH ?					1.00	27.00	00.00	27.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Estimate

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SURVEYOR NAME: Rajesh - H090010018

Confirm & accepted by

SURVEYOR SIGNATURE: [Signature]DATE: 06/10/2020 @ 1145REMARKS: 7 days

7% GST on

Nett

8000.00

8,000.00

560.00

Total Payable

8,560.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.