

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933  
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG20009875/ABA3Q2  
**Date:** 29/03/2021

### REFERENCE

|                       |                                      |                      |              |
|-----------------------|--------------------------------------|----------------------|--------------|
| Handling Insurer:     | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:           | 1700007985   |
| Claimant Vehicle No : | SJQ1561H                             | Insured Vehicle No : | SDN8990T     |
| Date of Loss:         | 11/09/2020                           | Nature of Claim:     | TP           |
|                       |                                      | Claim No:            | 7228040086SG |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |               |
|-----------------------------|-----------------------------------|-------------|---------------|
| Reg No:                     | SJQ1561H                          | Engine No:  | INZD315751    |
| Make & Model:               | TOYOTA ALLION, 1.5 (A)            | Chassis No: | NZT2603039347 |
| Reg. Date:                  | 27/04/2009 (Man. Year: 2008)      | Odometer:   | 222787 km     |
| Colour:                     | Black                             |             |               |
| Engine Capacity:            | 1496 cc                           |             |               |
| Market Value/New Car Price: | N/A                               |             |               |
| Sum Insured (\$\$):         | <b>Market Value/New Car Price</b> |             |               |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 215/45 R17    | Rear Tyre Size:  | 215/45 R17    |
| Front Left Side:  | Yokohama 6 mm | Rear Left Side:  | Yokohama 6 mm |
| Front Right Side: | Yokohama 6 mm | Rear Right Side: | Yokohama 6 mm |

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS                                     | Repairer's                          | Adjuster's      | Difference      | Diff %       |
|----------------------------------------------------|-------------------------------------|-----------------|-----------------|--------------|
| Parts                                              | 5,069.10                            | 3,867.50        | 1,201.60        | 23.70        |
| Miscellaneous Items                                | 0.00                                | 0.00            | 0.00            |              |
| Labour                                             | 3,250.00                            | 2,170.00        | 1,080.00        | 33.23        |
| Paintwork Labour                                   | 0.00                                | 0.00            | 0.00            |              |
| Towing                                             | 0.00                                | 0.00            | 0.00            |              |
| <b>Calculated Gross Total (\$\$)</b>               | <b>8,319.10</b>                     | <b>6,037.50</b> | <b>2,281.60</b> | <b>27.43</b> |
| <b>Approved Total (Overridden) (\$\$)</b>          |                                     | <b>4,800.00</b> |                 |              |
| <b>Nett Amount (\$\$)</b>                          | <b>8,319.10</b>                     | <b>4,800.00</b> | <b>3,519.10</b> | <b>42.30</b> |
| <b>+ Car Rental (6.0 x \$S\$120.00/day) (\$\$)</b> |                                     | 720.00          |                 |              |
|                                                    | <b>Nett Liability (\$\$)</b>        | <b>5,520.00</b> |                 |              |
|                                                    | <b>Global Sum Settlement (\$\$)</b> | <b>5,300.00</b> |                 |              |

### INSPECTION

|                             |            |               |                                                                                                     |
|-----------------------------|------------|---------------|-----------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 14/09/2020 |               |                                                                                                     |
| Date Inspected:             | 14/09/2020 | Inspected At: | Advance Auto Garage (HQ)<br>23 KAKI BUKIT AVENUE 4 #04-01 AAS KAKI BUKIT CENTRE<br>Singapore 415933 |
| Estimated Period of Repair: | 6.0 days   |               |                                                                                                     |

3/29/2021

Adjuster Report

**Adjuster:** ADRIAN LING

**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

| No. | Qty | Part No. | Particulars                                 | Condition     | Repairer's | Amount     |
|-----|-----|----------|---------------------------------------------|---------------|------------|------------|
| 1   | 1   |          | *REAR BUMPER                                | Deformed      | 968.40 FL  | *968.40 FL |
| 2   | 2   |          | *REAR BUMPER SIDE HOLDER                    | Necessary     | 90.20 FL   | *90.20 FL  |
| 3   | 1   |          | *REAR BUMPER REFLECTOR                      | O/S Cracked   | 195.20 FL  | *97.60 FL  |
| 4   | 1   |          | *REAR END PANEL                             | Dented        | 584.60 FL  | *584.60 FL |
| 5   | 1   |          | *REAR END PANEL TOP GARNISH                 | Deformed      | 233.90 FL  | *233.90 FL |
| 6   | 1   |          | *REAR END PANEL ANTENNA SENSOR              | Cracked       | 157.40 FL  | *157.40 FL |
| 7   | 2   |          | *TAILLAMP                                   | Cracked       | 756.40 FL  | *756.40 FL |
| 8   | 2   |          | *TAILLAMP PANEL                             | Repair        | 470.40 FL  | *- FL      |
| 9   | 1   |          | *BOOTLID                                    | Dented        | 951.60 FL  | *951.60 FL |
| 10  | 1   |          | *BOOTLID LOCK                               | Damaged       | 225.00 FL  | *225.00 FL |
| 11  | 1   |          | *BOOTLID WEATHERSTRIPE                      | Cut           | 229.10 FL  | *229.10 FL |
| 12  | 1   |          | *TOYOTA LOGO                                | Necessary     | 48.00 FL   | *48.00 FL  |
| 13  | 1   |          | *ALLION EMBLEM                              | Necessary     | 55.00 FL   | *55.00 FL  |
| 14  | 1   |          | *SPARE TYRE PANEL TOP COVER                 | Deformed      | 292.80 FL  | *292.80 FL |
| 15  | 1   |          | *REAR EXHAUST PIPE                          | Not Necessary | 781.80 FL  | *- FL      |
| 16  | 1   |          | *REAR EXHAUST PIPE MOUNTING                 | Not Necessary | 39.00 FL   | *- FL      |
| 17  | 1   |          | *REAR NUMBER PLATE                          | Not Necessary | 30.00 FS   | *- FS      |
| 18  | 1   |          | *REAR NUMBER PLATE HOLDER                   | Necessary     | 30.00 FS   | *- FS      |
| 19  | 1   |          | *SET REAR BUMPER CLIPS                      | Necessary     | 50.00 FS   | *30.00 FS  |
| 20  | 1   |          | *SET REVERSE SENSOR                         | Damaged       | 280.00 FS  | *200.00 FS |
| 21  | 1   |          | *REAR END PANEL TOP GARNISH CLIPS<br>(1SET) | Necessary     | 20.00 FS   | *20.00 FS  |
| 22  | 1   |          | *REAR END PANEL SEALANT<br>(1SET)           | Necessary     | 60.00 FS   | *60.00 FS  |
| 23  | 2   |          | *TAILLAMP SPONGE GASKET                     | Necessary     | 40.00 FS   | *40.00 FS  |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                 |                 |
|------------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>6,588.80</b> | <b>5,040.00</b> |
| <b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b> | 1,519.70        | 1,172.50        |
| <b>Total Parts (\$\$)</b>                                  | <b>5,069.10</b> | <b>3,867.50</b> |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                      | Particulars                           | Lab.Type | Repairer's | Amount   |
|-------------------------|---------------------------------------|----------|------------|----------|
| <b>Labour Items</b>     |                                       |          |            |          |
| 1                       | PANEL BEATING ,REMOVE AND REFIT PARTS | New      | 1,200.00   | 900.00   |
| 2                       | SPRAY PAINTING TO AFFECTED AREA       | New      | 1,200.00   | 900.00   |
| 3                       | WIRING CHECK                          | New      | 50.00      | 30.00    |
| 4                       | TO APPLY TUFF COAT                    | New      | 150.00     | 80.00    |
| 5                       | TO REMOVE REVERSE SENSOR              | New      | 100.00     | 50.00    |
| 6                       | TO REMOVE AND REFIT UPHOLSTERY        | New      | 150.00     | 80.00    |
| 7                       | TO REMOVE AND REFIT EXHAUST PIPE      | New      | 150.00     | 0.00     |
| 8                       | TO TRANSFER BOOTLID FITTINGS          | New      | 150.00     | 80.00    |
| 9                       | TO REMOVE AND REFIT CAMERA            | New      | 100.00     | 50.00    |
| Gross Labour Cost (S\$) |                                       |          | 3,250.00   | 2,170.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >