Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG20009879/USF3E2

Date: 30/09/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 30001484002 Claimant Vehicle SMC3033R

Insured Vehicle No: SMA2402B No:

TP Date of Loss: 14/09/2020 Nature of Claim: Claim No: 247600

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMC3033R

Make & Model: MERCEDES-BENZ E200K, 1.8 (A) Engine No: 27195631117275 Reg. Date: 29/12/2008 (Man. Year: 2008) Chassis No: WDB2110412B380013

Colour: Odometer: 185414 km Black

Engine Capacity: 1796 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 265/35Z R18 245/40Z R18 Rear Tyre Size: Front Left Side: Rear Left Side: Michelin 6 mm Michelin 6 mm Rear Right Side: Front Right Side: Michelin 6 mm Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,861.45	4,449.09	5,412.36	54.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,680.00	620.00	1,060.00	63.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,541.45	5,069.09	6,472.36	56.08
Approved Total (Overridden) (S\$)		4,050.00		
(S\$)	11,541.45	4,050.00	7,491.45	64.91
+ GST 7.00/7.00% (S\$)	807.90	283.50	524.40	64.91
Nett Amount (S\$)	12,349.35	4,333.50	8,015.85	64.91

INSPECTION

Date of Assignment: 17/09/2020

Date Inspected: 15/09/2020 Inspected At: Fastech Auto Pte Ltd (HQ)

1 Kaki Bukit Ave 6, #01-46/48/50 Autobay

Singapore 417883

Estimated Period of Repair: 3.0 days

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen ... 30/9/2020

Adjuster Report Page 2 of 4

Adjuster: MARCUS CHUA Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Sep 2020)

Parts: 143 MERCEDES-BENZ E200K 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMC3033R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

Qty	Part No.	Particulars	Condition	Repairer's	Amount
1		*FRONT BUMPER	Distorted	1,866.20 F	*1,415.32 FL
2		*FRONT BUMPER CHROME MOULDINGS	Necessary	370.20 F	*206.00 FL
1		*SET FRONT BUMPER CLIPS & RIVET	Necessary	60.00 F	*60.00 FL
1		*FRONT BUMPER INNER RETAINER O/S	Cracked	188.20 F	*87.20 FL
1		*FRONT BUMPER REINFORCEMENT	Dented	788.00 F	*698.35 FL
1		*FRONT BUMPER FOG LAMP O/S	Not Necessary	485.50 F	*- FL
1		*FRONT BUMPER LICENCE PLATE GARNISH	Torn	166.20 F	*88.50 FL
1		*FRONT GRILLE	Scratched	855.20 F	*688.00 FL
1		*HEADLAMP ASSY O/S	Cracked	2,838.25 F	*1,655.62 FL
1		*AIR CON CONDENSER	Not Necessary	1,480.20 F	*-FL
1		*AIR CON CONDENSER SIDE GARNISH O/S	Not Necessary	102.30 F	*- FL
1		*FRONT SUPPORT PANEL	Repair	611.20 F	*-FL
1		*FRONT LICENCE PLATE	Bent	50.00 FS	*40.00 FS
anchise	part. S=SpcI	Nett. L=ListItemDisc.			
			Sub Total (S\$)	9,861.45	4,938.99
		- List Item Discount on L Items	s 0.00/10.00% (S\$)	0.00	489.90
			Total Parts (S\$)	9,861.45	4,449.09
	1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 2 1 1 1 1 1 1 1 1 1 1	1 *FRONT BUMPER 2 *FRONT BUMPER CHROME MOULDINGS 1 *SET FRONT BUMPER CLIPS & RIVET 1 *FRONT BUMPER INNER RETAINER O/S 1 *FRONT BUMPER REINFORCEMENT 1 *FRONT BUMPER FOG LAMP O/S 1 *FRONT BUMPER LICENCE PLATE GARNISH 1 *FRONT GRILLE 1 *HEADLAMP ASSY O/S 1 *AIR CON CONDENSER 1 *AIR CON CONDENSER 1 *FRONT SUPPORT PANEL 1 *FRONT LICENCE PLATE 2 anchise part. S=SpcNett. L=ListItemDisc.	1 *FRONT BUMPER CHROME MOULDINGS Necessary 1 *SET FRONT BUMPER CLIPS & RIVET Necessary 1 *FRONT BUMPER INNER RETAINER O/S Cracked 1 *FRONT BUMPER REINFORCEMENT Dented 1 *FRONT BUMPER FOG LAMP O/S Not Necessary 1 *FRONT BUMPER LICENCE PLATE GARNISH Torn 1 *FRONT GRILLE Scratched 1 *HEADLAMP ASSY O/S Cracked 1 *AIR CON CONDENSER Not Necessary 1 *AIR CON CONDENSER SIDE GARNISH O/S Not Necessary 1 *FRONT SUPPORT PANEL Repair 1 *FRONT LICENCE PLATE Bent 1 *FRONT LICENCE PLATE Bent 1 *FRONT LICENCE PLATE Sub Total (S\$) - List Item Discount on L Items 0.00/10.00% (S\$)	1 *FRONT BUMPER Distorted 1,866.20 F 2 *FRONT BUMPER CHROME MOULDINGS Necessary 370.20 F 1 *SET FRONT BUMPER CLIPS & RIVET Necessary 60.00 F 1 *FRONT BUMPER INNER RETAINER O/S Cracked 188.20 F 1 *FRONT BUMPER REINFORCEMENT Dented 788.00 F 1 *FRONT BUMPER FOG LAMP O/S Not Necessary 485.50 F 1 *FRONT BUMPER LICENCE PLATE GARNISH Torn 166.20 F 1 *FRONT GRILLE Scratched 855.20 F 1 *HEADLAMP ASSY O/S Cracked 2,838.25 F 1 *AIR CON CONDENSER Not Necessary 1,480.20 F 1 *AIR CON CONDENSER SIDE GARNISH O/S Not Necessary 102.30 F 1 *FRONT SUPPORT PANEL Repair 611.20 F 1 *FRONT LICENCE PLATE Bent 50.00 FS *anchise part. S=SpcNett. L=ListItemDisc. *Sub Total (S\$) 9,861.45 - List Item Discount on L Items 0.00/10.00% (S\$) 0.00

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CHECK WIRING	New	50.00	20.00
2	TO REFILL AIR CON GAS	New	120.00	0.00
3	TO SPRAY RUST PROOFING	New	150.00	0.00
4	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	680.00	300.00
5	TO PUTTY & SPRAY PAINTING	New	680.00	300.00
	Gross La	bour Cost (S\$)	1,680.00	620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >