

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20009883/DES3Q2

Date: 13/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070027375

Claimant
Vehicle No : SHB2343S **Insured Vehicle No :** SMS4637H

Date of Loss: 14/09/2020 Nature of Claim: TP Claim No: 7028601625SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB2343S		
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Engine No:	G4LEJU188235
Reg. Date:	02/04/2019 (Man. Year: 2018)	Chassis No:	KMHC851CVKU140349
Colour:	Yellow	Odometer:	129963 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,026.24	13,601.72	1,424.52	9.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,130.00	2,450.00	2,680.00	52.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	20,156.24	16,051.72	4,104.52	20.36
+ GST 7.00/7.00% (\$\$)	1,410.94	1,123.62	287.32	20.36
Nett Amount (\$\$)	21,567.18	17,175.34	4,391.84	20.36
+ Loss of Use (9.0 x S\$50.00/day) (\$\$)		450.00		
+ Car Rental (9.0 x S\$125.19/day) (\$\$)		1,126.71		
+ Doc/Search Fee (\$\$)		7.49		
+ Other Costs (\$\$)		80.00		
Nett Liability (\$\$)		18,839.54		

INSPECTION

Date of Assignment: 15/09/2020

Date Inspected: 15/09/2020 Inspected At:

Bifrost Auto Pte Ltd (Kaki Bukit)
8 Kaki Bukit Ave 4, #01-49, Premier @
Kaki Bukit
Singapore 415875

Estimated Period of Repair: 7.0 days

Adjuster: BRYAN TANI**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER (LH)	Dented	490.70 FL	*490.70 FL
2	1		*FRT DOOR (LH)	Dented	1,797.20 FL	*1,797.20 FL
3	1		*FRONT DOOR PROTECTOR (LH)	Cut	186.20 FL	*186.20 FL
4	1		*REAR DOOR (LH)	Dented	1,789.90 FL	*1,789.90 FL
5	1		*REAR DOOR HINGE LOWER (LH)	Not Necessary	170.50 FL	*- FL
6	1		*REAR DOOR PROTECTOR (LH)	Bent	166.20 FL	*166.20 FL
7	1		*DOOR CENTRE PILLAR OUTER (LH)	Dented	3,764.90 FL	*3,764.90 FL
8	1		*ROCKER PANEL OUTER GARNISH	Cut	715.60 FL	*715.60 FL
9	1		*REAR BUMPER	Cut	459.40 FL	*459.40 FL
10	1		*REAR BUMPER SIDE RETAINER (LH)	Serviceable	85.80 FL	*- FL
11	1		*REAR BUMPER COVER CLIPS	Necessary	22.00 FL	*22.00 FL
12	1		*REAR BUMPER SIDE UNDER (LH)	Not Necessary	123.10 FL	*- FL
13	1		*REAR FENDER (LH)	Dented	1,768.30 FL	*1,768.30 FL
14	1		*REAR TYRE RIM (LH)	Distorted	1,124.20 FL	*1,124.20 FL
15	1		*REAR WHEEL HUP-CAP (LH)	Cut	346.40 FL	*289.80 FL
16	1		*REAR WHEELBEARING & HUB ASSY	Damaged	554.00 FL	*554.00 FL
17	1		*REAR TRAILING ARM (LH)	Distorted	265.40 FL	*265.40 FL
18	1		*REAR ASSIST (LH)	Distorted	227.90 FL	*227.90 FL
19	1		*REAR SHOCK ABSORBER (LH)	Distorted	230.50 FL	*230.50 FL
20	1		*REAR SHOCK ABSORBER MOUNTING (LH)	Not Necessary	133.10 FL	*- FL
21	1		*REAR ABSORBER STOPPER (LH)	Not Necessary	137.60 FL	*- FL
22	1		*REAR ABSORBER COVER (LH)	Not Necessary	175.60 FL	*- FL
23	1		*REAR CROSSMEMBER	Distorted	1,468.70 FL	*1,468.70 FL
24	1		*STABILIZER BAR	Not Necessary	387.30 FL	*- FL
25	1		*STABILIZER LINK (LH)	Not Necessary	147.30 FL	*- FL
26	1		*REAR UPPER ARM (LH)	Distorted	239.50 FL	*239.50 FL
27	1		*REAR LOWER ARM (LH)	Distorted	393.10 FL	*393.10 FL
28	1		*REAR KNUCKLE ARM (LH)	Distorted	538.10 FL	*538.10 FL
29	1		*EMBLEM -BLUE DRIVE (LH)	Necessary	27.00 FL	*27.00 FL
30	1		*FRONT DOOR CITY CAB LOGO (LH)	Not Necessary	75.00 FS	*- FS
31	1		*FRONT DOOR COMFORT LOGO (LH)	Necessary	75.00 FS	*75.00 FS
32	1		*REAR DOOR COMFORTDELGRO & APPS STICKER (LH)	Necessary	80.00 FS	*80.00 FS
33	1		*REAR TYRE (LH)	Not Necessary	216.00 FS	*- FS
34	1		*FRONT WHEEL CAP (LH)	Cut	289.80 FL	*289.80 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 18,671.30 16,963.40
- List Item Discount on L Items 20.00/20.00% (\$\$) 3,645.06 3,361.68

Total Parts (\$\$) 15,026.24 13,601.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,400.00	1,000.00
2	SPRAY PAINTING CHARGE	New	1,200.00	900.00
3	WIRING CHARGE	New	140.00	0.00
4	TUFF KOTE	New	160.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	REMOVE/REFIX REVERSE SENSOR	New	120.00	0.00
7	REMOVE/REFIX UNDERCARRIAGE (RR)	New	400.00	150.00
8	RE-SET REAR ABS SYSTEM	New	400.00	0.00
9	TRANSFER OF DOOR MECHANISM FRONT	New	80.00	60.00
10	RE-SET FRT POWER WINDOW SYSTEM	New	200.00	0.00
11	TRANSFER OF DOOR MECHANISM REAR	New	80.00	60.00
12	RE-SET REAR POWER WINDOW SYSTEM	New	200.00	0.00
13	FOUR WHEEL ALIGNMENT	New	120.00	60.00
14	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	180.00
Gross Labour Cost (\$\$)			5,130.00	2,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >