

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20009885/QPA3Q2
Date: 19/10/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993970
Claimant Vehicle No :	SMB1415R	Insured Vehicle No :	SLQ5907U
Date of Loss:	08/09/2020	Nature of Claim:	TP
		Claim No:	4455594040SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMB1415R	Engine No:	50334930473492
Make & Model:	MAN NL320F (A22), 10.5 D (M)	Chassis No:	WMAA22ZZ3D7001994
Reg. Date:	06/01/2014 (Man. Year: 2013)	Odometer:	624873 km
Colour:	Multi-colour		
Engine Capacity:	10518 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,195.30	200.00	4,995.30	96.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,978.00	2,108.00	870.00	29.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,173.30	2,308.00	5,865.30	71.76
Approved Total (Overridden) (S\$)		2,250.00		

Nett Amount (S\$)		8,173.30	2,250.00	5,923.30	72.47
Global Sum Settlement (S\$)			0.00		

INSPECTION

Date of Assignment:	11/09/2020		
Date Inspected:	11/09/2020	Inspected At:	Strides Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	3.0 days		

Adjuster:	OI SUN PIN	Manager:	CHEW HSIAO TONG
------------------	------------	-----------------	-----------------

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL,SIDE:R6,FOR MAN A22 BUS	Repair	1,776.80 F	*- F
2	1		*PANEL,SIDE:R7,FOR MAN A22 BUS	Repair	885.50 F	*- F
3	1		*PANEL,SIDE:R8,FOR MAN A22 BUS	Repair	330.70 F	*- F
4	1		*PANEL,SIDE:R9 WITH FRAME,FOR MAN A22 BUS	Repair	710.70 F	*- F
5	1		*PANEL,SIDE:R10,FOR MAN A22 BUS	Repair	192.70 F	*- F
6	1		*WHEEL ARCH TRIM	Repair	124.20 F	*- F
7	1		*COVER:REAR TAIL LAMP ,RH ,FOR MAN A22 BUS	Repair	974.70 F	*- F
8	1		*STICKER SMRT	Missing	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	5,195.30	200.00
-------------------	----------	--------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	New	1,590.00	1,060.00
2	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	New	1,388.00	1,048.00
Gross Labour Cost (S\$)			2,978.00	2,108.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >