

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20009888/AVF3E2

Date: 25/01/2021

REFERENCE

Insured/Claimant:	LIM KIM HEONG	Policy No:	1800075552-02		
Date of Loss:	13/09/2020	Nature of Claim:	OD	Claim No:	0022984793SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGB9029R		
Make & Model:	AUDI A4, 2.0 MU TFSI (8E) (A)	Engine No:	CVK061907
Reg. Date:	28/06/2018 (Man. Year: 2018)	Chassis No:	WAUZZZF46JA170965
Colour:	Grey	Odometer:	33643 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$120,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,641.00	10,265.64	9,375.36	47.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,082.00	5,162.00	2,920.00	36.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,723.00	15,427.64	12,295.36	44.35
- Excess (S\$)	550.00	550.00	0.00	0.00
(S\$)	27,173.00	14,877.64	12,295.36	45.25
+ GST 7.00/7.00% (S\$)	1,902.11	1,041.43	860.68	45.25
Nett Amount (S\$)	29,075.11	15,919.07	13,156.04	45.25

INSPECTION

Date of Assignment:	15/09/2020		
Date Inspected:	15/09/2020	Inspected At:	24 BENOI SECTOR Repairer : Premium Automobiles Pte Ltd
Estimated Period of Repair:	6.0 days		

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	2,171.00 FS	*1,736.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	282.00 FS	*- FS
3	1		*FRONT BUMPER SECURING STRIP	N/S Bent	70.00 FS	*27.84 FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	208.00 FS	*- FS
5	1		*FRONT BUMPER AIR GUIDE - LH	Not Necessary	62.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	361.00 FS	*- FS
7	1		*FRONT BUMPER CARRIER	Not Necessary	795.00 FS	*- FS
8	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	123.00 FS	*- FS
9	1		*FOAM FILLER PIECE COVER	Not Necessary	126.00 FS	*- FS
10	1		*FRONT BUMPER GUIDE SECTION - LH	Damaged	36.00 FS	*28.48 FS
11	1		*LOCK CARRIER BRACKET	Not Necessary	136.00 FS	*- FS
12	2		*LOCK CARRIER BRACKET SUPPRORT - LH / RH	Not Necessary	56.00 FS	*- FS
13	1		*CAUTION SIGN STICKER	Not Necessary	14.00 FS	*- FS
14	1		*AIRCON STICKER	Not Necessary	8.00 FS	*- FS
15	1		*HORN - LH HIGH TONE	Not Necessary	124.00 FS	*- FS
16	1		*SPRING SHACKLE - LH	Not Necessary	29.00 FS	*- FS
17	2		*FRONT PARKING AID SENSOR (NPA)	Not Necessary	0.00 FS	*- FS
18	4		*FRONT PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
19	1		*FRONT FENDER - LH	Distorted	758.00 FS	*606.00 FS
20	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	200.00 FS	*- FS
21	1		*FRONT FENDER CLOSING ELEMENT - LH	Damaged	49.00 FS	*39.20 FS
22	1		*FRONT FENDER BRACKET - LH	Bent	35.00 FS	*27.60 FS
23	1		*DEFORMATION ELEMENT BRACKET - LH	Bent	49.00 FS	*38.80 FS
24	1		*FRONT FENDER BRACKET	Bent	31.00 FS	*24.80 FS
25	1		*FRONT FENDER BRACKET	Not Necessary	33.00 FS	*- FS
26	1		*FRONT FENDER BRACE - LH	Bent	117.00 FS	*93.60 FS
27	1		*FRONT FENDER CLOSING ELEMENT - LH	Not Necessary	33.00 FS	*- FS
28	1		*WHEEL HOUSING LINER - LH	Torn	237.00 FS	*189.20 FS
29	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	90.00 FS	*- FS
30	1		*WHEEL SPOILER	Torn	73.00 FS	*57.76 FS
31	1		*WHEEL SPOILER TRIM - LH	Not Necessary	35.00 FS	*- FS
32	1		*STONE CHIP GUARD - LH	Necessary	50.00 FS	*39.92 FS
33	1		*TOP FENDER LEDGE COVER - UPPER	Deformed	31.00 FS	*24.40 FS
34	1		*TOP FENDER LEDGE COVER - LOWER	Missing	23.00 FS	*17.68 FS
35	1		*BONNET IMPACT PROTECTION - CENTRE	Necessary	27.00 FS	*21.52 FS
36	1		*BONNET IMPACT PROTECTION - LH	Necessary	28.00 FS	*21.84 FS
37	1		*BONNET IMPACT PROTECTION - RH	Necessary	27.00 FS	*21.52 FS
38	1		*FENDER TOP INNER COVER - LH	Deformed	61.00 FS	*48.24 FS
39	1		*LED HEADLIGHT - LH	Cracked	7,693.00 FS	*6,154.40 FS
40	1		*LIFT CYLINDER - LH	Not Necessary	208.00 FS	*- FS
41	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	92.00 FS	*- FS
42	1		*REFRIGERANT LINE	Bent	165.00 FS	*131.60 FS
43	1		*REFRIGERANT LINE	Bent	245.00 FS	*196.00 FS
44	1		*REFRIGERANT LINE	Not Necessary	336.00 FS	*- FS
45	1		*REFRIGERANT PIPE	Bent	517.00 FS	*413.20 FS
46	1		*EXTERIOR MIRROR MOUNTING - LH	Not Necessary	1,077.00 FS	*- FS
47	1		*MIRROR CAP - LH	Not Necessary	261.00 FS	*- FS
48	1		*MIRROR GLASS - LH	Not Necessary	1,196.00 FS	*- FS
49	1		*FRONT ALUMINIUM RIM - LH	Not Necessary	684.00 FS	*- FS
50	1		*FRONT TYRE - LH	Cut	265.00 FS	*265.00 FS
51	1		*SUNDRIES	Necessary	300.00 FS	*40.24 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					19,641.00	10,265.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT AIR COND PIPES. TO VACUUM AND REGAS AIR COND SYSTEM	New	480.00	480.00
3	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	350.00	250.00
4	TO DISMANTLE LHS FRONT DOOR PANEL TRIM. TO REMOVE AND RENEW LHS WING MIRROR ASSY	New	350.00	280.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. TO REPAIR BONNET. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,450.00	1,000.00
6	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS FRONT DOOR	New	3,500.00	2,200.00
7	TO RENEW LHS FRONT RIM WITH TYRE. TO CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
8	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			8,082.00	5,162.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >