

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20009890/ACF3E2

Date: 12/03/2021

REFERENCE

Insured/Claimant:	PREMIUM AUTOMOBILES PTE LTD	Policy No:	0999993762
Date of Loss:	12/09/2020	Nature of Claim:	OD Claim No: 2499179713SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS4915E	Engine No:	DLH066820
Make & Model:	AUDI A6, 2.0 TFSI (A)	Chassis No:	WAUZZZF2XLN013143
Reg. Date:	27/02/2020 (Man. Year: 2019)	Odometer:	3296 km
Colour:	Black		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$170,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,656.00	7,815.84	7,840.16	50.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,672.00	3,022.00	2,650.00	46.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	21,328.00	10,837.84	10,490.16	49.18
- Excess (\$\$)	2,800.00	2,800.00	0.00	0.00
(\$\$)	18,528.00	8,037.84	10,490.16	56.62
+ GST 7.00/7.00% (\$\$)	1,296.96	562.65	734.31	56.62
Nett Amount (\$\$)	19,824.96	8,600.49	11,224.47	56.62

INSPECTION

Date of Assignment: 15/09/2020

Date Inspected: 15/09/2020 Inspected At:

24 BENOI SECTOR

Repairer : Premium Automobiles Pte Ltd

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	2,547.00 FS	*2,037.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	643.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT - CENTRE	Cracked	220.00 FS	*175.60 FS
4	1		*FRONT BUMPER ADAPTER - LH	Damaged	39.00 FS	*30.88 FS
5	1		*FRONT BUMPER REINFORCEMENT - LH	Not Necessary	110.00 FS	*- FS
6	1		*FRONT BUMPER GRILLE - LOWER CENTRE	Not Necessary	151.00 FS	*- FS
7	1		*FRONT BUMPER CLOSING ELEMENT - LOWER	Not Necessary	208.00 FS	*- FS
8	1		*FRONT BUMPER SPOILER	Not Necessary	249.00 FS	*- FS
9	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Cracked	429.00 FS	*343.20 FS
10	1		*RADIATOR AIR GUIDE - LH	Deformed	28.00 FS	*22.32 FS
11	1		*RADIATOR AIR GUIDE - LH	Not Necessary	21.00 FS	*- FS
12	1		*RADIATOR GRILLE	Not Necessary	2,192.00 FS	*- FS
13	1		*RADIATOR GRILLE COVER	Not Necessary	54.00 FS	*- FS
14	1		*CONNECTOR HOUSING BRACKET - LH	Not Necessary	28.00 FS	*- FS
15	1		*FRONT PARKING AID SENSOR (NPA)	Not Necessary	0.00 FS	*- FS
16	4		*FRONT PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
17	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	223.00 FS	*178.40 FS
18	1		*FRONT BUMPER CARRIER	Not Necessary	960.00 FS	*- FS
19	2		*FRONT BUMPER SUPPORT	Not Necessary	59.00 FS	*- FS
20	1		*FRONT BUMPER BRACKET - LH	Not Necessary	54.00 FS	*- FS
21	1		*FRONT BUMPER GUIDE SECTION - LH	Damaged	44.00 FS	*34.72 FS
22	1		*FRONT BUMPER COVER	Not Necessary	124.00 FS	*- FS
23	1		*PEDESTRIAN PROTECTION WARNING SIGN	Not Necessary	14.00 FS	*- FS
24	1		*CAUTION SIGN STICKER	Not Necessary	14.00 FS	*- FS
25	1		*FRONT FENDER - LH	Dented	1,451.00 FS	*1,160.80 FS
26	1		*FRONT FENDER BRACE - LH	Not Necessary	117.00 FS	*- FS
27	1		*FRONT FENDER BRACKET - LH UPPER	Not Necessary	43.00 FS	*- FS
28	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	42.00 FS	*- FS
29	1		*WHEEL HOUSING LINER - LH	Torn	272.00 FS	*217.20 FS
30	1		*WHEEL SPOILER - LH	Not Necessary	164.00 FS	*- FS
31	1		*STONE CHIP GUARD - LH	Necessary	50.00 FS	*39.92 FS
32	1		*HEADLIGHT MOUNTING - LH	Not Necessary	117.00 FS	*- FS
33	1		*LED HEADLIGHT - LH	Cut	4,469.00 FS	*3,575.20 FS
34	1		*LOCK COVER	Not Necessary	43.00 FS	*- FS
35	1		*FENDER TOP LEDGE SUPPORT - LH	Not Necessary	35.00 FS	*- FS
36	1		*RADIATOR AIR GUIDE - LH	Not Necessary	38.00 FS	*- FS
37	1		*RADIATOR AIR GUIDE - UPPER	Not Necessary	30.00 FS	*- FS
38	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
39	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 15,656.00 7,815.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,400.00	1,000.00
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	2,200.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,672.00	3,022.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >