

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG20009893/AVF3E2

**Date:** 14/12/2020

### REFERENCE

Insured/Claimant: TAN KAI KOK EDWIN(CHEN KAIGUO, EDWIN)

Policy No: 2100275716-08

Date of Loss: 12/09/2020

Nature of Claim: OD

Claim No: 4873620771SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMM1688L**

Make & Model: AUDI A6, 2.8 FSI MU (A)

Engine No: CHV004393

Reg. Date: 13/10/2011 (Man. Year: 2011)

Chassis No: WAUZZZ4G7BN027725

Colour: White

Odometer: 111159 km

Engine Capacity: 2773 cc

Market Value/New Car Price: S\$41,000.00

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 245/45R18

Rear Tyre Size: 245/45R18

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	12,985.00	5,017.20	7,967.80	61.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,452.00	3,372.00	5,080.00	60.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>21,437.00</b>	<b>8,389.20</b>	<b>13,047.80</b>	<b>60.87</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>8,000.00</b>		
<b>(S\$)</b>	21,437.00	8,000.00	13,437.00	62.68
<b>+ GST 7.00/7.00% (S\$)</b>	1,500.59	560.00	940.59	62.68
<b>Nett Amount (S\$)</b>	<b>22,937.59</b>	<b>8,560.00</b>	<b>14,377.59</b>	<b>62.68</b>

### INSPECTION

Date of Assignment: 15/09/2020

Date Inspected: 15/09/2020 Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 5.0 days

**Adjuster:** ADRIAN LING

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR-LH	Dented	3,684.00 FS	*2,947.20 FS
2	1		*FRONT FENDER STONE GUARD FILM-LH	Not Necessary	119.00 FS	*- FS
3	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	188.00 FS	*- FS
4	1		*FRONT DOOR OUTER SEAL	Necessary	228.00 FS	*182.00 FS
5	1		*BONDING AGENT	Not Necessary	47.00 FS	*- FS
6	1		*CLEANING SOLUTION	Not Necessary	65.00 FS	*- FS
7	1		*FRONT DOOR CATCH	Not Necessary	118.00 FS	*- FS
8	1		*EXTERIOR DOOR HANDLE TRIM PLATE-LH	Not Necessary	494.00 FS	*- FS
9	1		*DOOR HANDLE CAP	Repair	86.00 FS	*- FS
10	1		*EXTERIOR MIRROR MOUNTING-LH	Cut	1,391.00 FS	*1,112.80 FS
11	1		*EXTERIOR MIRROR HOUSING-LH	Repair	175.00 FS	*- FS
12	1		*TURN SIGNAL INDICATOR	Not Necessary	125.00 FS	*- FS
13	1		*REAR DOOR-LH	Repair	3,684.00 FS	*- FS
14	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	123.00 FS	*- FS
15	1		*REAR DOOR OUTER SEAL	Not Necessary	228.00 FS	*- FS
16	1		*BONDING AGENT	Not Necessary	47.00 FS	*- FS
17	1		*CLEANING SOLUTION	Not Necessary	65.00 FS	*- FS
18	1		*REAR DOOR CATCH	Not Necessary	118.00 FS	*- FS
19	1		*SIDE MIRROR TRIM-LH	Deformed	849.00 FS	*678.80 FS
20	1		*FRONT STONE GUARD FILM-LH	Not Necessary	117.00 FS	*- FS
21	1		*SILL PANEL TRIM CLIP	Necessary	105.00 FS	*84.00 FS
22	1		*SILL PANEL TRIM ADHESIVE TAPE	Necessary	16.00 FS	*12.40 FS
23	1		*WINDOW SLOT SEAL-LH FRONT	Not Necessary	336.00 FS	*- FS
24	1		*WINDOW SLOT SEAL-LH REAR	Not Necessary	277.00 FS	*- FS
25	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
F=Franchise part. S=SpcNett.						
					<b>Total Parts (\$\$)</b>	<b>12,985.00</b>
						<b>5,017.20</b>

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES	New	560.00	280.00
2	TO DISMANTLE AND RENEW LHS FRONT DOOR,LHS REAR DOOR AND LHS SILL PANEL TRIM.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	3,200.00	1,000.00
3	TO RESPRAY LHS FRONT DOOR,LHS REAR DOOR,LHS SILL PANEL TRIM,LHA REAR FENDER,LHS FRONT DOOR,HANDLE AND LHS WING MIRROR COVER	New	4,500.00	1,900.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>8,452.00</b>	<b>3,372.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >