



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

QBE INSURANCE (SINGAPORE) PTE LTD

INV No. AC2100038

1 RAFFLES QUAY #29-10 SOUTH TOWER
SINGAPORE 048583

INV Date 05/01/2021
Reference CC6/QBE20009894/Ura3q2
Code QBE

PROFESSIONAL SERVICE FEE

Vehicle No. SJA 5611E
Insured Veh. GBF 8614X
Claim No. VC013956
Policy No. 8-V0014946-MVA-R003
Accident Date 14/09/2020
Inspection Date 15/09/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
QBE INSURANCE (SINGAPORE) PTE LTD 1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583			Ref: CC6/QBE20009894/Ura3q2 Date: 05/01/2021 Code: QBE	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBF 8614X	Veh. Inspected	SJA 5611E	
Policy No.	8-V0014946-MVA-R003	Coverage (\$)	0.00	
Claim No.	VC013956	Excess (\$)	0.00	
Assign From		Assign Date	15/09/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA COROLLA ALTIS (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	MR053ZEC107156206	Colour	GREY	
Odometer	70742 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/70 R14	YOKOHAMA	6 mm	
L/H Front Tyre	185/70 R14	YOKOHAMA	6 mm	
R/H Rear Tyre	185/70 R14	YOKOHAMA	6 mm	
L/H Rear Tyre	185/70 R14	YOKOHAMA	6 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR & FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
Accident Date	14/09/2020	Inspection Date	15/09/2020	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJA 5611E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BOOTLID	BUCKLED	855.10	855.10
1	BOOTLID REAR LOGO	NECESSARY	48.00	48.00
1	BOOTLID '1.6' EMBLEM	NECESSARY	42.00	42.00
1	BOOTLID 'COROLLA' EMBLEM	NECESSARY	45.00	45.00
1	BOOTLID 'ALTIS' EMBLEM	NECESSARY	43.00	43.00
1	BOOTLID 'VVTI' EMBLEM	NECESSARY	42.00	42.00
1	BOOTLID OUTER GARNISH	BENT	266.10	266.10
2	BOOTLID REFLECTORS @\$184.10	CRACKED	368.20	368.20
1	BOOTLID INNER LOCK	TWISTED	109.90	109.90
1	BOOTLID WEATHERSTRIP	TWISTED	195.30	195.30
1	REAR BUMPER	DISTORTED	485.10	485.10
2	REAR BUMPER BRACKETS @\$66.50	NOT NECESSARY	133.00	-
2	REAR BUMPER SIDE RETAINERS @\$65.10	BENT	130.20	130.20
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
2	TAILLAMPS @\$340.10	CRACKED	680.20	680.20
2	TAILAMP HOUSING PANELS @\$408.00	BENT	816.20	816.20
2	TAILAMP LOWER APRON PANELS @\$115.00	BUCKLED	230.00	230.00
1	REAR END PANEL	BADLY DENTED	580.10	580.10
1	REAR END PANEL GARNISH	TWISTED	288.10	288.10
1	REAR FLOOR PANEL	CRUMPLED / BUCKLED	980.90	980.90
1	REAR FLOOR PANEL TOP BOARD	TORN	285.10	285.10
2	REAR FENDERS @\$917.40	DISTORTED	1,834.80	1,834.80
2	REAR FENDER INNER TRIMS @\$315.10	NOT NECESSARY	630.26	-
1	REAR WINDSCREEN MOULDING	NECESSARY	68.10	68.10
1	BONNET	BUCKLED	855.20	855.20
1	BONNET INNER LOCK	TWISTED	105.00	105.00
2	BONNET HINGES @\$78.10	NOT NECESSARY	156.20	-
1	BONNET LOCK	REPEATED	105.00	-
1	FRONT BUMPER	DISTORTED	522.10	488.10
2	FRONT BUMPER SIDE RETAINERS @\$45.10	NOT NECESSARY	90.20	-

Report Ref No. CC6/QBE20009894/Ura3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET FRONT BUMPER CLIPS	NECESSARY	50.00	50.00
1	FRONT BUMPER REINFORCEMENT	BENT	381.10	381.10
2	FRONT BUMPER FOG LAMPS @\$255.10	NOT NECESSARY	510.20	-
2	FRONT BUMPER FOG LAMP COVERS @\$105.00	NOT NECESSARY	210.00	-
1	FRONT BRACE PANEL	TWISTED	87.80	87.80
1	FRONT GRILLE	CRACKED	388.10	388.10
1	FRONT GRILLE LOGO	NECESSARY	68.50	68.50
2	HEADLAMPS @\$850.10	BROKEN	1,700.20	1,160.20
1	FRONT SUPPORT PANEL	BENT / TWISTED	1,388.20	1,388.20
1	AIR CON CONDENSER	NOT NECESSARY	1,389.50	-
1	RADIATOR	NOT NECESSARY	1,690.20	-
1	RADIATOR FAN COWLING	NOT NECESSARY	301.10	-
1	RADIATOR FAN MOTOR	NOT NECESSARY	458.90	-
1	RADIATOR FAN BLADE	NOT NECESSARY	99.80	-
2	FRONT FENDERS @\$655.10	BUCKLED	1,310.20	1,310.20
2	FRONT FENDER INNER SHIELDS @\$188.10	NOT NECESSARY	376.20	-
2	FRONT FENDER 'VVTI' EMBLEM @\$65.50	NOT FITTED	131.00	-
1	FRONT DOOR	TO REPAIR SEE LABOUR	998.10	-
	LESS 25% DISCOUNT		-	-3,681.45
			22,579.46	11,044.35
	<u>SPECIAL NETT ITEMS</u>			
1	REAR LICENCE PLATE (SN)	BENT	50.00	40.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	SET FLOOR PANEL INSULATOR (SN)	NOT NECESSARY	280.00	-
1	FRONT LICENCE PLATE (SN)	BENT	50.00	40.00
			760.00	370.00
	<u>LABOUR</u>			
	TO CHECK WIRING .		80.00	30.00
	TO DISMANTLE & REPLACED REVERSE SENSOR .		80.00	50.00
	TO TRANSFER BOOTLID MECHANISM .		80.00	60.00

Report Ref No. CC6/QBE20009894/Ura3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY.	NOT NECESSARY	120.00	80.00
	TO DISMANTLE & REFIX REAR WINDSCREEN .		150.00	120.00
	TO DISMANTLE & REFIX FUEL TANK .		100.00	60.00
	TO MOUNT VEHICLE ON CAR O-LINER.		380.00	-
	TO REFILL AIR CON GAS.		120.00	100.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF FRONT DOOR .		3,000.00	2,200.00
	TO PUTTY & SPRAY PAINTING.		2,800.00	1,800.00
			6,910.00	4,500.00
GRAND TOTAL			30,249.46	15,914.35

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,200.00
---	--	--	-----------------

Report Ref No. CC6/QBE20009894/Ura3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJA 5611E

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJA 5611E

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJA 5611E

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

