Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20009901/EGS3Q2

Date: 29/04/2021

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900151733 Claimant XE2086D Insured Vehicle No: SMN6170A

Vehicle No:

Date of Loss: 12/09/2020 Nature of Claim: ΤP Claim No: 9589656604SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

XE2086D Reg No:

Engine No: Make & Model: UD TRUCKS GKB85ELDHNT, 10.8 D (M) **HIDDEN** Reg. Date: (Man. Year: 1900) Chassis No: HNS979208 Odometer: 0 km

Colour: Orange

**Engine Capacity:** 0 сс Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

**General Condition:** Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 295/80 R22.5 Rear Tyre Size: 295/80 R22.5 Rear Left Side: Front Left Side: Dunlop 5 mm Dunlop 5 mm Rear Right Side: Front Right Side: Dunlop 5 mm Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	630.00	570.00	60.00	9.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	800.00	500.00	300.00	37.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S	1,430.00	1,070.00	360.00	25.17
+ GST 7.00/7.00% (\$	<b>5\$)</b> 100.10	74.90	25.20	25.17
Nett Amount (S	1,530.10	1,144.90	385.20	25.17
+ Loss of Use	(4.0 x S\$200.00/day) (S\$)	800.00		
	+ Doc/Search Fee (S\$)	7.45		

**INSPECTION** 

Date of Assignment: 15/09/2020

Date Inspected: 16/09/2020 Inspected At: Accord Auto Services Pte Ltd (Bukit

**Nett Liability (S\$)** 

Merah)

1,952.35

BLK 1009 BUKIT MERAH LANE 3,

#01-80

Singapore 159723

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE Manager: Chong Pui Lin Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

# **REPAIR DETAILS**

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER (4X4 8FT X 4.5MM)	Dented	240.00 FS	*220.00 FS	
2	2		*BUMPER TOP SUPPORT BRACKET	Bent	230.00 FS	*200.00 FS	
3	2		*SUPPORT BRACKET FLAT PLATE	Bent	160.00 FS	*150.00 FS	
F=Franchise part. S=SpcNett.							
				Total Parts (S\$)	630.00	570.00	
Report was unsubmitted during this print-out.							

Adjuster Report Page 4 of 4

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	EQUIPMENTS & LABOUR CHAGE FOR CUTTING WELDING ,CHANGING REAR BUMPER DAMAGE PARTS ,BUMPER SUPPORT & BUMPER FLAT DAMAGE PARTS AND PAINT WORKS	New	800.00	500.00
	Gross Labou	ır Cost (S\$)	800.00	500.00
	Report was unsubmitted duri	ng this print-out.		

< END OF ESTIMATES >