

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20009913/BBA3Q2

Date: 09/11/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SFF38P	Insured Vehicle No :	SHA7265G
Date of Loss: 14/09/2020	Nature of Claim: TP	Claim No: MCT20090206

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFF38P	Engine No:	2ZR1794060
Make & Model:	TOYOTA WISH, 1.8 X (A)	Chassis No:	ZGE206033180
Reg. Date:	26/01/2017 (Man. Year: 2016)	Odometer:	188417 km
Colour:	White		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,986.82	5,559.57	7,427.25	57.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,440.00	2,600.00	3,840.00	59.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,426.82	8,159.57	11,267.25	58.00
Approved Total (Overridden) (S\$)		6,300.00		
Nett Amount (S\$)	19,426.82	6,300.00	13,126.82	67.57
+ Car Rental (8.0 x S\$120.00/day) (S\$)		960.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		7,296.45		
Global Sum Settlement (S\$)		7,100.00		

INSPECTION

Date of Assignment:	16/09/2020	
Date Inspected:	16/09/2020 Inspected At:	Team Auto Pro Pte Ltd - Sin Ming (HQ) 160 Sin Ming Drive #01-14 Sin Ming Autocity Singapore 575722
Estimated Period of Repair:	7.0 days	

Adjuster: Lim Teow Guan

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 14 Oct 2020)
Parts: M1-MPV	TOYOTA WISH 1.8 X (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFF38P)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR LH	Bent	1,526.50 FL	*1,290.30 FL
2	1		*FRONT DOOR BLACK TAPE LH	Necessary	92.60 FL	*92.60 FL
3	1		*FRONT DOOR WEATHERSTRIP LH	Not Damaged	309.80 FL	*- FL
4	1		*FRONT DOOR INNER LOCK LH	Not Damaged	358.30 FL	*- FL
5	1		*FRONT DOOR LOCK STRIKER LH	Not Damaged	68.00 FL	*- FL
6	1		*FRONT DOOR FRAME RUBBER LH	Not Damaged	106.90 FL	*- FL
7	1		*FRONT DOOR TRIMBOARD LH	Not Damaged	397.90 FL	*- FL
8	1		*DOOR CENTRE PILLAR LH	Not Damaged	678.00 FL	*- FL
9	1		*REAR DOOR LH	Dented	1,467.50 FL	*1,280.70 FL
10	1		*REAR DOOR BLACK TAPE LH	Necessary	92.60 FL	*92.60 FL
11	1		*REAR DOOR WEATHERSTRIP LH	Torn	309.80 FL	*185.60 FL
12	1		*REAR DOOR INNER LOCK LH	Jammed	328.90 FL	*328.90 FL
13	1		*REAR DOOR LOCK STRIKER LH	Not Damaged	86.50 FL	*- FL
14	2		*REAR DOOR HINGE LH	Not Damaged	164.00 FL	*- FL
15	1		*REAR DOOR CHECKER ARM LH	Not Damaged	102.80 FL	*- FL
16	1		*REAR DOOR TRIMBOARD LH	Broken	397.90 FL	*397.90 FL
17	1		*REAR DOOR FRAME RUBBER LH	Not Necessary	106.90 FL	*- FL
18	1		*REAR DOOR REGULATOR LH	Bent	332.00 FL	*271.00 FL
19	1		*REAR DOOR REGULATOR MOTOR LH	Short Circuit	421.00 FL	*421.00 FL
20	1		*REAR DOOR GLASS CHANNEL LH	Dented	177.30 FL	*177.30 FL
21	1		*REAR DOOR OUTER HANDLE LH	Not Damaged	86.00 FL	*- FL
22	1		*REAR DOOR BLACK GARNISH LH	Broken (1Pc Only)	239.20 FL	*119.60 FL
23	1		*SIDE SKIRT LH	Broken	785.30 FL	*525.00 FL
24	1		*ROKER PANEL LH	Repair	615.00 FL	*- FL
25	1		*REAR FENDER LH	Dented	1,137.50 FL	*806.20 FL
26	1		*REAR FENDER INNER TRIM BOARD LH	Not Damaged	723.00 FL	*- FL
27	1		*REAR FENDER SIDE GLASS MOULDING LH	Necessary	227.60 FL	*227.60 FL
28	1		*REAR SHOCK ABSORBER LH	Not Damaged	412.50 FL	*- FL
29	1		*REAR AXLE	Not Damaged	1,688.00 FL	*- FL
30	1		*REAR WHEEL HUB WITH BEARING LH	Jammed	369.80 FL	*369.80 FL
31	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
32	1		*FRONT DOOR SEALANT	Necessary	100.00 FS	*30.00 FS
33	1		*FRONT DOOR SPEAKER	Not Damaged	210.00 FS	*- FS
34	1		*FRONT DOOR TRIMBOARD CLIPS	Necessary	50.00 FS	*30.00 FS
35	1		*DOOR CENTRE PILLAR SEALANT	Not Necessary	100.00 FS	*- FS
36	1		*REAR DOOR SEALANT	Necessary	100.00 FS	*30.00 FS
37	1		*REAR DOOR SPEAKER	Not Damaged	210.00 FS	*- FS
38	1		*REAR DOOR TRIMBOARD CLIPS	Necessary	50.00 FS	*30.00 FS
39	1		*SIDE SKIRT CLIPS	Necessary	50.00 FS	*30.00 FS
40	1		*ROKER PANEL SEALANT	Not Necessary	100.00 FS	*- FS
41	1		*REAR FENDER SEALANT	Necessary	50.00 FS	*30.00 FS
42	1		*REAR FENDER INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
43	1		*REAR FENDER SIDE GLASS SEALANT	Necessary	100.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*REAR FENDER SIDE GLASS INNER SEAL	No such part	60.00 FS	*- FS
45	1		*REAR FENDER PRIMER & CLEANER	Not Necessary	80.00 FS	*- FS
46	1		*TAILLAMP CLIPS	Not Necessary	50.00 FS	*- FS
47	1		*TAILLAMP SEAL	Not Necessary	60.00 FS	*- FS
48	1		*REAR ALLOY RIM CAP LH	Cut	180.00 FS	*80.00 FS
49	1		*REAR TYRE LH	Not Damaged	350.00 FS	*- FS
50	1		*FRONT DOOR SOUNDPROOFING MATERIAL	Necessary	200.00 FS	*100.00 FS
51	1		*REAR DOOR SOUNDPROOFING MATERIAL	Necessary	200.00 FS	*100.00 FS
52	1		*REAR FENDER SOUNDPROOFING MATERIAL	Necessary	200.00 FS	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	16,439.10	7,206.10
- List Item Discount on L Items 25.00/25.00% (S\$)	3,452.28	1,646.53
Total Parts (S\$)	12,986.82	5,559.57

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R FRONT DOOR COMPONENT	New	150.00	80.00
2	R&R DOOR CENTRE PILLAR INNER GARNISH	New	100.00	0.00
3	R&R REAR DOOR COMPONENT	New	150.00	80.00
4	R&R REAR FENDER SIDE GLASS	New	250.00	100.00
5	R&R FUEL TANK PIPE	New	150.00	80.00
6	R&R REVERSE SENSOR	New	80.00	0.00
7	R&R REAR UNDER CARRIAGE	New	300.00	120.00
8	R&R REAR TYRE AND BALANCING	New	100.00	0.00
9	WHEEL ALIGNMENT	New	120.00	60.00
10	CHECK WIRING	New	100.00	60.00
11	UPHOLSTERY	New	300.00	0.00
12	DIAGNOSTIC RESET FAULT CODE	New	300.00	0.00
13	CONDUCT WATER LEAK TEST	New	180.00	0.00
14	PANEL BEAT	New	1,800.00	800.00
15	RUST PROOFING	New	200.00	40.00
16	SPRAY PAINT	New	1,800.00	1,000.00
17	R&R FRONT DOOR SOUNDPROOFING MATERIAL	New	120.00	60.00
18	R&R REAR DOOR SOUNDPROOFING MATERIAL	New	120.00	60.00
19	R&R REAR FENDER SOUNDPROOFING MATERIAL	New	120.00	60.00
Gross Labour Cost (S\$)			6,440.00	2,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >