

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI20009918/QVF3Q2**Date:** 30/10/2020REFERENCE

China Taiping
 Handling Insurer: Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00057912000
Claimant Vehicle No : SMC2819Y **Insured Vehicle No :** SML7655Y
 Date of Loss: 13/09/2020 Nature of Claim: TP Claim No: SNM20D203352/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMC2819Y**
 Make & Model: TOYOTA PRIUS, 1.5 (A) Engine No: 2ZR8429195
 Reg. Date: 28/06/2018 (Man. Year: 2018) Chassis No: ZVW506124321
 Colour: Silver Odometer: 233623 km
 Engine Capacity: 1797 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Arivo 6 mm Rear Left Side: Arivo 6 mm
 Front Right Side: Arivo 6 mm Rear Right Side: Arivo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,620.00	3,543.15	10,076.85	73.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,030.00	1,280.00	2,750.00	68.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$)	17,650.00	4,823.15	12,826.85	72.67
Approved Total (Overridden) (\$)		3,850.00		
(\$)	17,650.00	3,850.00	13,800.00	78.19
+ GST 7.00/7.00% (\$)	1,235.50	269.50	966.00	78.19
Nett Amount (\$)	18,885.50	4,119.50	14,766.00	78.19

INSPECTION

Date of Assignment: 23/09/2020
 Date Inspected: 16/09/2020 Inspected At: 60 Jalan Lam Huat #05-68
 Repairer: My Car Consultant Pte Ltd (Ubi)
 Estimated Period of Repair: 5.0 days

Adjuster: OI SUN PIN**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 30 Oct 2020)
Parts: 144	TOYOTA PRIUS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMC2819Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Serviceable	1,211.00 FL	*- FL
2	1		*TAILGATE LOCK	Serviceable	398.20 FL	*- FL
3	1		*TAILGATE LOCK CATCH	Serviceable	89.50 FL	*- FL
4	1		*TAILGATE LOCK SENSOR	Serviceable	360.90 FL	*- FL
5	1		*TAILGATE WEATHERSTRIP	Cut	212.00 FL	*212.00 FL
6	1		*TAILGATE INNER TRIM BOARD	Serviceable	428.20 FL	*- FL
7	1		*TAILGATE OUTER GARNISH	Cracked	341.00 FL	*341.00 FL
8	1		*TAILGATE LOGO	Necessary	95.50 FL	*95.50 FL
9	1		*TAILGATE EMBLEM PRIUS	Necessary	89.40 FL	*89.40 FL
10	1		*TAILGATE EMBLEM HYBRID	Necessary	82.30 FL	*82.30 FL
11	1		*TAILGATE OUTER GARNISH	Repeated	498.00 FL	*- FL
12	1		*REAR BUMPER	Crumpled	658.00 FL	*658.00 FL
13	2		*REAR BUMPER SIDE RETAINER	Broken	224.00 FL	*224.00 FL
14	1		*REAR BUMPER REINFORCEMENT	Bent	350.50 FL	*350.50 FL
15	2		*REAR BUMPER BRACKET	Bent (1 PCS ONLY)	228.00 FL	*114.00 FL
16	1		*REAR BUMPER LIP	Scratched	512.00 FL	*512.00 FL
17	1		*REAR BUMPER REFLECTOR RH	Cracked	258.00 FL	*258.00 FL
18	1		*REAR WINDSCREEN GLASS MOULING	Serviceable	128.30 FL	*- FL
19	1		*REAR FENDER RH	Serviceable	898.00 FL	*- FL
20	1		*REAR FENDER INNER TRIM RH	Serviceable	412.00 FL	*- FL
21	1		*REAR FENDER COWLING RH	Serviceable	198.00 FL	*- FL
22	1		*TAILLAMP RH	Cracked	698.00 FL	*486.00 FL
23	2		*REAR TAILLAMP PANEL RH	Serviceable	824.00 FL	*- FL
24	2		*REAR TAILLAMP LOWER BRACKET RH	Serviceable	164.00 FL	*- FL
25	1		*REAR BUMPER FILER RH	Cut	192.00 FL	*192.00 FL
26	1		*REAR FLOOR PANEL	Serviceable	1,425.00 FL	*- FL
27	1		*REAR FLOOR PANEL TOP BOARD	Serviceable	398.00 FL	*- FL
28	1		*REAR EXHAUST PIPE	Serviceable	1,251.00 FL	*- FL
29	1		*REAR KEYLESS SENSOR	Crumpled	169.50 FL	*169.50 FL
30	1		*REAR KEYLESS SENSOR WIRE HARNESS	Serviceable	438.60 FL	*- FL
31	1		*REAR END PANEL	Dented	660.20 FL	*580.00 FL
32	1		*REAR END PANEL TOP GARNISH	Serviceable	225.10 FL	*- FL
33	1		*REAR SPARE TYRE COMPARTMENT	Serviceable	694.30 FL	*- FL
34	1		*REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
35	1		*REAR TAILGATE INNER TRIM BOARD CLIPS	Serviceable	80.00 FS	*- FS
36	1		*REAR TAILGATE OUTER GARNISH CLIPS	Serviceable	80.00 FS	*- FS
37	1		*REAR CAMERA	Serviceable	350.00 FS	*- FS
38	1		*REAR REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
39	1		*REAR FENDER INNER TRIM BOARD CLIPS LH	Serviceable	80.00 FS	*- FS
40	1		*REAR FENDER INNER TRIM BARD CLIPS RH	Serviceable	80.00 FS	*- FS
41	1		*REAR END PANEL TOP GARNISH CLIPS	Serviceable	80.00 FS	*- FS
42	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*40.00 FS
43	1		*REAR FLOOR PANEL SEALANT	Serviceable	60.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*REAR WINDSCREEN GLASS SEALANT	Serviceable	60.00 FS	*- FS
45	1		*REAR NUMBER PLATE WITH CASING	Serviceable	60.00 FS	*- FS
46	1		*REAR WINDSCREEN GLASS SOLAR FILM	Serviceable	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	16,582.50	4,634.20
- List Item Discount on L Items 20.00/25.00% (\$)	2,962.50	1,091.05
Total Parts (\$)	13,620.00	3,543.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK REAR ELECTRICAL WIRING	New	80.00	30.00
2	REMOVE AND RENEW REAR WIPER MOTOR	New	150.00	0.00
3	TO REMOVE AND RENEW REVERSE SENSOR	New	150.00	30.00
4	TO MOVE AND RENEW REAR REVERSE CAMERA	New	150.00	0.00
5	TO REMOVE AND RENEW WINDSCREEN GLASS	New	150.00	0.00
6	REMOVE AND RENEW REAR GARNISH /UPHOLSTERY	New	200.00	40.00
7	TO RESPRAY UNDERCOATING	New	150.00	40.00
8	APPLY ANTI RUST ON AFFECTED AREAS	New	200.00	40.00
9	SPRAY PAINTING ON AFFECTED AREAS	New	1,400.00	500.00
10	PANEL BEATING ON AFFECTED AREAS	New	1,400.00	600.00
Gross Labour Cost (\$\$)			4,030.00	1,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >