

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20009920/T1PA3Q2

Date: 09/02/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SME4019R	Insured Vehicle No :	SHC3403R
Date of Loss: 12/09/2020	Nature of Claim: TP	Claim No: MCT20090182

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME4019R		
Make & Model:	MAZDA 3, 1.5 SEDAN AT EU6 (A)	Engine No:	P520537501
Reg. Date:	27/09/2018 (Man. Year: 2018)	Chassis No:	JM6BN22A8J0242378
Colour:	Red	Odometer:	41417 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,797.60	1,159.90	1,637.70	58.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,700.00	1,950.00	1,750.00	47.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,497.60	3,109.90	3,387.70	52.14
+ GST 7.00/7.00% (S\$)	454.83	217.69	237.14	52.14
Nett Amount (S\$)	6,952.43	3,327.59	3,624.84	52.14
+ Car Rental (3.0 x S\$100.00/day + 7.00% GST) (S\$)		321.00		
Nett Liability (S\$)		3,648.59		

INSPECTION

Date of Assignment:	16/09/2020	
Date Inspected:	17/09/2020 Inspected At:	Trans Eurokars Pte Ltd (Sungei Kadut)
		12 Sungei Kadut Ave
		Singapore 729648
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Jan 2021)
Parts:	143	MAZDA 3 1.5 SEDAN AT EU6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SME4019R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER ,REAR	Deformed	996.70 F	*996.70 F
2	1		*REFLECTOR (L) ,REFLEX -SIDE	Not Necessary	53.00 F	*- F
3	1		*BRACKET CTR, BUMPER	Not Necessary	5.40 F	*5.40 F
4	1		*BRACKET COR,BUMPER	Not Necessary	24.90 F	*- F
5	3		*TAPE ,PROTECTOR	Necessary	25.80 F	*25.80 F
6	1		*REINF, REAR BUMPER	Not Necessary	564.20 F	*- F
7	1		*RETAINER (L) ,REAR BUMPER	Necessary	38.00 F	*38.00 F
8	4		*RIVET	Necessary	18.00 F	*18.00 F
9	1		*SENSOR ,ULTRASONIC	Not Necessary	180.80 F	*- F
10	1		*CORD ,SHORT ULTRASONIC	Not Necessary	152.80 F	*- F
11	1		*COVER (L) ,TOWING HOOK-RR	Not Necessary	16.50 F	*- F
12	4		*FASTENER	Necessary	12.00 F	*12.00 F
13	1		*RETAINER ,SENSOR	Not Necessary	15.50 F	*- F
14	1		*GASKET (R) ,RR COMB	Necessary	22.00 F	*22.00 F
15	1		*GASKET (L) ,RR COMB	Necessary	22.00 F	*22.00 F
16	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS
17	1		*REAR BUMPER SKIRT	Not Necessary	550.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					2,797.60	1,159.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER ,REPAIR ALL AREAS AFFECTED BY THE ACCIDENT	New	1,260.00	660.00
2	TO RESPRAY REAR BUMPER	New	1,260.00	630.00
3	TO CHECK & ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	150.00
4	TO TRANSFER REVERSE SENSOR	New	330.00	330.00
5	TO CARRY -OUT BODY CAVITY PRESERVATION	New	250.00	0.00
6	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	350.00	180.00
Gross Labour Cost (S\$)			3,700.00	1,950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >