

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/EGI20009921/AQF3Q2

**Date:** 29/10/2020

### REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

**Claimant**

**Vehicle No :** SLU6576M

**Insured Vehicle No :**

GBH3696G

Date of Loss: 12/09/2020

Nature of Claim:

TP

Claim No: N/A

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLU6576M**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A)

Engine No: 3ZZ4943218

Reg. Date: 09/12/2009 (Man. Year: 2009)

Chassis No: MR053ZEE106158700

Colour: Gold

Odometer: 164232 km

Engine Capacity: 1598 cc

Market Value/New Car

Price: N/A

Sum Insured (\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side: Yokohama 6 mm

Rear Left Side:

Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side:

Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                     | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                     | 11,117.20         | 3,766.39          | 7,350.81          | 66.12         |
| Miscellaneous Items                       | 0.00              | 0.00              | 0.00              |               |
| Labour                                    | 3,330.00          | 1,330.00          | 2,000.00          | 60.06         |
| Paintwork Labour                          | 0.00              | 0.00              | 0.00              |               |
| Towing                                    | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (\$\$)</b>      | <b>14,447.20</b>  | <b>5,096.39</b>   | <b>9,350.81</b>   | <b>64.72</b>  |
| <b>Approved Total (Overridden) (\$\$)</b> |                   | <b>4,000.00</b>   |                   |               |
| <b>Nett Amount (\$\$)</b>                 | <b>14,447.20</b>  | <b>4,000.00</b>   | <b>10,447.20</b>  | <b>72.31</b>  |

### INSPECTION

Date of Assignment: 16/09/2020

Date Inspected: 16/09/2020 Inspected At:

Cn Motor (HQ)

1 Kaki Bukit Ave 6 Blk C #01-41

Autobay

Singapore 417883

Estimated Period of Repair: 5.0 days

**Adjuster:** ADRIAN LING

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                                |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 28 Oct 2020)                  |
| <b>Parts:</b>        | 143                                                                                                                                                                          | TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                              |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SLU6576M)                                                                                                                                    |                                                                |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                |

### Recommended Parts

| No. | Qty | Part No. | Particulars                         | Condition     | Repairer's | Amount     |
|-----|-----|----------|-------------------------------------|---------------|------------|------------|
| 1   | 1   |          | *FRONT BUMPER                       | Distorted     | 561.85 F   | *561.85 FL |
| 2   | 10  |          | *FRONT BUMPER CLIP                  | Necessary     | 65.00 F    | *30.00 FL  |
| 3   | 1   |          | *FRONT BUMPER EMBLEM LOGO           | Necessary     | 61.75 F    | *61.75 FL  |
| 4   | 1   |          | *FRONT BUMPER TOP RUBBER            | Not Necessary | 191.60 F   | *- FL      |
| 5   | 1   |          | *FRONT BUMPER CENTRE LOWER GARNISH  | Not Necessary | 182.20 F   | *- FL      |
| 6   | 1   |          | *FRONT BUMPER REINFORCEMENT         | Not Necessary | 374.40 F   | *- FL      |
| 7   | 1   |          | *FRONT L/H BUMPER SIDE RETAINER     | Damaged       | 122.10 F   | *67.00 FL  |
| 8   | 1   |          | *FRONT L/H BUMPER FOG LAMP          | Cracked       | 374.10 F   | *281.00 FL |
| 9   | 1   |          | *FRONT L/H BUMPER FOG LAMP COVER    | Not Necessary | 174.40 F   | *- FL      |
| 10  | 1   |          | *FRONT GRILLE                       | Not Necessary | 381.45 F   | *- FL      |
| 11  | 1   |          | *FRONT GRILLE INNER                 | Cracked       | 281.75 F   | *281.75 FL |
| 12  | 1   |          | *FRONT RESONATOR BOX                | Cracked       | 325.60 F   | *141.00 FL |
| 13  | 1   |          | *FRONT RESONATOR BOX UPPER AIR DUCT | Deformed      | 186.50 F   | *68.00 FL  |
| 14  | 1   |          | *FRONT RESONATOR BOX LOWER AIR DUCT | Not Necessary | 98.20 F    | *- FL      |
| 15  | 1   |          | *FRONT L/H HEAD LAMP                | Cracked       | 625.20 F   | *625.20 FL |
| 16  | 1   |          | *FRONT L/H FENDER                   | Dented        | 581.90 F   | *581.90 FL |
| 17  | 1   |          | *FRONT L/H FENDER COWLING           | Torn          | 182.10 F   | *182.10 FL |
| 18  | 10  |          | *FRONT L/H FENDER COWLING CLIP      | Necessary     | 65.00 F    | *30.00 FL  |
| 19  | 1   |          | *FRONT L/H RIM                      | Cut           | 680.00 FS  | *450.00 FS |
| 20  | 1   |          | *FRONT L/H TYRE                     | Not Necessary | 350.00 FS  | *- FS      |
| 21  | 1   |          | *FRONT L/H LOWER ARM                | Bent          | 581.90 F   | *375.00 FL |
| 22  | 1   |          | *FRONT L/H KNUCKLE ARM              | Damaged       | 561.60 F   | *561.60 FL |
| 23  | 1   |          | *FRONT L/H KNUCKLE ARM BEARING      | Necessary     | 191.80 F   | *191.80 FL |
| 24  | 1   |          | *FRONT L/H SHOCK ABSORBER           | Bent          | 381.90 F   | *381.90 FL |
| 25  | 1   |          | *FRONT L/H DRIVE SHAFT              | Not Necessary | 1,712.40 F | *- FL      |
| 26  | 1   |          | *FRONT STEERING RACK                | Not Necessary | 1,822.50 F | *- FL      |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                           |                  |                 |
|-----------------------------------------------------------|------------------|-----------------|
| <b>Sub Total (\$\$)</b>                                   | <b>11,117.20</b> | <b>4,871.85</b> |
| <b>- List Item Discount on L Items 0.00/25.00% (\$\$)</b> | <b>0.00</b>      | <b>1,105.46</b> |
| <b>Total Parts (\$\$)</b>                                 | <b>11,117.20</b> | <b>3,766.39</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                                               | Lab.Type | Repairer's      | Amount          |
|--------------------------------|-----------------------------------------------------------|----------|-----------------|-----------------|
| <b><u>Labour Items</u></b>     |                                                           |          |                 |                 |
| 1                              | TO REMOVE & REFIT FRONT L/H UNDERCARRIAGE & STEERING RACK | New      | 380.00          | 220.00          |
| 2                              | TO CHECK WHEEL ALIGNMENT                                  | New      | 150.00          | 80.00           |
| 3                              | TO CHECK WIRING                                           | New      | 100.00          | 30.00           |
| 4                              | TUFF KOTE                                                 | New      | 150.00          | 50.00           |
| 5                              | TOWING FEE                                                | New      | 150.00          | 50.00           |
| 6                              | PANEL BEATING                                             | New      | 1,200.00        | 500.00          |
| 7                              | SPRAY PAINTING                                            | New      | 1,200.00        | 400.00          |
| <b>Gross Labour Cost (S\$)</b> |                                                           |          | <b>3,330.00</b> | <b>1,330.00</b> |

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**