

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG17020132/KEA3Q2-1

**Date:** 24/11/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100388134

**Claimant**  
**Vehicle No :** SKJ9442R **Insured Vehicle No :** SFP37P

Date of Loss: 02/10/2017 Nature of Claim: TP Claim No: 3670849612SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKJ9442R	Engine No:	CHP112442
Make & Model:	VOLKSWAGEN GOLF A7, 1.4 (A)	Chassis No:	WVWZZZAUZDW102032
Reg. Date:	28/05/2013 (Man. Year: 2013)	Odometer:	148179 km
Colour:	White		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/40Z R18	Rear Tyre Size:	225/40Z R18
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 7 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	632.99	323.48	309.51	48.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	600.00	400.00	200.00	33.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>1,232.99</b>	<b>723.48</b>	<b>509.51</b>	<b>41.32</b>
<b>+ GST 7.00/7.00% (S\$)</b>	86.31	50.64	35.67	41.33
<b>Nett Amount (S\$)</b>	<b>1,319.30</b>	<b>774.12</b>	<b>545.18</b>	<b>41.32</b>
<b>+ Loss of Use (2.0 x S\$50.00/day) (S\$)</b>		100.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>876.12</b>		
<b>Global Sum Settlement (S\$)</b>		<b>870.00</b>		

### INSPECTION

Date of Assignment: 20/10/2017

Date Inspected: 20/10/2017 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)  
Blk 1019 #01-374/382, Yishun  
Industrial Park A  
Singapore 768761

Estimated Period of Repair: 2.0 days

**Adjuster:** KENNETH KONG**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER RH FOG LAMP	Cracked	195.50 FL	*195.50 FL
2	1		*FRONT BUMPER RH FOG LAMP GARNISH WITH CHROME	Dented / Cut	45.60 FL	*45.60 FL
3	1		*FRONT BUMPER RH LOWER GRILLE WITH CHROME	Dented	118.32 FL	*118.32 FL
4	1		*FRONT GRILLE	Serviceable	343.90 FL	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>703.32</b>	<b>359.42</b>
<b>- List Item Discount on L Items 10.00/10.00% (S\$)</b>	70.33	35.94

<b>Total Parts (S\$)</b>	<b>632.99</b>	<b>323.48</b>
--------------------------	---------------	---------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REFIX FRT BUMPER & ATTACHMENTS,FRT GRILLE & REALIGN THE SAME	New	300.00	180.00
2	PUTTY & RESPRAY FRT BUMPER & ALL AFFECTED AREAS	New	300.00	220.00
<b>Gross Labour Cost (\$\$)</b>			<b>600.00</b>	<b>400.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >