

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20009925/KES3Q2
Date: 12/04/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900206949
Claimant Vehicle No :	SJG8883K	Insured Vehicle No :	SKW5362X
Date of Loss:	14/09/2020	Nature of Claim:	TP
		Claim No:	4494607972SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJG8883K		
Make & Model:	PORSCHE CAYENNE, 3.6 Tiptronic (92A) (A)	Engine No:	B07855
Reg. Date:	19/04/2011 (Man. Year: 2011)	Chassis No:	WP7ZZZ92ZBLA06874
Colour:	Metallic Grey	Odometer:	76983 km
Engine Capacity:	3598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/55 R18	Rear Tyre Size:	255/55 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,414.20	6,315.30	1,098.90	14.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,980.00	1,180.00	800.00	40.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,394.20	7,495.30	1,898.90	20.21
Approved Total (Overridden) (S\$)		6,000.00		
(S\$)	9,394.20	6,000.00	3,394.20	36.13
+ GST 7.00/7.00% (S\$)	657.59	420.00	237.59	36.13
Nett Amount (S\$)	10,051.79	6,420.00	3,631.79	36.13
+ Loss of Use (4.0 x S\$180.00/day) (S\$)		720.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		7,142.00		
Global Sum Settlement (S\$)		7,100.00		

INSPECTION

Date of Assignment:	16/09/2020		
Date Inspected:	16/09/2020	Inspected At:	Optima Werkz Pte Ltd (HQ) 6 Kung Chong Road Singapore 159143
Estimated Period of Repair:	4.0 days		

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR RH	Bent	4,255.00 FL	*4,009.00 FL
2	1		*REAR DOOR SIDE GARNISH RH	Bent / Warped	518.00 FL	*518.00 FL
3	1		*REAR DOOR SIDE GARNISH CLIPS RH	Necessary	85.00 FL	*85.00 FL
4	1		*REAR WHEEL ARCH RH	Dented	555.00 FL	*555.00 FL
5	1		*REAR WHEEL ARCH CLIPS RH	Necessary	50.00 FL	*50.00 FL
6	1		*REAR RIM RH	Dented	2,775.00 FL	*1,800.00 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (S\$)					8,238.00	7,017.00
- List Item Discount on L Items 10.00/10.00% (S\$)					823.80	701.70
Total Parts (S\$)					7,414.20	6,315.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REPAIR ,READJUST ,DISMANTLE ACCIDENT AREA	New	600.00	500.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNNING MATERIALS AT ACCIDENT AREAS & ETC	New	700.00	500.00
3	LABOUR CHARGES TO DIAGNOSE FAULTY CODE & RESET MEMORY	New	200.00	0.00
4	LABOUR CHARGES TO REMOVE & REINSTALLED REAR DOOR INNER MECHANISM & ETC BACK TO ORIGINAL OPERATIONS	New	150.00	100.00
5	TO TUFF KOTE & UNDERSEAL MATERIALS	New	150.00	0.00
6	TO WHEEL ALIGNMENT & BALANCING	New	180.00	80.00
Gross Labour Cost (\$\$)			1,980.00	1,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >