		Chin
ASS.	REO. BY:	Steve

ASSIGNMENT

From: Date:	Veh No: 585 6939A Yr Regn: 13/6/1/
Estimated Cost:	Type: M.Car / M.Cycle (Bus) / Van / Lorry / Taxl / Prime Mover /
OD (THIWS/IP RESIOD RESIEVA/INVIMV	Truck / Trailer or
To Inspect Vehicle No:	Make: Merredes CHaro
at Workshop m/s	Colour Aulti- (0/94/ AC: Insured / Std / NI / NA
of	Sp.Reading 7/8/17 T/Radio: Insured / Std / NI / NA
Insured: .	Eng/No:
Policy No. 30001193633	CNO: WEB 6280832 17 1911
Claims No 247613	Gen. Cond: Good (Fal) / Poor / Burnt
Sum Insured: Excess:	Steering: horder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modl: NII / S/RIm / S(D)A/Rim or
	Tyre Size: F: 195/80 R22.5
(Policy Condition)	R: 710/03 K/2-3
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YORD or \$
Bal. or Market Value;	
IDAC Accident Rport: Consistent? : Yes or No	R/Ral C
GIA / PR Seen: Consistent? : Yes or No	1/Bal
Est. Repairs: days Res.: Yes or No	D.O.A. $9/9/20$ mm D.O.I. $1/6/9/20$
Lum Sum: % 3 Val.: Yes or No	Survey held at SBS Transit
0.4 0.50 4.0000	Des. of Damages : Frt / (Rea) / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS Vehicle: IN / OUT	
Dale: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
NO 61A 18port	
17/09/20@11.37am revised to Jasmine Lok via Merimer	1.
Einglize is © 2.199.20 part by part 2	rongir dava
Finalize is \$ 2,188.30 part by part. 2 (red: 0; 0%)	Tepali days.
Date/Time, File Pass to? Prell. Report D	ays Of Repair: 2
) : Final Report R	esurvey No. of Trip: Survey Fee:
Dale/Time, File Return to?	Transportation:
2) Add Fee:	: Site Insp (\$)_s+RSSi
	: Interview (\$) Photos
Repaironnes:	: Tech. Invs (\$) Others
Lump Sum / LEd: Ca	: Westend (5
	YOLAL

Steve (LKK) 16/9/20, 2.00pm 83228813 P/P Stevechan@IKKauto. Com 2 days Ry Bet SH DATE: 11.09.2020

SBS Transit

SBS Transit Ltd Soon Lee Depot 28 Soon Lee Road Singapore 628083

> Mainline +65 6284 8866 Facsimile +65 6262 3055

www.sbstransit.com.sg

Company Registration No: 199206653M

Workshop Accident Repair Estimate

ACCIDENT DATE

09.09.2020

BUS REGISTRATION NUMBER

S8S6030A

ACCIDENT TIME

17:21 HRS

BUS TYPE (DD OR SD)

THIRD PARTY CLAIM AGAINST

PRIVATE CAR, SGN9170B

SECTION A:	PARTS & MATERIAL COST		
Part or Item Description	Quantity	Total Cost	
BUMPER CENTRE.REAR BUMPER COMPL	1	\$	813.30
AST ITEM		\$	-
		\$	-
		\$	-
		\$	-
		\$	
		\$	
		\$	-
		\$	-
		\$	-
		\$	4
-		\$	-
		\$	-
		\$	•
		\$	-
	TOTAL PARTS & MATERIAL COST	\$	813.3

SECTION B:	ASSESSMENT/REPAIR/SPRAY PAINT (LABOUR COST)			
Labour 651 day		\$	975.00	/
Spray Painting/Vinyl		\$	400.00	
	TOTAL LABOUR COST	\$	1,375.00	

SECTION C:	SUMMARY:————		
			2 100 20
	TOTAL REPAIR COSTS	12	2,188.30
	TOTAL DOWNTIME		1.5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Adknowledged by Repairer

MY ORIDELGRO













