

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20009934/R1TF3E2

Date: 01/10/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 2100435787
<b>Claimant Vehicle No :</b> SMH6530B	<b>Insured Vehicle No :</b> SKW4518X
Date of Loss: 11/09/2020	Nature of Claim: TP Claim No: 1129967211SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMH6530B</b>		
Make & Model:	HONDA STREAM, 1.8 L SUNROOF (A)	Engine No:	R18A13800721
Reg. Date:	26/02/2009 (Man. Year: 2008)	Chassis No:	JHMRN68809S200720
Colour:	White	Odometer:	240962 km
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/50Z R17	Rear Tyre Size:	215/50Z R17
Front Left Side:	Tourador 6 mm	Rear Left Side:	Tourador 6 mm
Front Right Side:	Tourador 6 mm	Rear Right Side:	Tourador 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment:	16/09/2020	
Date Inspected:	17/09/2020 Inspected At:	Ong Ah Pee Welding Works (HQ) BLK 1001 BUKIT MERAH LANE 3 #01-43 Singapore 159718
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*REVERSE SENSOR	Shorted	0.00 F	*- F
4	1		*REAR END PANEL	Bent	0.00 F	*- F
5	1		*REAR END PANEL TOP GARNISH	Cracked	0.00 F	*- F
6	1		*TAILGATE	Bent	0.00 F	*- F
7	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
8	1		*TAILGATE LOCK	Cut	0.00 F	*- F
9	1		*TAILGATE RUBBER	Cut	0.00 F	*- F
10	1		*SPARE TYRE PANEL	Repair	0.00 F	*- F

F=Franchise part.

<b>Total Parts (S\$)</b>	<b>0.00</b>	<b>0.00</b>
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

**< END OF ESTIMATES >**