

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20009938/DEA3Q2
Date: 19/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070058308
Claimant Vehicle No :	SHC8931A	Insured Vehicle No :	SGM3333T
Date of Loss:	15/09/2020	Nature of Claim:	TP
		Claim No:	1255746806SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC8931A	Engine No:	D4FDFU553068
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Chassis No:	KMHLB41UMGU079746
Reg. Date:	22/10/2015 (Man. Year: 2015)	Odometer:	684050 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Hankook 5 mm	Rear Left Side:	Hankook 5 mm
Front Right Side:	Hankook 5 mm	Rear Right Side:	Hankook 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,814.84	7,261.92	11,552.92	61.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,280.00	2,300.00	2,980.00	56.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,094.84	9,561.92	14,532.92	60.32
Approved Total (Overridden) (S\$)		7,650.00		

(S\$)	24,094.84	7,650.00	16,444.84	68.25
+ GST 7.00/7.00% (S\$)	1,686.64	535.50	1,151.14	68.25
Nett Amount (S\$)	25,781.48	8,185.50	17,595.98	68.25
+ Loss of Use (7.0 x S\$50.00/day) (S\$)		350.00		
+ Car Rental (7.0 x S\$114.95/day) (S\$)		804.65		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		9,347.60		

INSPECTION

Date of Assignment: 16/09/2020

Date Inspected: 16/09/2020

Inspected At:

Bifrost Auto Pte Ltd (HQ)
 Blk 9 Sector C #01-42, Sin Ming Industrial Estate
 Singapore 575644

Estimated Period of Repair: 6.0 days

Adjuster: BRYAN TANI**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER (RH)	Buckled	2,171.40 FL	*2,171.40 FL
2	1		*REAR FENDER WITH HOUSING (RH)	Not Necessary	4,736.80 FL	*- FL
3	1		*REAR FENDER UNDER SHIELD (RH)	Deformed	338.60 FL	*169.30 FL
4	1		*REAR FENDER AIR -DUCT (RH)	Not Necessary	51.60 FL	*- FL
5	1		*REAR FENDER TRIM BOARD (RH)	Not Necessary	688.75 FL	*- FL
6	1		*REAR WINDSCREEN MOULDING	Necessary	51.80 FL	*51.80 FL
7	1		*REAR DOOR (RH)	Buckled	2,201.10 FL	*2,201.10 FL
8	1		*REAR DOOR RUBBER (RH)	Serviceable	185.40 FL	*- FL
9	1		*REAR DOOR REGULATOR (RH)	Not Necessary	660.90 FL	*- FL
10	1		*REAR DOOR POWER WINDOW MOTOR	Not Necessary	386.20 FL	*- FL
11	1		*REAR DOOR LOCK ASSY	Not Necessary	468.20 FL	*- FL
12	1		*REAR DOOR TRIM BOARD (RH)	Not Necessary	743.80 FL	*- FL
13	1		*ROCKER PANEL OUTER GARNISH (RH)	Cut / Deformed	732.80 FL	*732.80 FL
14	1		*REAR TYRE RIM (RH)	Distorted	650.60 FL	*325.30 FL
15	1		*REAR TYRE WHEEL CAP	Cut	214.20 FL	*107.10 FL
16	1		*REAR WHEEL BEARING ING & HUB	Damaged	724.00 FL	*362.00 FL
17	1		*REAR TRAILING ARM (RH)	Distorted	384.00 FL	*384.00 FL
18	1		*REAR ASSIST (RH)	Distorted	219.40 FL	*219.40 FL
19	1		*REAR SHOCK ABSORBER (RH)	Distorted	683.70 FL	*341.80 FL
20	1		*REAR SHOCK ABSORBER MOUNTING (RH)	Not Necessary	162.60 FL	*- FL
21	1		*ABS SENSOR	Not Necessary	217.90 FL	*- FL
22	1		*REAR CROSS MEMBER	Not Necessary	2,021.50 FL	*- FL
23	1		*STABILIZER BAR	Not Necessary	199.60 FL	*- FL
24	1		*STABILIZER LINK	Not Necessary	85.90 FL	*- FL
25	1		*REAR UPPER ARM (RH)	Distorted	335.75 FL	*335.75 FL
26	1		*REAR LOWER ARM (RH)	Distorted	353.80 FL	*353.80 FL
27	1		*REAR KNUCKLE ARM (RH)	Distorted	545.60 FL	*545.60 FL
28	1		*FRONT DOOR (RH)	Repair	2,256.40 FL	*- FL
29	1		*REAR FENDER ADVERTISEMENT LOGO (RH)	Necessary	100.00 FS	*100.00 FS
30	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
31	1		*REAR DOOR COMFORTDELGRO & APPS STICKER (RH)	Necessary	80.00 FS	*80.00 FS
32	1		*REAR DOOR ADVERTISEMENT LOGO (RH)	Necessary	100.00 FS	*100.00 FS
33	1		*ROCKER PANEL ADVERTISEMENT (RH)	Necessary	120.00 FS	*120.00 FS
34	1		*REAR TYRE (RH)	Not Necessary	216.00 FS	*- FS
35	1		*FRONT DOOR COLOURED COMFORT LOGO	Necessary	75.00 FS	*75.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*FRONT DOOR ADVERTISEMENT LOGO	Necessary	100.00 FS	*100.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					23,309.30	8,922.15
- List Item Discount on L Items 20.00/20.00% (\$)					4,494.46	1,660.23
Total Parts (\$)					18,814.84	7,261.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,400.00	800.00
2	SPRAY PAINTING CHARGE	New	1,200.00	800.00
3	WIRING CHARGE	New	140.00	0.00
4	TUFF KOTE	New	160.00	60.00
5	TOWING CHARGE	New	80.00	0.00
6	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
7	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	80.00
8	REMOVE/REFIX UNDERCARRIAGE (RR)	New	400.00	150.00
9	RE-SET REAR ABS SYSTEM	New	400.00	0.00
10	TRANSFER OF DOOR MECHANISM FRONT	New	80.00	60.00
11	RE-SET FRT POWER WINDOW SYSTEM	New	200.00	0.00
12	TRANSFER OF DOOR MECHANISM REAR	New	80.00	60.00
13	RE-SET REAR POWER WINDOW SYSTEM	New	200.00	0.00
14	FOUR WHEEL ALIGNMENT	New	120.00	60.00
15	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	150.00
Gross Labour Cost (\$\$)			5,280.00	2,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >