

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III20009940/EPS3Q2

Date: 18/11/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015		
Claimant				
Vehicle No : SLV3486D	Insured Vehicle No :	SHC8955G		
Date of Loss: 12/09/2020	Nature of Claim:	TP	Claim No:	MCT20090204

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV3486D			
Make & Model:	BMW 520I LED NAV, 2.0 (A)	Engine No:	16535094B48B20A	
Reg. Date:	28/12/2017 (Man. Year: 2017)	Chassis No:	WBAJA12030BJ18629	
Colour:	Black	Odometer:	15183 km	
Engine Capacity:	1998 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,523.55	1,673.30	1,850.25	52.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,667.00	2,084.00	583.00	21.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,190.55	3,757.30	2,433.25	39.31
+ GST 7.00/7.00% (S\$)	433.34	263.01	170.33	39.31
Nett Amount (S\$)	6,623.89	4,020.31	2,603.58	39.31
+ Car Rental (2.0 x S\$120.00/day + 7.00% GST) (S\$)		256.80		
		4,277.11		
		Nett Liability (S\$)		

INSPECTION

Date of Assignment:	28/09/2020	
Date Inspected:	28/09/2020 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 05 Nov 2020)
Parts: 143	BMW 520I LED NAV 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV3486D)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
2	1		*REAR BUMPER CARRIER	Not Necessary	862.10 FS	*- FS
3	1		*REAR BUMPER TRIM STRIP	Not Necessary	105.70 FS	*- FS
4	1		*REAR BUMPER TOWING EYE FLAP PRIMED	Not Necessary	52.60 FS	*- FS
5	1		*REAR BUMPER PANEL PRIMED (PDC/PMA)	Dented	1,619.15 FS	*1,619.15 FS
6	1		*REAR RH REAR REFLECTOR	Broken	38.85 FS	*38.85 FS
7	1		*ULTRASONIC SENSOR BLACK	Not Necessary	249.95 FS	*- FS
8	2		*ULTRASONIC SENSOR BLACK	Not Necessary	499.90 FS	*- FS
9	3		*DECOUPING RING PDC TORQUE CONVERTER	Necessary	15.30 FS	*15.30 FS
Total Parts (S\$)					3,523.55	1,673.30

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER ,REAR BUMPE CARRIER ,ATTACHMENT ITEM CAUSE BY ACCIDENT	New	1,275.00	850.00
2	TO PAINTING REAR BUMPER	New	1,038.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
4	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION	New	177.00	150.00
			Gross Labour Cost (\$)	2,667.00
				2,084.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >