

ASS. REC. BY:

REF:

LPC/2000 9942/Kgfb

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

09

days

Res.: Yes or No

Lum Sum:

1-3.1

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

1 Est not ready

22/7 11:00 8645d (Red to 21(76.70, 77.1))

Date/Time, File Pass to?

☐

: Prel. Report

1) 26/1 11:00

☐

: Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.F. (\$) 70 6450

Days Of Repair: 9

Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Veh No:

Smm 8162R Yr Regn: 07, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Toy Vory

C.C.

1797

Colour

M. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

103503

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

ZWR80 0386855

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

APLUS

195/65R15

Cant. 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

8

mm

Rear

R/Bal.

5

mm

L/Bal.

8

mm

L/Bal.

5

mm

D.O.A.

13/9/20

D.O.I.

17/9/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

6/15/21

The U/C / Chassis frame / Body Structure affected due to collision.

Kg

AERO GARAGE PTE LTD

Blk 160, Sin Ming Drive, #08-07 Sin Ming AutoCity, Singapore 575722

Tel : 6266 9511 Fax : 6266 9512

Vehicle No : SMM8162R
Vehicle Model : Toyota Voxy

Not Authorised
L1 Reg # 6454h
Permanently After Pain

Estimate Repair Cost

No.	Qty	Parts List Items	
1	1	Front bumper 855.90	Per \$ 1,401.40 ✓
2	1	Front bumper retainer	\$ Dri 164.20 ✓
3	1	Front fender	\$ R 727.10 X
4	1	Front fender inner side garnish	\$ Sn 262.10 X
5	1	Head lamps 211	CMT \$ 2,040.80 ✓
6	1	Rear tailgate	Ry \$ 1,561.90 ✓
7	1	Rear tailgate centre logo	\$ R 68.90 ✓
8	1	Rear tailgate outer chrome handle 687	Wap \$ 769.50 ✓
9	1	Rear tailgate lock 467.60	\$ Sn 771.80 ✓
10	2	Rear tailgate hinges	\$ R 129.60 X
11	2	Rear tailgate dampers	\$ Sn 419.50 X
12	2	Rear tailgate weatherstrip	\$ R 471.60 X
13	1	Rear tailgate number plate lamp	\$ Sn 98.70 X
14	1	Rear tailgate inner top garnish	\$ Sn 652.90 X
15	2	Rear tailgate inner side garnishes	\$ Sn 783.60 X
16	1	Rear tailgate inner trim board	\$ R 619.60 ✓
17	1	Rear bumper 798.20	\$ Ry 891.60 ✓
18	1	Rear bumper retainers	Dri \$ 95.60 ✓
19	1	Rear bumper brackets	\$ R 98.90 X
20	1	Rear bumper reflectors	\$ Sn 92.90 X
21	1	Rear bumper tow cover	\$ CMT 48.90 ✓
22	1 set	Rear bumper clips	\$ R 40.00 ✓
23	2	Tail lamps	Sn \$ 1,973.80 X
24	2	Rear fender inner side trims	\$ Sn 1,979.80 X
25	1	Rear end panel 715.80	\$ Ry 918.00 ✓
26	1	Rear end panel top garnish 345	\$ Dri 352.90 ✓
27	1	Rear spare tyre compartment	\$ R 1,211.90 X
28	1	Rear spare tyre top board	\$ Sn 938.00 X
29	1	Rear exhaust silencer	\$ R 711.60 X
30	1	Rear exhaust silencer mounting	\$ Sn 89.60 X
Total			\$ 20,386.70

Parts Special Nett Items

31	1	Rear number plate	\$ Sn 60.00 X
32	1 set	Reverse sensor	\$ CMT 300.00 2005N
33	1	Reverse camera	\$ Sn 250.00 X
			\$ 610.00
Total Parts			\$ 20,996.70

Labour

1	Labour charge to remove, cut out damage portion, jack out, straighten, panel beating, welding, align and renew replaced parts.	\$	3,200.00	700l
2	To putty and respray painting on affected areas.	\$	2,200.00	660l
3	To remove, replace rear tailgate fittings to facilitate repair.	\$	350.00	60l
4	To remove, replace rear windscreen glass.	\$	200.00	120l
5	To remove, replace reverse camera.	\$	200.00	60l
6	To remove, replace reverse sensor.	\$	150.00	50l
7	To remove, replace rear exhaust silencer.	uns	250.00	X
8	To check wiring and lightings.	\$	80.00	20l

Total Labour \$ 6,630.00

Total Parts and Labour \$ 27,626.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/inter-spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: