

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20009943/KGA3Q2

Date: 29/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800002490

Claimant
Vehicle No : SKA8422C **Insured Vehicle No :** SLW417T

Date of Loss: 15/09/2020 Nature of Claim: TP Claim No: 9071917727SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKA8422C		
Make & Model:	TOYOTA VIOS, 1.5 J (A)	Engine No:	1NZY075722
Reg. Date:	06/04/2011 (Man. Year: 2010)	Chassis No:	MR053HY9305160536
Colour:	Metallic Grey	Odometer:	237195 km
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Linglong 2 mm	Rear Left Side:	Falken 2 mm
Front Right Side:	Linglong 2 mm	Rear Right Side:	Falken 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,778.31	4,165.20	2,613.11	38.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,650.00	1,990.00	660.00	24.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,428.31	6,155.20	3,273.11	34.72
Approved Total (Overridden) (S\$)		3,200.00		
(S\$)	9,428.31	3,200.00	6,228.31	66.06
+ GST 7.00/7.00% (S\$)	659.98	224.00	435.98	66.06
Nett Amount (S\$)	10,088.29	3,424.00	6,664.29	66.06
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,031.45		

INSPECTION

Date of Assignment: 16/09/2020

Date Inspected: 17/09/2020 Inspected At:

Wega Engineering Pte Ltd (HQ)
BLK 176 Sin Ming Drive #04-16, Sin
Ming AutoCare
Singapore 57521

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Bent	486.30 F	*486.30 FL
2	1		*FRONT BONNET HINGE LH	Bent	75.40 F	*75.40 FL
3	1		*FRONT BONNET HINGE RH	Bent	75.40 F	*75.40 FL
4	1		*FRONT LOCK	Distorted	107.40 F	*107.40 FL
5	1		*FRONT FENDER RH	Bent	397.70 F	*397.70 FL
6	1		*FRONT WHEEL HOUSE RH	Repair	380.26 F	*- FL
7	1		*FRONT HEADLAMP RH	Broken	472.70 F	*472.70 FL
8	1		*FPRNT BUMPER	Torn	457.00 F	*457.00 FL
9	1		*FPRNT BUMPER RETAINER RH	Cracked	56.31 F	*56.31 FL
10	1		*FRONT SUPPORT PANEL	Bent	599.20 F	*599.20 FL
11	1		*FRONT BUMPER FOG LAMP COVER RH	Cracked	78.93 F	*78.93 FL
12	1		*FRONT BUMPER REINFORCEMENT	Bent	340.30 F	*340.30 FL
13	1		*FRONT EMBLEM FENDER (VVT-I)	Necessary	45.00 F	*45.00 FL
14	1		*FRONT GRILLE EMBLEM (TOYOTA)	Necessary	35.40 F	*35.40 FL
15	1		*FRONT INNER SHIELD FENDER RH	Distorted	144.50 F	*144.50 FL
16	1		*WIPER GARNISH	Cracked	594.55 F	*594.55 FL
17	1		*WIPER TANK	Dented	146.50 F	*146.50 FL
18	1		*WIPER TANK MOTOR	Serviceable	179.40 F	*- FL
19	1		*FRONT TYRE WHEEL RIM RH	Dented	456.00 F	*456.00 FL
20	1		*FRONT TYRE RH (20%)	Cut	135.00 FS	*27.00 FS
21	1		*FRONT ABSORBER RH	Bent	382.40 F	*382.40 FL
22	1		*FRONT LOWER ARM RH	Serviceable	422.05 F	*- FL
23	1		*FRONT WHEEL BEARING RH	Necessary	123.59 F	*123.59 FL
24	1		*FRONT KNUCKLE RH	Bent	443.02 F	*443.02 FL
25	1		*FRONT ENGINE UNDER COVER RH	Serviceable	144.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,778.31	5,544.60
- List Item Discount on L Items 0.00/25.00% (\$)	0.00	1,379.40
Total Parts (\$)	6,778.31	4,165.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING FEE	New	200.00	60.00
2	TO 4 WHEEL ALIGNMENT	New	150.00	60.00
3	TO CHECKING WIRING SYSTEM	New	100.00	20.00
4	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	100.00	90.00
5	TO REMOVE & REFIX UNDERCARRIAGE	New	300.00	160.00
6	TO REPAIR FRONT PORTION, BONNET ,BUMPER ,FENDER RH & WHEEL HOUSE	New	800.00	700.00
7	TO RESPRAY FRONT BONNET ,BUMPER ,FENDER RH ,FENDER RH N WHEEL HOUSE	New	1,000.00	900.00
Gross Labour Cost (\$\$)			2,650.00	1,990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >