

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III20009949/APA3Q2
Date: 05/03/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0006751
Claimant Vehicle No :	SFN99X	Insured Vehicle No :	SLU4015D
Date of Loss:	15/09/2020	Nature of Claim:	TP
		Claim No:	MFL2020D0001812

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFN99X	Engine No:	CKH014521
Make & Model:	BENTLEY CONTINENTAL, 6.0 FS (A)	Chassis No:	SCBBE53W9DC082440
Reg. Date:	16/11/2012 (Man. Year: 2012)	Odometer:	96433 km
Colour:	Silver		
Engine Capacity:	5998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/40 R19	Rear Tyre Size:	275/40 R19
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	56,359.80	40,853.20	15,506.60	27.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,700.00	3,540.00	2,160.00	37.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	62,059.80	44,393.20	17,666.60	28.47
Approved Total (Overridden) (\$\$)		32,000.00		
Nett Amount (\$\$)	62,059.80	32,000.00	30,059.80	48.44
+ Loss of Use (12.0 x S\$240.00/day) (\$\$)		2,880.00		
	Nett Liability (\$\$)	34,880.00		

INSPECTION

Date of Assignment:	16/09/2020	
Date Inspected:	16/09/2020	Inspected At: Advance Auto Garage 10 Kaki Bukit Road 2, #01-21 First East Centre Singapore 417868
Estimated Period of Repair:	10.0 days	

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

3/5/2021

Adjuster Report

any other liability under any other circumstances is hereby expressly excluded.

SPECIAL REMARKS

Market Value: \$190,000.00 (est) less LTA Rebate: \$130,214.00 (est) = Nett Value :\$59,786.00 (est)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Jan 2021)
Parts:	143	BENTLEY CONTINENTAL 6.0 FS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFN99X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR NUMBER PLATE LAMP	Cracked	208.00 FL	*208.00 FL
2	1		*REAR BUMPER	Distorted	8,353.00 FL	*8,353.00 FL
3	2		*REAR BUMPER SIDE HOLDER	Not Necessary	590.00 FL	*- FL
4	1		*REAR BUMPER REINFORCEMENT	Bent	1,994.00 FL	*1,994.00 FL
5	2		*REAR BUMPER REINFORCEMENT BRACKET	Bent	694.00 FL	*694.00 FL
6	2		*REAR BUMPER CHROME MOULDING	Necessary	3,678.00 FL	*970.00 FL
7	1		*REAR BUMPER SPONGE	Cracked	715.00 FL	*505.00 FL
8	1		*REAR BUMPER EXHAUST TAIL PIPE	O/S Dented	1,408.00 FL	*704.00 FL
9	1		*REAR BUMPER EXHAUST TAIL PIPE BRACKET	O/S Bent	110.00 FL	*55.00 FL
10	1		*REAR BUMPER UNDERCOVER	Distorted	772.00 FL	*772.00 FL
11	1		*REAR BUMPER LOWER GARNISH	Distorted	1,965.00 FL	*1,965.00 FL
12	1		*REAR BUMPER REVERSE LAMP	O/S Cracked	1,306.00 FL	*653.00 FL
13	1		*REAR BUMPER CAMERA	Damaged	695.00 FL	*695.00 FL
14	1		*REAR BUMPER CENTRE BRACKET	Cracked	424.00 FL	*424.00 FL
15	2		*REAR BUMPER REVERSE SENSOR	Damaged	1,772.00 FL	*1,772.00 FL
16	2		*REAR BUMPER REVERSE SENSOR HOLDER	Necessary	136.00 FL	*136.00 FL
17	1		*REAR END PANEL	Dented	1,473.00 FL	*1,473.00 FL
18	1		*REAR END PANEL TOP GARNISH	Not Necessary	458.00 FL	*- FL
19	1		*TAILLAMP	O/S Cracked	8,138.00 FL	*4,069.00 FL
20	1		*BOOTLID	Dented	18,030.00 FL	*18,030.00 FL
21	1		*BOOTLID LOCK	Damaged	895.00 FL	*895.00 FL
22	1		*BOOTLID WEATHERSTRIPE	Not Necessary	675.00 FL	*- FL
23	1		*BENTLEY LOGO	Necessary	581.00 FL	*581.00 FL
24	1		*SPARE TYRE PANEL TOP COVER	Not Necessary	938.00 FL	*- FL
25	1		*TOOLS TRAY SPONGE	Not Necessary	785.00 FL	*- FL
26	1		*REAR EXHAUST PIPE	Repair	5,144.00 FL	*- FL
27	1		*REAR EXHAUST PIPE MOUNTING	Not Necessary	185.00 FL	*- FL
28	1		*REAR NUMBER PLATE	Necessary	100.00 FS	*100.00 FS
29	1		*SET REAR BUMPER CLIPS	Necessary	100.00 FS	*100.00 FS
30	1		*SET REAR BUMPER UNDERCOVER CLIPS	Necessary	100.00 FS	*100.00 FS
31	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
32	1		*SET REAR END PANEL SEALANT	Necessary	100.00 FS	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	62,572.00	45,348.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	6,212.20	4,494.80
Total Parts (\$\$)	56,359.80	40,853.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVE AND REFIT PARTS	New	2,000.00	1,400.00
2	SPRAY PAINTING TO AFFECTED AREA	New	2,000.00	1,250.00
3	WIRING CHECK	New	200.00	50.00
4	TO APPLY TUFF COAT	New	200.00	100.00
5	TO REMOVE REVERSE SENSOR	New	150.00	100.00
6	TO REMOVE REAR CAMERA	New	150.00	100.00
7	TO REMOVE UPHOLSTERY	New	200.00	120.00
8	TO TRANSFER BOOTLID FITTINGS	New	250.00	120.00
9	TO REMOVE EXHAUST PIPE	New	250.00	150.00
10	TO PERFORM DIANOGSTIC TEST	New	300.00	150.00
Gross Labour Cost (\$\$)			5,700.00	3,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >