

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20009958/T1RA3Q2
Date: 08/07/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100286102	
Claimant Vehicle No :	SHA5318B	Insured Vehicle No :	SFL658T	
Date of Loss:	16/09/2020	Nature of Claim:	TP	Claim No: 6015682742SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA5318B		
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Engine No:	D4FDGU706873
Reg. Date:	25/01/2017 (Man. Year: 2016)	Chassis No:	KMHLB41UMHU098297
Colour:	Blue	Odometer:	409734 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,872.28	1,962.84	4,909.44	71.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,870.00	1,360.00	510.00	27.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,742.28	3,322.84	5,419.44	61.99
Approved Total (Overridden) (S\$)		2,650.00		

(S\$)	8,742.28	2,650.00	6,092.28	69.69
+ GST 7.00/7.00% (S\$)	611.96	185.50	426.46	69.69
Nett Amount (S\$)	9,354.24	2,835.50	6,518.74	69.69
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.0 x S\$112.67/day) (S\$)		338.01		
(S\$)		3,323.51		
Liabe Amount (50.00%) (S\$)		1,661.76		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,663.76		

INSPECTION

Date of Assignment: 17/09/2020

Date Inspected: 17/09/2020

Estimated Period of Repair: 3.0 days

 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)
 59 Loyang Drive
 Singapore 508969
Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,052.20 FL	*- FL
2	1		*FRONT BUMPER BRACKET RH	Not Necessary	24.60 FL	*- FL
3	1		*FRONT RH WING MIRROR	Distorted	670.00 FL	*670.00 FL
4	1		*FRT DOOR OUTER MOULDING	Cut	53.10 FL	*53.10 FL
5	1		*HEADLAMP RH	Not Necessary	1,388.00 FL	*- FL
6	1		*HEAD LAMP SUPPORT PANEL	Not Necessary	907.40 FL	*- FL
7	1		*FRONT FENDER SHIELD RH	Not Necessary	174.90 FL	*- FL
8	1		*FRONT FENDER RH	Bent	663.00 FL	*663.00 FL
9	1		*FRONT S/ABSORBER RH	Not Necessary	342.00 FL	*- FL
10	1		*FRONT S/ABSORBER MTG	Not Necessary	217.60 FL	*- FL
11	1		*FRONT SUSPENSION LOWER ARM RH	Not Necessary	595.90 FL	*- FL
12	1		*FRT RH KNUCKLE ARM	Not Necessary	1,104.00 FL	*- FL
13	1		*FRT RH STRG TIE ROD	Not Necessary	135.00 FL	*- FL
14	1		*FRT RH STRG TIE BALL JOINT	Not Necessary	73.10 FL	*- FL
15	1		*FRT RH STABILIZER LINK	Not Necessary	68.10 FL	*- FL
16	1		*FRONT WHEEL RIM RH	Bent	650.60 FL	*650.60 FL
17	1		*FRONT WHEEL COVER RH	Cracked	107.10 FL	*107.10 FL
18	1		*FRONT DOOR COMFORT LOGO STICKER	Necessary	75.00 FS	*75.00 FS
19	1		*FRT RH TYRE HANKOOK (80%)	Punctured	216.00 FS	*172.80 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,517.60	2,391.60
- List Item Discount on L Items 20.00/20.00% (\$)	1,645.32	428.76
Total Parts (\$)	6,872.28	1,962.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	720.00	560.00
2	SPRAY PAINTING CHARGE	New	640.00	600.00
3	REMOVE/REPLACE FRT UNDER SUSPENSION	New	120.00	0.00
4	REMOVE/REFIX RADIATOR	New	90.00	0.00
5	RESET FRONT WHEEL ALIGNMENT	New	90.00	80.00
6	TOWING FEES	New	60.00	60.00
7	TUFF KOTE	New	90.00	30.00
8	CHECK LIGHTING	New	60.00	30.00
Gross Labour Cost (S\$)			1,870.00	1,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >