

(08/11/13) wef

ASS. REC. BY: *Marcus*

REF:

CC6/ A1620009959/4ba3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (M/ (Refrigerated)

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal.

L/Bal.

D.O.I.

Date / Time

Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐

: Preli. Report

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) ___ S + RS, ___ SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

21/9/20 4/5 \$3500 confirmed with Susan

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: YP3691E200915

Estimate**Customer**

Name: AIG Asia Pacific Insurance Pte Ltd

Address: Motor Claims Department

78 Shenton Way #07-16

AIG Building Singapore 079120

Date: 16-09-20

Vehicle No: YP3691E

Model/Make: Mitsubishi
FEB21CR4SDEB

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front Rh Door	\$ 2,001.50	X
2	Door Hinges 02 pcs (@ \$109.10)	\$ 218.20	X
3	Door View Mirror	\$ 112.50	X
4	Corner Panel	\$ 474.60	X
5	Signal Lamp	\$ 324.30	X
6	Signal Lamp Clips 01 set	\$ 20.00	SN X
7	Side Lamp	\$ 235.20	X
8	Head Lamp	\$ 856.40	X
9	Head Lamp Clips 01 set	\$ 30.00	SN X
10	Bumper	\$ 1,133.40	X
11	Bumper Clips 1 set	\$ 50.00	SN X
12	Bumper Side	\$ 375.00	X
13	Bumper Side Clips 01 set	\$ 45.00	SN
	To check all wiring & electrical component for proper function	\$ 40.00	-
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 520.00	-
	To putty & spray painting & including touch up paint on accident affected	\$ 680.00	-
	To remove, replace and transfer door panel, fitting and mechanisms	\$ 80.00	-
	To apply Rust Proofing , reseal tuff-coating treatment on accident area	\$ 60.00	-

Total Parts & Labour of estimate for damaged vehicle

\$ 7,256.10

Total amount in Lump Sum Basis for repaired vehicle

SDLS:

M/s Liu's Brother Auto Engrg Wks

not Authorized
note
2/5 \$3500/
17/9/20
3 days
Liu's. Jasper

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 4389.11
25%
P- 3269.33
SN- 45.00
L- 1070.00
4389.33
202
3507