

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG20009963/UPA3Q2

**Date:** 07/01/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100476793

**Claimant**  
**Vehicle No :** SJT1259R **Insured Vehicle No :** SLE5137M

Date of Loss: 15/09/2020 Nature of Claim: TP Claim No: 2787210253SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJT1259R		
Make & Model:	MERCEDES-BENZ E250, 1.8 CGI (A)	Engine No:	27186030003078
Reg. Date:	24/09/2009 (Man. Year: 2009)	Chassis No:	WDD2120472A074010
Colour:	Grey	Odometer:	180097 km
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

### CONDITION OF TYRES

Front Tyre Size:	225/50ZR17	Rear Tyre Size:	225/50ZR17
Front Left Side:	SpeedeX 6 mm	Rear Left Side:	SpeedeX 6 mm
Front Right Side:	SpeedeX 6 mm	Rear Right Side:	SpeedeX 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,573.00	1,905.50	1,667.50	46.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,030.00	450.00	580.00	56.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>4,603.00</b>	<b>2,355.50</b>	<b>2,247.50</b>	<b>48.83</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>1,800.00</b>		
<b>Nett Amount (\$\$)</b>	<b>4,603.00</b>	<b>1,800.00</b>	<b>2,803.00</b>	<b>60.90</b>
<b>+ Loss of Use (2.0 x \$S\$100.00/day) (\$\$)</b>		200.00		
		<b>(S\$) 2,000.00</b>		
<b>Liabe Amount (80.00%) (\$\$)</b>		<b>1,600.00</b>		
<b>+ Doc/Search Fee (\$\$)</b>		7.45		
<b>Nett Liability (\$\$)</b>		<b>1,607.45</b>		
<b>Global Sum Settlement (\$\$)</b>		<b>1,600.00</b>		

### INSPECTION

Date of Assignment: 17/09/2020

Date Inspected: 17/09/2020 Inspected At:

Super-zee Motor Service (HQ)  
BLK 14 DEFU LANE 10, #01-402  
Singapore 539195

Estimated Period of Repair: 2.0 days

---

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	1,815.80 F	*1,635.22 FL
2	1		*REAR BUMPER MOULDING (1 SET) (3 PCS)	Necessary	486.20 F	*422.00 FL
3	1		*REAR BUMPER RETAINER RH	Not Necessary	65.80 F	*- FL
4	1		*REAR BUMPER BRACKET RH	Not Necessary	45.60 F	*- FL
5	1		*REAR BUMPER TOWING COVER	Not Necessary	75.20 F	*- FL
6	10		*REAR BUMPER CLIPS	Necessary	75.00 F	*60.00 FL
7	1		*TAILLAMP RH	Not Necessary	690.40 F	*- FL
8	1		*REVERSE SENSOR	Not Necessary	319.00 F	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>3,573.00</b>	<b>2,117.22</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$)</b>	0.00	211.72
<b>Total Parts (\$)</b>	<b>3,573.00</b>	<b>1,905.50</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO DISMANTLE & REPLACE DAMAGED PARRTS, PANELBEAT WHERE NECESSARY	New	400.00	200.00
2	TO PUTTY, APPLY PRIMER & SPRAY PAINT AFFECTED PORTION	New	450.00	200.00
3	TO APPLY RUSTPROOFING ON REPAIRED, REPLACED PANEL	New	100.00	0.00
4	TO CHECK ELECTRICAL WIRING FUNCTIONS	New	80.00	50.00
<b>Gross Labour Cost (S\$)</b>			<b>1,030.00</b>	<b>450.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >