

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20009966/AQF3E2

Date: 26/02/2021

REFERENCE

Insured/Claimant:	LEE YEE PING	Policy No:	2000002554		
Date of Loss:	16/09/2020	Nature of Claim:	OD	Claim No:	0789723852SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR6727Z		
Make & Model:	AUDI Q3, 1.4 TFSI (A)	Engine No:	CZD886648
Reg. Date:	17/01/2020 (Man. Year: 2019)	Chassis No:	WAUZZZF30L1018349
Colour:	Grey	Odometer:	7085 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$140,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65 R17	Rear Tyre Size:	215/65 R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,615.00	8,326.88	7,288.12	46.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,332.00	4,752.00	4,580.00	49.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	24,947.00	13,078.88	11,868.12	47.57
+ GST 7.00/7.00% (S\$)	1,746.29	915.52	830.77	47.57
Nett Amount (S\$)	26,693.29	13,994.40	12,698.89	47.57

INSPECTION

Date of Assignment:	17/09/2020		
Date Inspected:	17/09/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	7.0 days		

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	2,045.00 FS	*1,634.80 FS
2	1		*FRONT BUMPER CLOSING ELEMENT - RH	Not Necessary	58.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE - RH	Not Necessary	109.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	188.00 FS	*- FS
5	1		*FRONT SPOILER	Scratched	379.00 FS	*303.20 FS
6	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Cut	151.00 FS	*120.80 FS
7	1		*FRONT BUMPER GUIDE SECTION - RH	Damaged	38.00 FS	*30.16 FS
8	1		*FRONT FENDER - RH	Distorted	1,271.00 FS	*1,016.80 FS
9	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	62.00 FS	*- FS
10	1		*FRONT FENDER BRACE - RH	Bent	87.00 FS	*68.96 FS
11	1		*FRONT FENDER BRACKET - RH	Bent	31.00 FS	*24.56 FS
12	1		*FRONT FENDER DAMPING - RH UPPER	Not Necessary	31.00 FS	*- FS
13	1		*DAMPING SEAL	Not Necessary	36.00 FS	*- FS
14	1		*FRONT FENDER CLOSING ELEMENT - RH	Not Necessary	33.00 FS	*- FS
15	1		*FRONT FENDER INSULATION - RH	Not Necessary	42.00 FS	*- FS
16	1		*FRONT WHEEL HOUSING LINER - RH	Torn	237.00 FS	*189.20 FS
17	1		*WHEEL HOSUING LINER ATTACHMENT PARTS	Not Necessary	100.00 FS	*- FS
18	1		*WHEEL HOUSING LINER COVER - RH	Not Necessary	16.00 FS	*- FS
19	1		*WHEEL HOUSING LINER CLOSING ELEMENT - RH	Not Necessary	19.00 FS	*- FS
20	1		*HEADLIGHT MOUNTING - RH	Cracked	117.00 FS	*93.60 FS
21	1		*LED HEADLIGHT - RH	Cracked	5,526.00 FS	*4,420.80 FS
22	1		*LIFT CYLINDER - RH	Not Necessary	208.00 FS	*- FS
23	2		*FRONT WHEEL COVER - LH / RH	N/S Necessary / O/S Missing	530.00 FS	*424.00 FS
24	1		*FRONT DOOR - RH	Repair	2,542.00 FS	*- FS
25	1		*FRONT DOOR OUTER SEAL	Not Necessary	164.00 FS	*- FS
26	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	155.00 FS	*- FS
27	1		*FRONT DOOR CATCH	Not Necessary	119.00 FS	*- FS
28	1		*FRONT DOOR COVER - RH	Not Necessary	265.00 FS	*- FS
29	1		*FRONT ALUMINIUM RIM - RH	Not Necessary	756.00 FS	*- FS
30	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 15,615.00 8,326.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO DISMANTLE AND REINSTALL RH FRONT DOOR PANEL TRIM.TO REMOVE AND REINSTALL WIND MIRROR ASSY	New	280.00	280.00
4	TO DISMANTLE AND RENEW FRONT BUMPER,RHS FRONT FENDER,RHS FRONT DOOR AND RHS HEADLIGHT.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	3,200.00	1,000.00
5	TO RESPRAY FRONT BUMPER,RHS FRONT FENDER AND RHS FRONT DOOR	New	3,400.00	1,650.00
6	TO RENEW RHS FRONT RIM.TO CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
7	TO REAPPLY PAINT COATING ON DAMAGED AREA	New	800.00	600.00
8	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
9	TO REAPPLY HEADLIGHT STICKER	New	300.00	300.00
Gross Labour Cost (\$\$)			9,332.00	4,752.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >