

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIG20009975/GCF3E2**Date:** 05/07/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900162213
Claimant Vehicle No :	SG1773J	Insured Vehicle No :	SMP2518Y
Date of Loss:	04/09/2020	Nature of Claim:	TP
		Claim No:	7246427386SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SG1773J	Engine No:	50350241075026
Make & Model:	MAN A22, 10.5 D (A)	Chassis No:	WMAA22ZZ8JF006951
Reg. Date:	19/07/2018 (Man. Year: 2018)	Odometer:	101853 km
Colour:	Green		
Engine Capacity:	10518 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5 (D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6/6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	339.00	339.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,392.00	1,200.00	192.00	13.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,731.00	1,539.00	192.00	11.09
+ GST 7.00/7.00% (S\$)	121.17	107.73	13.44	11.09
Nett Amount (S\$)	1,852.17	1,646.73	205.44	11.09

INSPECTION

Date of Assignment:	17/09/2020		
Date Inspected:	17/09/2020	Inspected At:	SBS Transit Ltd (Defu) 4 Defu Ave 1 Singapore 539536
Estimated Period of Repair:	2.0 days		

Adjuster: XING GUO QIANG**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*BOSTICK SEALANT 7008	Necessary	31.00 F	*31.00 F
2	1		*FLAP DOOR FL~GL+FR~GR;0.25X0.3M	Cut	79.00 F	*79.00 F
3	1		*SIDE PANEL R8.E6	Cut	229.00 F	*229.00 F
					F=Franchise part.	
Total Parts (S\$)					339.00	339.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	(2) WORKSHOP LABOUR	New	192.00	0.00
2	CONTRACTORS REPAIR CHARGES	New	1,200.00	1,200.00
Gross Labour Cost (S\$)			1,392.00	1,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >