

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/AIG20009976/GYF3E2

**Date:** 18/11/2020

#### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800120292
<b>Claimant Vehicle No :</b> SBS8507D	<b>Insured Vehicle No :</b>	SKB3653E
Date of Loss: 07/09/2020	Nature of Claim:	TP Claim No: 4119655379SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBS8507D	Engine No:	6337474
Make & Model:	SCANIA KUB4X2, 8.9 D (A)	Chassis No:	YS2K4X20001862212
Reg. Date:	28/11/2008 (Man. Year: 2008)	Odometer:	824831 km
Colour:	Purple		
Engine Capacity:	8867 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5 (D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6/6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6/6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	490.00	490.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>490.00</b>	<b>490.00</b>	<b>0.00</b>	<b>0.00</b>
<b>+ GST 7.00/7.00% (S\$)</b>	34.30	34.30	0.00	0.00
<b>Nett Amount (S\$)</b>	<b>524.30</b>	<b>524.30</b>	<b>0.00</b>	<b>0.00</b>

#### INSPECTION

Date of Assignment:	17/09/2020	Inspected At:	SBS Transit Ltd (AMK) 15 Ang Mo Kio Street 63 Singapore 569117
Date Inspected:	17/09/2020		
Estimated Period of Repair:	2.0 days		

**Adjuster:** XING GUO QIANG

**Manager:** YVONNE WONG YIN CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH RADIATOR FRAME (NPA)	Bent	0.00 F	*- F
					<b>Total Parts (\$)</b>	<b>0.00</b>
						<b>0.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR COST }	New	490.00	490.00
2	DISMANTLE AND REPLACE N/S RADIATOR ACCESS DOOR }	New	0.00	0.00
3	REPAIR O/S/R CORNER PANEL }	New	0.00	0.00
4	REPAIR N/S/R CORNER PANEL }	New	0.00	0.00
5	REPAIR REAR BUMPER ASSY }	New	0.00	0.00
6	TOUCH UP PUTTY ON ACCIDENT AREA }	New	0.00	0.00
7	RESPRAY ACCIDENT AREA }	New	0.00	0.00
<b>Gross Labour Cost (\$)</b>			<b>490.00</b>	<b>490.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >