



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

OPINION ON REPAIR COST FOR VEHICLE NO. SLB 3011X

Qty	Description of Parts	Condition	Recommended (\$)
	<u>REPLACEMENT OF PARTS</u>		
1	FRT NUMBER PLATE	BENT	15.00
1	FRT NUMBER PLATE BASE	BROKEN	25.00
1	FRT BUMPER	BROKEN	689.00
1	FRT BUMPER CLIPS	NECESSARY	30.00
2	FRT BUMPER SIDE RETAINER	BROKEN	160.00
1	FRT BUMPER REINFORCEMENT	DENTED	506.00
2	FRT BUMPER REINFORCEMENT BRACKET	BENT	300.00
1	FRT BUMPER SPONGE	BROKEN	80.00
1	FRT LH BUMPER FOG LAMP COVER	CUT	80.00
1	FRT GRILLE	BROKEN	650.00
1	FRT EMBLEM	NECESSARY	80.00
1	FRT GRILLE INNER BRACKET	BROKEN	186.00
1	FRT SUPPORT PANEL	BROKEN	564.00
1	FRT SUPPORT PANEL TOP GARNISH COVER	BROKEN	120.00
1	FRT LH HEADLAMP ASSY	BROKEN	1,411.00
1	FRT RH HEADLAMP ASSY	BROKEN	1,411.00
1	BONNET	DENTED	1,032.00
1	BONNET LOCK	BENT	139.00
1	AIR-CON CONDENSER	DENTED	800.00
1	AIR-CON DISCHARGE HOSE	BENT	247.00
1	RADIATOR	DENTED	800.00
1	RADIATOR FAN ASSY	BROKEN	809.00
1	RADIATOR HOSE TOP	CRUSHED	40.00
1	AIR CLEANER ASSY	BROKEN	150.00
1	INTAKE MANIFOLD	BROKEN	2,150.00
3	ENGINE UNDER COVER	BROKEN	478.00
1	FRT LH FENDER	DENTED	968.00
1	FRT RH FENDER	TO REPAIR SEE LABOUR	-
1	REAR NUMBER PLATE	BENT	15.00
1	REAR NUMBER PLATE BASE	CUT	25.00
2	REAR NUMBER PLATE LAMP	BROKEN	240.00
1	REAR BUMPER	DENTED	961.00

Report Ref No. CS3/ICA20009978/Etf3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Recommended (\$)
1	REAR BUMPER CLIPS	NECESSARY	30.00
2	REAR BUMPER SIDE RETAINER	BROKEN	90.00
1	REAR BUMPER REINFORCEMENT	BENT	188.00
1	REAR BUMPER REFLECTOR	BROKEN	112.00
1	REVERSE SENSOR	BROKEN	200.00
1	REAR END PANEL	DENTED	515.00
1	REAR END PANEL TOP GARNISH	CRUSHED	98.00
1	REAR LH TAILLAMP	BROKEN	573.00
1	REAR RH TAILLAMP	BROKEN	573.00
1	TAILGATE	DENTED	1,637.00
3	TAILGATE EMBLEM	NECESSARY	240.00
1	TAILGATE OUTER HANDLE SWITCH	TORN	482.00
1	TAILGATE GARNISH (NPA)	BROKEN	-
2	TAILGATE LAMP	BROKEN	818.00
1	TAILGATE TRIM BOARD	BROKEN	496.00
1	TAILGATE WIPER MOTOR	BENT	365.00
1	TAILGATE GLASS SEALANT	NECESSARY	60.00
1	TAILGATE LOCK	BENT	256.00
1	TAILGATE RUBBER	CRUSHED	188.00
1	REVERSE CAMERA	CUT	350.00
1	SPARE TYRE BOARD	CRUSHED	407.00
1	SPARE TYRE PANEL	DENTED	1,185.00
1	SPARE TYRE TRAY	CRUSHED	428.00
1	REAR EXHAUST CHROME PIPE	CUT	180.00
	LESS 20% DISCOUNT		-4,926.40
			19,705.60
	LABOUR		
	LABOUR. INCLUSIVE OF THE REPAIR OF FRT RH FENDER.		1,800.00
	SPRAY.		1,600.00
			-
			-
			-
			3,400.00
GRAND TOTAL			23,105.60



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)	18,500.00
---	-----------

Report Ref No. CS3/ICA20009978/Etf3s2

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.