

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20009981/KCF3E2

**Date:** 09/03/2021

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00097932000  
**Claimant Vehicle No :** SML2545P **Insured Vehicle No :** SKK7732L  
Date of Loss: 11/09/2020 Nature of Claim: TP Claim No: SNM20D203331C02/TOHHS

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SML2545P**  
Make & Model: HYUNDAI AVANTE, 1.6 (A) Engine No: G4FGKU125606  
Reg. Date: 13/05/2019 (Man. Year: 2019) Chassis No: KMHD841CMKU892944  
Colour: Metallic Grey Odometer: 16108 km  
Engine Capacity: 1591 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

### CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17  
Front Left Side: Bridgestone 8 mm Rear Left Side: Bridgestone 8 mm  
Front Right Side: Bridgestone 8 mm Rear Right Side: Bridgestone 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,577.50	1,419.44	1,158.06	44.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,030.00	1,045.00	2,985.00	74.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,607.50</b>	<b>2,464.44</b>	<b>4,143.06</b>	<b>62.70</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,950.00</b>		
<b>(S\$)</b>	6,607.50	1,950.00	4,657.50	70.49
<b>+ GST 7.00/7.00% (S\$)</b>	462.53	136.50	326.03	70.49
<b>Nett Amount (S\$)</b>	<b>7,070.03</b>	<b>2,086.50</b>	<b>4,983.53</b>	<b>70.49</b>

### INSPECTION

Date of Assignment: 17/09/2020  
Date Inspected: 17/09/2020 Inspected At: Vermogen Ace Pte Ltd (Jln Lam Huat) (HQ)  
60 Jalan Lam Huat, #03-35/36  
Singapore 737869  
Estimated Period of Repair: 4.0 days

**Adjuster:** KENNETH KONG

**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 09 Mar 2021)
<b>Parts:</b> 143	HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SML2545P)	
<b>Validity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*REAR BUMPER</b>	Dented / Warped	459.40 F	*459.40 FL
2	2		<b>*REAR BUMPER SIDE RETAINER</b> (NPA)	Serviceable	0.00 F	*- FL
3	2		<b>*REAR BUMPER REFLECTOR</b> (NPA)	Serviceable	0.00 F	*- FL
4	1		<b>*REAR BUMPER REINFORCEMENT</b> (NPA)	Repair	0.00 F	*- FL
5	2		<b>*REAR BUMPER STAY</b> (NPA)	Serviceable	0.00 F	*- FL
6	1		<b>*REAR BUMPER LOWER SKIRT</b> (NPA)	Serviceable	0.00 F	*- FL
7	1		<b>*REAR BUMPER UNDER COVER RH</b> (NPA)	Serviceable	0.00 F	*- FL
8	1		<b>*REAR BUMPER GUARD RH</b> (NPA)	Serviceable	0.00 F	*- FL
9	2		<b>*REAR BUMPER MUD GUARD</b> (NPA)	Serviceable	0.00 F	*- FL
10	5		<b>*REAR BUMPER REINFORCEMENT BRACKET</b> (NPA)	Repair	0.00 F	*- FL
11	1		<b>*TAILLAMP LH</b> (NPA)	Serviceable	0.00 F	*- FL
12	1		<b>*TAILLAMP CLIPS LH</b> (NPA)	Not Necessary	0.00 F	*- FL
13	1		<b>*TAILLAMP PANEL LH</b> (NPA)	Repair	0.00 F	*- FL
14	1		<b>*REAR END PANEL</b> (NPA)	Repair	0.00 F	*- FL
15	1		<b>*REAR END PANEL TOP GARNISH</b> (NPA)	Serviceable	0.00 F	*- FL
16	1		<b>*SET REAR END PANEL TOP GARNISH CLIPS</b> (NPA)	Not Necessary	0.00 F	*- FL
17	1		<b>*SPARE TYRE PANEL</b> (NPA)	Repair	0.00 F	*- FL
18	1		<b>*SPARE TYRE PANEL TOP BOARD</b> (NPA)	Serviceable	0.00 F	*- FL
19	1		<b>*REAR FENDER LH</b> (NPA)	Repair	0.00 F	*- FL
20	1		<b>*REAR FENDER INNER SHIELD (REAR) LH</b> (NPA)	Serviceable	0.00 F	*- FL
21	1		<b>*REAR FENDER INNER SHIELD (FRONT) LH</b> (NPA)	Not Necessary	0.00 F	*- FL
22	1		<b>*SET REAR FENDER INNER SHIELD CLIPS LH</b> (NPA)	Not Necessary	0.00 F	*- FL
23	1		<b>*REAR FENDER INNER TRIM BOARD LH</b> (NPA)	Serviceable	0.00 F	*- FL
24	1		<b>*SET REAR FENDER INNER TRIMBOARD CLIPS LH</b> (NPA)	Not Necessary	0.00 F	*- FL
25	1		<b>*REAR RIM LH</b>	Dented	500.00 FS	*500.00 FS
26	1		<b>*REAR TYRE LH</b>	Serviceable	300.00 FS	*- FS
27	1		<b>*REAR SHOCK ABSORBER LH</b>	Bent	235.90 F	*235.90 FL
28	1		<b>*REAR WHEEL HUB LH }</b>	Bent	454.00 F	*454.00 FL
29	1		<b>*REAR WHEEL BEARING LH }</b>		148.20 F	*- FL
30	1		<b>*REAR AXLE BEAM</b> (NPA)	Serviceable	0.00 F	*- FL

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
31	1		*REAR DOOR LH (NPA)	Serviceable	0.00 F	*- FL
32	2		*REAR DOOR STICKER LH (NPA)	Not Necessary	0.00 F	*- FL
33	1		*REAR WINDSCREEN GLASS MOULDING (NPA)	Serviceable	0.00 F	*- FL
34	1		*REAR WINDSCREEN GLASS SEALANT	Not Necessary	80.00 FS	*- FS
35	1		*REAR WINDSCREEN GLASS INNER SEAL	Not Necessary	80.00 FS	*- FS
36	1		*REAR WINDSCREEN GLASS PRIMER & CLEAN	Not Necessary	80.00 FS	*- FS
37	1		*TAILLAMP PAD	Not Necessary	80.00 FS	*- FS
38	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
39	1		*SPARE TYRE PANEL SEALANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>2,577.50</b>	<b>1,649.30</b>
<b>- List Item Discount on L Items 0.00/20.00% (\$)</b>	0.00	229.86
<b>Total Parts (\$)</b>	<b>2,577.50</b>	<b>1,419.44</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO PUTTY, RESPRAY PAINTING AND POLISH ACCIDENT AREA. REAR PORTION	New	1,600.00	500.00
2	TO CHECK AND RECTIFY WIRING AFTER DISCONNECT AND CONNECT	New	150.00	15.00
3	TO SPRAY RUST PROOFING	New	150.00	0.00
4	TO REMOVE & REFIT TRIMS, UPHOLSTERY TO ASSIST WORK LOAD	New	180.00	0.00
5	TO REMOVE & REFIT UNDERCARRIAGE TO ASSIST WORK LOAD	New	280.00	100.00
6	TO DO WHEEL ALIGNMENT	New	150.00	60.00
7	TO DO TYRE BALANCING	New	120.00	20.00
8	TO STRAIGHTEN AND PANEL BEATING ACCIDENT AREA. REAR PORTION	New	1,400.00	350.00
			<b>Gross Labour Cost (\$)</b>	<b>1,045.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >