11/12/21, 4:56 PM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20009989/KQF3N2

12/11/2021 Date:

**REFERENCE** 

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMB1SN15479919044

**Claimant Vehicle** No:

SMQ9412S

**Insured Vehicle** No:

PA6538G

Date of Loss: 16/09/2020

Nature of Claim: TP

Claim

No:

SNM20D203382/C2/LEWLC

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

**SMQ9412S** Reg No:

TOYOTA NOAH HYBRID, 1.8 X CVT (A) 2ZR0B06567 Make & Model: Engine No: Reg. Date: 26/07/2018 (Man. Year: 2017) Chassis No: ZWR800305629 Colour: Metallic Black Odometer: 48073 km

**Engine Capacity:** 1797 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes Nο

**CONDITION OF TYRES** 

Front Tyre Size: 215/50R17 Rear Tyre Size: 215/50R17 Front Left Side: Toyo 3 mm Rear Left Side: Tovo 1 mm Toyo 1 mm Front Right Side: Toyo 3 mm Rear Right Side:

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,685.00	1,685.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	980.00	900.00	80.00	8.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,665.00	2,585.00	80.00	3.00
+ GST 7.00/7.00% (S\$)	186.55	180.95	5.60	3.00
Nett Amount (S\$)	2,851.55	2,765.95	85.60	3.00

**INSPECTION** 

Date Inspected:

Date of Assignment: 17/09/2020

Cheng Hoe Motor Pte Ltd (AMK)

10 ANG MO KIO IND PARK 2A, #01-04 ANG MO

KIO AUTOPOINT

Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: **KENNETH KONG** Manager: SHIAU CHAN

17/09/2020 Inspected At:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

### **REPAIR DETAILS**

#### Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Nov 2021)

Parts: M1-MPV TOYOTA NOAH HYBRID 1.8 X CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMQ9412S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	650.00 F	*650.00 F
2	1		*REAR TAILGATE EMBLEM-HYBRID	Necessary	35.00 F	*35.00 F
3	1		*REAR TAILGATE OUTER CHROME MOULDING	Cracked	310.00 F	*310.00 F
4	1		*REAR WINDSCREEN GLASS	Shattered	650.00 F	*650.00 F
5	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
F=Fra	nchise	part. S=SpcN	lett.	-		
				Total Parts (S\$)	1,685.00	1,685.00
				_		

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	<u>our Items</u>			
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	100.00	100.00
2	TO REMOVE AND REFIX TAILGATE, LOCK ASSY, REAR WIPER ASSY AND RE-ALIGN THE SAME	New	400.00	320.00
3	TO REMOVE AND REFIX REVERSE CAMERA AND RESET SYSTEM	New	50.00	50.00
4	TO PUTTY AND RESPRAY ON TAILGATE	New	400.00	400.00
5	RUSTPROOFING	New	30.00	30.00
	Gross Labou	r Cost (S\$)	980.00	900.00
	Report was unsubmitted during this	print-out		

< END OF ESTIMATES >