



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 6833T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	TAILLAMP ASSY RH	CUT	450.00	450.00
1	REAR MUDFLAP RH	BUCKLED / CUT	520.00	520.00
1	REAR MUDFLAP BRACKET INNER RH	TO REPAIR SEE LABOUR	220.00	-
1	REAR MUDFLAP BRACKET OUTER RH	TO REPAIR SEE LABOUR	220.00	-
1	REAR MUDFLAP LOWER RUBBER-ISUZU RH	DISTORTED / CUT	180.00	180.00
2	REAR SHAFT BRACKET	TO REPAIR SEE LABOUR	240.00	-
1	REAR NO PLATE LAMP	DENTED	180.00	180.00
	LESS 10% DISCOUNT		-201.00	-133.00
			1,809.00	1,197.00
<u>SPECIAL NETT ITEMS</u>				
1	REAR CABIN TAILLAMP PANEL RH (SN)	TO REPAIR SEE LABOUR	680.00	-
1	REAR REFLECTOR STICKER-RED (SN)	NECESSARY	180.00	180.00
1	REAR REFLECTOR STICKER-BLUE AND ORANGE (SN)	NOT NECESSARY	380.00	-
1	HYDRALIC OIL (SN)	NOT NECESSARY	450.00	-
1	REAR NUMBER PLATE (SN)	BENT	50.00	15.00
1	REAR NUMBER PLATE BRACKET (SN)	TO REPAIR SEE LABOUR	150.00	-
			1,890.00	195.00
<u>LABOUR</u>				
	STRAIGHTEN & PANEL BEAT ACCIDENT AREAS.INCLUSIVE OF THE REPAIR OF REAR MUDFLAP BRACKET INNER RH, REAR MUDFLAP BRACKET OUTER RH,REAR SHAFT BRACKET,REAR CABIN TAILLAMP PANEL RH AND REAR NUMBER PLATE BRACKET.		1,200.00	350.00
	SPRAY PAINTING ON ACCIDENT AREA.		1,200.00	300.00
	CHECK & REPAIR WIRING SYSTEM.		120.00	20.00
	CONDUCT CHASSIS REPAIR-REAR RH PORTION.	NOT NECESSARY	1,200.00	-
	RESPRAY TUFF KOTE ON AFFECTED AREA.	NOT NECESSARY	120.00	-

Report Ref No. CS/SMO20009997/Kcf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	RESET & PROGRAMME LTA SYSTEM & INSPECTION.	NOT NECESSARY	480.00	-
			4,320.00	670.00
GRAND TOTAL			8,019.00	2,062.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,650.00

Report Ref No. CS/SMO20009997/Kcf3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.