

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592

E-Mail: jwg.claims@yahoo.com

To: AIG ASIA PACIFIC INSURANCE PTE LTD

Att: Motor Claims Dept

ACCIDENT INVOLVING SML9193A [YOUR INSURED] & SMS4488X [OUR CLIENT]
ON 16/09/2020.

ESTIMATED REPAIR COSTS FOR SMS4488X

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>
1PC	BOOTLID <i>1st</i>	1782.40 \$ 1,982.40
1PC	BOOTLID 'HYUNDAI' LOGO <i>NH</i>	54.70 \$ 196.20
1PC	BOOTLID 'AVANTE' EMBLEM <i>NH</i>	31.20 \$ 61.20
1PC	BOOTLID REVERSE CAMERA <i>NH</i>	\$ 926.10
1PC	BOOTLID LOCK <i>NH</i>	\$ 216.20
1PC	BOOTLID INNER TRIM <i>NH</i>	\$ 246.80
2PC	BOOTLID LAMP L+R @ \$484.90 EACH <i>NH</i>	\$ 969.80
1PC	BOOTLID WEATHER STRIP <i>NH</i>	161.00 \$ 292.50
1PC	REAR BUMPER <i>Debris</i>	\$ 659.40
1PC	REAR BUMPER BRACKET <i>NH</i>	\$ 178.60
2PC	REAR BUMPER SIDE RETAINER L+R @ \$59.40 EACH <i>NH</i>	\$ 118.80
1PC	REAR BUMPER CENTER GARNISH <i>distorted</i>	127.60 \$ 553.50
2PC	REAR BUMPER CENTER GARNISH LAMP L+R @ \$799.80 EACH <i>NH</i>	\$ 1,599.60
2PC	REAR BUMPER NO. PLATE LAMP L+R @ \$118.20 EACH <i>NH</i>	\$ 236.40
2PC	TAIL LAMP L+R @ \$635.10 EACH <i>NH</i>	\$ 1,270.20
2PC	TAIL LAMP LOWER BRACKET L+R @ \$293.10 EACH <i>NH</i>	\$ 586.20
1PC	REAR REINFORCEMENT BAR <i>broken / crack</i>	\$ 694.80
1PC	REAR KEYLESS SENSOR <i>NH</i>	\$ 244.50
1PC	REAR END PANEL <i>Debris</i>	454.60 \$ 254.60
1PC	REAR END PANEL TOP GARNISH <i>NH</i>	\$ 259.80

PARTS SUM: \$ 12,047.60

PARTS LESS 20%: \$ 2,409.52

PARTS TOTAL: \$ 9,638.08

LABOUR & SPECIAL NETT ITEMS

5154.30

4123.44

* TO SUPPLY 1 SET REAR REVERSE SENSOR <i>NH</i>	\$ 300.00 X
* TO SUPPLY REAR END PANEL SEALANT <i>NH</i>	\$ 80.00 X <i>41-</i>
* TO SUPPLY REAR NUMBER PLATE <i>NH</i>	\$ 40.00 X
* TO SUPPLY REAR BUMPER CLIPS <i>NH</i>	\$ 50.00 <i>30-</i>
* TO SUPPLY REAR BOOTLID INNER TRIM CLIPS <i>NH</i>	\$ 50.00 X
* TO SUPPLY REAR BUMPER CORNER GARNISH <i>NH</i>	\$ 500.00 X
* TO SUPPLY REAR BUMPER WHITE STICKER <i>NH</i>	\$ 300.00 <i>80-</i>
* TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILITATE REPAIRS	\$ 300.00 <i>80-</i>
* TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$ 1,600.00 <i>700-</i>
* TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	\$ 1,400.00 <i>700-</i>
* TO TUFF COAT DAMAGED AREAS	\$ 300.00 <i>40-</i>
* TO RNR REVERSE CAMERA	\$ 100.00 <i>NH</i>
* TO RNR REAR WINDSCREEN TO ASSIST WORK LOAD	\$ 250.00 <i>NH</i>
* TO RNR REAR BOOT MECHANISM TO ASSIST WORK LOAD	\$ 200.00 <i>60-</i>
* TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS <i>1650.00</i>	\$ 250.00 <i>NH</i>
* TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	\$ 200.00 <i>30-</i>
* TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	\$ 300.00 <i>NH</i>
* TO RNR REVERSE SENSOR TO ASSIST WORK LOAD	\$ 120.00 <i>40-</i>

LABOUR & S/N TOTAL: \$ 6,340.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 15,978.08

18/09/2020 @ 1608m

NH Andri

2/Sum

4 dgs.

Ryan

LKK Andri

[Signature]

Check part price

5923.44

4/5 4700/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: