

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20010009/RES3Q2**Date:** 08/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800113539
Claimant Vehicle No :	SMB3043S	Insured Vehicle No :	EL202L
Date of Loss:	15/09/2020	Nature of Claim:	TP
		Claim No:	3030618897SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMB3043S	Engine No:	HIDDEN
Make & Model:	MAN NL320F (A22), 10.5 D ABS TURBO (A)	Chassis No:	WMAA22ZZ207001758
Reg. Date:	01/03/2013 (Man. Year: 2013)	Odometer:	463401 km
Colour:	Green		
Engine Capacity:	10518 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5 (D)
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8/8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,762.60	1,192.00	570.60	32.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,450.00	3,545.00	2,905.00	45.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,212.60	4,737.00	3,475.60	42.32
+ GST 7.00/7.00% (S\$)	574.88	331.59	243.29	42.32
Nett Amount (S\$)	8,787.48	5,068.59	3,718.89	42.32
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	17/09/2020	
Date Inspected:	18/09/2020	Inspected At: Tower Transit Singapore Pte Ltd (HQ) 21 Bulim Drive, Bulim Bus Depot Singapore 648170
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD RASUL**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*O/S SIDE PANEL RS	Bent	520.00 F	*520.00 F
2	1		*O/S SIDE PANEL FRAME	Bent	640.00 F	*640.00 F
3	1		*PANEL WHEELARCH TRIM	Repair	87.00 F	*- F
4	1		*O/S SIDE PANEL R6	Repair	230.00 F	*- F
5	1		*N/S HINGE SIDE FLAP (DHGE -0058-00)	*Check	126.80 F	*- F
6	1		*O/S HINGE SIDE FLAP (DHGE -0057-00)	*Check	126.80 F	*- F
7	2		*SIKAFLEX BLACK	Necessary	32.00 F	*32.00 F
					F=Franchise part.	
					Total Parts (S\$)	1,762.60 1,192.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE DAMAGED PARTS	New	1,950.00	975.00
2	TO PERFORM REPAIR WORKS ON RADIATOR BOTTOM	New	1,300.00	650.00
3	SPRAY PAINTING	New	3,200.00	1,920.00
Gross Labour Cost (S\$)			6,450.00	3,545.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >