

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20010021/UPA3Q2

Date: 15/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100485402

Claimant
Vehicle No : SJX4009E **Insured Vehicle No :** SKS1074A

Date of Loss: 18/09/2020 Nature of Claim: TP Claim No: 5578343787SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJX4009E	Engine No:	1NZY103718
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Chassis No:	MR053HY9305168982
Reg. Date:	11/06/2010 (Man. Year: 2010)	Odometer:	245537 km
Colour:	White		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Maxmiler 6 mm	Rear Left Side:	Maxmiler 6 mm
Front Right Side:	Maxmiler 6 mm	Rear Right Side:	Maxmiler 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,159.50	3,372.40	7,787.10	69.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,370.00	2,310.00	2,060.00	47.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,529.50	5,682.40	9,847.10	63.41
Approved Total (Overridden) (S\$)		4,500.00		
(S\$)	15,529.50	4,500.00	11,029.50	71.02
+ GST 7.00/7.00% (S\$)	1,087.07	315.00	772.07	71.02
Nett Amount (S\$)	16,616.57	4,815.00	11,801.57	71.02
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,177.00		
Global Sum Settlement (S\$)		5,100.00		

INSPECTION

Date of Assignment: 18/09/2020

Date Inspected: 18/09/2020 Inspected At:

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50
Autobay
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Repair	766.50 F	*- FL
2	1		*BOOTLID OUTER HANDLE	Not Necessary	198.10 F	*- FL
3	1		*BOOTLID REAR LOGO	Necessary	60.80 F	*60.80 FL
4	1		*BOOTLID VIOS EMBLEM	Necessary	55.20 F	*55.20 FL
5	1		*BOOTLID E EMBLEM	Necessary	48.80 F	*48.80 FL
6	1		*BOOTLID INNER LOCK	Twisted	199.40 F	*199.40 FL
7	1		*BOOTLID LOCK STRIKER	Not Necessary	89.90 F	*- FL
8	1		*BOOTLID WEATHERSTRIP	Twisted	266.50 F	*266.50 FL
9	2		*BOOTLID HINGES	Not Necessary	300.00 F	*- FL
10	1		*REAR BUMPER	Distorted	655.10 F	*415.20 FL
11	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	153.00 F	*- FL
12	2		*REAR BUMPER BRACKETS	Not Necessary	198.20 F	*- FL
13	1		*REAR BUMPER REFLECTORS	N/s Cracked	390.00 F	*195.00 FL
14	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
15	1		*REAR END PANEL	Badly Dented	655.20 F	*655.20 FL
16	1		*REAR END PANEL GARNISH	Twisted	315.10 F	*188.20 FL
17	2		*TAILLAMP INNER GASKETS	Necessary	21.00 F	*21.00 FL
18	1		*TAILLAMPS	N/s Cracked	1,040.20 F	*466.10 FL
19	2		*TAILLAMPS HOUSING PANELS	Repair	399.00 F	*- FL
20	1		*REAR FLOOR PANEL SIDE PANEL N/S	Buckled	911.20 F	*485.10 FL
21	1		*REAR FLOOR PANEL TOP BOARD	Torn	422.50 F	*315.50 FL
22	1		*REAR FLOOR PANEL SIDE TOOLS SPONGES	N/s Cracked	778.20 F	*389.10 FL
23	2		*REAR FENDERS	Repair	1,690.20 F	*- FL
24	1		*REAR FENDER INNER TRIMS	N/s Deformed/Torn	573.00 F	*286.50 FL
25	1		*REAR AIR VENT	Cracked	65.60 F	*65.60 FL
26	2		*REAR FENDER INNER SPLASH SHIELDS	Not Necessary	210.00 F	*- FL
27	1		*REAR WINDSCREEN MOULDING	Not Necessary	66.80 F	*- FL
28	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
29	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
30	1		*REAR FLOOR PANEL INSULATOR	Not Necessary	200.00 FS	*- FS
31	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
					Sub Total (\$\$)	11,159.50 4,413.20
					- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00 1,040.80
					Total Parts (\$\$)	11,159.50 3,372.40

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	80.00	50.00
3	TO TRANSFER BOOTLID MECHANISM	New	80.00	0.00
4	TO SPRAY RUST PROOFING	New	120.00	50.00
5	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
6	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	180.00	80.00
7	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	0.00
8	TO DISMANTLE & REFIX FUEL TANK	New	100.00	0.00
9	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	1,800.00	1,000.00
10	TO PUTTY & SPRAY PAINTING	New	1,680.00	1,100.00
Gross Labour Cost (\$\$)			4,370.00	2,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >