

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20010026/QGA3Q2

Date: 05/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800044941

Claimant
Vehicle No : SHB5452R **Insured Vehicle No :** SMA1511B

Date of Loss: 15/09/2020 Nature of Claim: TP Claim No: 9181813081SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB5452R		
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Engine No:	2ZR1673405
Reg. Date:	08/04/2016 (Man. Year: 2015)	Chassis No:	JTDKN36U905767855
Colour:	Maroon	Odometer:	315408 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Neuton 6 mm	Rear Left Side:	Neuton 6 mm
Front Right Side:	Neuton 6 mm	Rear Right Side:	Neuton 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,150.99	1,902.05	17,248.94	90.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,306.00	1,410.00	3,896.00	73.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	24,456.99	3,312.05	21,144.94	86.46
Approved Total (Overridden) (\$\$)		3,000.00		
Nett Amount (\$\$)	24,456.99	3,000.00	21,456.99	87.73
+ Loss of Use (8.0 x S\$60.00/day) (\$\$)		480.00		
+ Car Rental (8.0 x S\$105.40/day) (\$\$)		843.20		
+ Doc/Search Fee (\$\$)		7.00		
Nett Liability (\$\$)		4,330.20		
Global Sum Settlement (\$\$)		4,330.00		

INSPECTION

Date of Assignment: 16/09/2020

Date Inspected: 16/09/2020 Inspected At:

SMRT Automotive Services Pte Ltd
(Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Estimated Period of Repair: 5.0 days

Adjuster: OI SUN PIN**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BRACKET ,FR BUMPER (DISC 25%)	Broken	110.40 F	*82.80 F
2	1		*BUMPER REAR (DISC 25%)	Crumpled	458.60 F	*343.95 F
3	1		*BUMPER CLIPS (DISC 25%) (10 PCS)	Necessary	16.10 F	*12.08 F
4	1		*TAILGATE DOOR WEATHER STRIP (DISC 25%)	Crumpled	353.40 F	*265.05 F
5	1		*NAME PLATE (HYBRID) (DISC 25%)	Necessary	51.90 F	*38.93 F
6	1		*BUMPER REINFORCEMENT REAR (DISC 25%)	Bent	205.70 F	*154.28 F
7	1		*ARM SUB-ASSY ,RR BUMPER LH (DISC 25%)	Bent	139.60 F	*104.70 F
8	1		*ARM SUB-ASSY ,RR BUMPER RH (DISC 25%)	Bent	139.60 F	*104.70 F
9	1		*BUMPER LIP REAR (DISC 25%)	Crumpled	228.90 F	*171.68 F
10	1		*ADVERTISEMENT STICKER (SN)	Necessary	296.88 F	*296.88 F
11	1		*NUMBER PLATE (SN)	Crumpled	15.00 F	*15.00 F
12	1		*NUMBER PLATE FRAME (SN)	Crumpled	12.00 F	*12.00 F
13	1		*SENSOR REVERSE (SN)	Shorted	180.00 F	*180.00 F
14	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
15	1		*BUMPER FRT	Repair	482.00 F	*- F
16	1		*TAILGATE ASY	Repair	1,007.90 F	*- F
17	1		*BUMPER CLIPS	Serviceable	1.61 F	*- F
18	1		*BUMPER ENERGY ABSORBER FRT	Serviceable	78.80 F	*- F
19	1		*BUMPER REINFORCEMENT FRT	Serviceable	498.40 F	*- F
20	1		*ARM SUB-ASSY ,FRT BUMPER LH	Serviceable	250.40 F	*- F
21	1		*ARM SUB-ASSY ,FRT BUMPER RH	Serviceable	250.40 F	*- F
22	1		*BRACKET ,SUPPORT F/LH	Serviceable	76.40 F	*- F
23	1		*BRACKET ,SUPPORT F/RH	Serviceable	76.40 F	*- F
24	1		*BUMPER GRILLE SUB-ASSY ,LOWER	Serviceable	311.10 F	*- F
25	1		*FOG LAMP LH	Serviceable	280.10 F	*- F
26	1		*FOG LAMP RH	Serviceable	295.20 F	*- F
27	1		*LENS & BODY ,FR TURN RH	Serviceable	511.80 F	*- F
28	1		*LENS & BODY ,FR TURN LH	Serviceable	511.80 F	*- F
29	1		*GRILLE ,RADIATOR	Serviceable	310.60 F	*- F
30	1		*EMBLEM FRONT	Serviceable	86.50 F	*- F
31	1		*BUMPER LIP FRT	Serviceable	139.60 F	*- F
32	1		*BUMPER FRT ABSORBER LOWER	Serviceable	127.70 F	*- F
33	1		*COVER ,FR BUMPER HOLE LH	Serviceable	18.50 F	*- F
34	1		*COVER ,FR BUMPER HOLE RH	Serviceable	18.50 F	*- F
35	1		*BUMPER REINFORCEMENT REAR	Serviceable	205.70 F	*- F
36	1		*ARM SUB-ASSY ,RR BUMPER LH	Serviceable	139.60 F	*- F
37	1		*ARM SUB-ASSY ,RR BUMPER RH	Serviceable	139.60 F	*- F
38	1		*ANTENNA ,ELECTRICAL LOWER REAR	Serviceable	157.40 F	*- F
39	1		*BUMPER LIP COVER RR/LH	Serviceable	72.20 F	*- F
40	1		*BUMPER LIP COVER RR/RH	Serviceable	118.10 F	*- F
41	1		*BUMPER LIP REAR	Serviceable	228.90 F	*- F
42	1		*BUMPER SEAL ,RR LH	Serviceable	88.90 F	*- F
43	1		*BUMPER SEAL ,RR RH	Serviceable	65.70 F	*- F
44	1		*BUMPER SIDE RETAINER RR/LH	Serviceable	94.80 F	*- F
45	1		*BUMPER SIDE RETAINER RR/RH	Serviceable	94.80 F	*- F
46	1		*UNDER COVER SUBASSY,RR FLOOR	Serviceable	514.50 F	*- F
47	1		*DAM ,BACK DOOR GLASS ADHESIVE NO.1	Serviceable	27.30 F	*- F
48	1		*TAIL GATE DOOR GLASS MOULDING LH	Serviceable	29.40 F	*- F
49	1		*TAIL GATE DOOR GLASS MOULDING RH	Serviceable	29.40 F	*- F
50	1		*MOULDING BACK WINDOW LOWER NO.1	Serviceable	29.40 F	*- F
51	1		*DAM ,BACK DOOR GLASS ADHESIVE NO.2	Serviceable	17.40 F	*- F
52	1		*MOULDING ,BACK WINDOW LOWER NO.2	Serviceable	29.40 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
53	1		*MOULDING BACK WINDOW ,OUTSIDE LH NO.2	Serviceable	29.40 F	*- F
54	1		*MOULDING ,BACK WINDOW OUTSIDE RH NO.2	Serviceable	29.40 F	*- F
55	1		*SEALANT W/SCREEN	Serviceable	37.00 F	*- F
56	2		*TAILGATE DOOR HINGE LH/RH	Serviceable	58.30 F	*- F
57	1		*TAILGATE DOOR LOCK	Serviceable	444.10 F	*- F
58	1		*TAILGATE LOCK COVER	Serviceable	15.70 F	*- F
59	1		*TAILGATE OUTSIDE GARNISH	Serviceable	504.90 F	*- F
60	1		*STRIKER BACK DOOR	Serviceable	48.90 F	*- F
61	1		*EMBLEM REAR	Serviceable	60.30 F	*- F
62	1		*NUMBER PLATE	Serviceable	15.00 F	*- F
63	1		*NUMBER PLATE FRAME	Serviceable	12.00 F	*- F
64	1		*NAME PLATE (PRIUS)	Serviceable	60.80 F	*- F
65	1		*NAME PLATE (TOYOTA)	Serviceable	51.90 F	*- F
66	1		*SPOILER REAR	Serviceable	953.70 F	*- F
67	1		*3RD BRAKE LAMP	Serviceable	231.30 F	*- F
68	1		*SMRT LOGO	Serviceable	7.80 F	*- F
69	1		*STICKER DECAL 6555 8888	Serviceable	21.60 F	*- F
70	1		*END PANEL	Serviceable	602.10 F	*- F
71	1		*END PANEL COVER ,DECK TRIM HOLE	Serviceable	46.10 F	*- F
72	1		*END PANEL COVER ,DECK TRIM ,RR	Serviceable	121.10 F	*- F
73	1		*REINFORCEMENT ,RR	Serviceable	34.60 F	*- F
74	1		*SEALANT SIKAFLEX	Serviceable	37.00 F	*- F
75	1		*SPARE TYRE PANEL	Serviceable	667.70 F	*- F
76	1		*BOX ,DECK FLOOR ,RR	Serviceable	649.70 F	*- F
77	1		*BOX ,RR FLOOR ,BOARD	Serviceable	679.60 F	*- F
78	1		*BOARD ,RR FLOOR	Serviceable	392.30 F	*- F
79	1		*PANEL ASSY ,DECK LH	Serviceable	307.00 F	*- F
80	1		*PANEL ASSY ,DECK RH	Serviceable	307.00 F	*- F
81	1		*WIRE ,FLOOR	Serviceable	1,675.00 F	*- F
82	1		*WIRE ,FLOOR NO.2	Serviceable	1,305.40 F	*- F

F=Franchise part.

Total Parts (\$\$) **19,150.99** **1,902.05**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING & BODY WORK	New	1,602.00	600.00
2	SPRAY PAINT	New	2,394.00	700.00
3	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	20.00
4	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	100.00	30.00
5	TO TRANSFER REAR TAILGATE MECHANISM	New	120.00	0.00
6	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	30.00
7	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	New	120.00	30.00
8	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	New	120.00	0.00
9	TO REMOVE AND REFIX REAR WINDSCREEN	New	240.00	0.00
10	TO REMOVE AND REFIT WIRE HARDESS	New	250.00	0.00
11	TO REPLACE SUNDRY PARTS	New	100.00	0.00
12	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (\$\$)			5,306.00	1,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >