

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

SOMPO INSURANCE SINGAPORE PL **50 RAFFLES PLACE** #05-01/06 SINGAPORE LAND TOWER

SINGAPORE 048623

INV No. AC2007055

INV Date 19/10/2020

Reference CS/SMO20010033/EKyf3q2

Code



PROFESSIONAL SERVICE FEE

Vehicle No. SJY 1957H

Insured Veh. GBC 6071R

Claim No. CMTD2002713/AGC

Policy No.

Accident Date 12/09/2020

Inspection Date 21/09/2020

Description	Total
Survey Inspection	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	250.00
GST (7%)	17.50
Grand Total	267.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

	Affiliated to Federation Internationale Des Experts En Automobile				
SOM	PO INSURANCE	SINGAPORE PL	E PL Ref : CS/SMO20010033/EKyf3q2		
#05-0		DWERSINGAPORE 048623	Date: 19-10-2020 Code: SMO		
1.		Policy Particulars	:- THIRD PARTY CLAIM		
	Insured Veh.	GBC 6071R	Veh. Inspected	SJY 1957H	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	CMTD2002713/AGC	Excess (\$)	0.00	
	Assign From	GRACE TEO	Assign Date	18/09/2020	
2.		Vehicle Partic	culars & Condition		
	Make & Model	TOYOTA GS300	c.c	2995	
	Engine No.	HIDDEN	Year of Reg.	2010	
	Chassis No.	JTHBH96S205068526	Colour	GREY	
	Odometer	62841	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3.		Conditi	ons of Tyres		
		Size	Make	Balance	
	R/H Front Tyre	225/45 R18	YOKOHAMA	5 mm	
	L/H Front Tyre	225/45 R18	YOKOHAMA	5 mm	
	R/H Rear Tyre	225/45 R18	YOKOHAMA	5 mm	
	L/H Rear Tyre	225/45 R18	YOKOHAMA	5 mm	
4.		Description	on of Damages		
	THE VEHICLE SU	STAINED DAMAGES AT THE REA	AR PORTION.		
	DAMAGES SEE D	ETAILS.			
5.		Genera	Information		
	Accident Date	12/09/2020	Inspection Date	21/09/2020	
	Survey held at	ADVANTAGE VAG-48 TOH GUA	AN RD , #05-136		
	Repairer	-			
5a.		Re	emarks		
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	3 Working Days		



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJY 1957H

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	BROKEN	540.00	540.00
1	RH TOW-EYE CAP	NOT NECESSARY	27.00	-
1	ABSORBER ,REAR BUMPER	BROKEN	117.00	117.00
1	REINFORCEMENT	BENT	324.00	324.00
1	RH SUPPORT ,REAR BUMPER	BROKEN	72.00	72.00
1	LH SUPPORT ,REAR BUMPER	BROKEN	72.00	72.00
1	RH TOP RETAINER ,REAR BUMPER	NOT NECESSARY	49.00	-
1	LH TOP RETAINER ,REAR BUMPER	NOT NECESSARY	54.00	-
	LESS 25% DISCOUNT		-313.75	-281.25
			941.25	843.75
	SPECIAL NETT ITEMS			
1	SUNDRIES (SN)	NECESSARY	25.00	25.00
	REVERSE SENSOR (SN)	NOT NECESSARY	200.00	-
			225.00	25.00
	LABOUR			
	REMOVE AND REFIT REAR BUMPER ,REINFORCEMENT ,SUPPORTS ,RETAINERS		400.00	250.00
	AND OTHER ASSOCIATED COMPONENTS. SURFACE PREPARATION ,SPRAY PAINT AND POLISH REAR BUMPER ,REVERSE SENSORS AND OTHER AFFECTED AREAS.		500.00	400.00
	REMOVE AND REFIT REVERSE SENSORS TO ASSIST THE REPAIR.		20.00	20.00
	DIAGNOSTIC CHECK AND ERASE FAULT CODES.		80.00	30.00
	-		-	-
	-		-	-
	-			
			1,000.00	700.00
	GRAND TOTAL		2,166.25	1,568.75

RECOMMENDED COST OF LUMP SUM REPAIRS		1,250.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/SMO20010033/EKyf3q2





Report Ref No. CS/SMO20010033/EKyf3q2



Automotive Assessor

St.S.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJY 1957H

INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315









51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJY 1957H

RE-INSPECTION











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJY 1957H

RE-INSPECTION

