

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III20010035/EPA3Q2

**Date:** 07/01/2021

### REFERENCE

|                                                         |                             |                        |
|---------------------------------------------------------|-----------------------------|------------------------|
| Handling Insurer: India International Insurance Pte Ltd | Policy No:                  | MCOM0015               |
| <b>Claimant Vehicle No :</b> SLD6835E                   | <b>Insured Vehicle No :</b> | SHD3803P               |
| Date of Loss: 17/09/2020                                | Nature of Claim: TP         | Claim No: MCT200090246 |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | SLD6835E                          | Engine No:  | 1ZRX559871        |
| Make & Model:               | TOYOTA COROLLA ALTIS, 1.6 (A)     | Chassis No: | MR053REH104547800 |
| Reg. Date:                  | 27/06/2016 (Man. Year: 2015)      | Odometer:   | 61307 km          |
| Colour:                     | Black                             |             |                   |
| Engine Capacity:            | 1598 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (\$\$):         | <b>Market Value/New Car Price</b> |             |                   |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |                  |                  |                  |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size:  | 185/55 R15       | Rear Tyre Size:  | 185/55 R15       |
| Front Left Side:  | Bridgestone 5 mm | Rear Left Side:  | Bridgestone 5 mm |
| Front Right Side: | Bridgestone 5 mm | Rear Right Side: | Bridgestone 5 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                                        | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--------------------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                                        | 4,429.75          | 2,745.50          | 1,684.25          | 38.02         |
| Miscellaneous Items                                          | 11.00             | 11.00             | 0.00              | 0.00          |
| Labour                                                       | 770.00            | 750.00            | 20.00             | 2.60          |
| Paintwork Labour                                             | 926.95            | 913.42            | 13.53             | 1.46          |
| Towing                                                       | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (\$\$)</b>                         | <b>6,137.70</b>   | <b>4,419.92</b>   | <b>1,717.78</b>   | <b>27.99</b>  |
| <b>Approved Total (Overridden) (\$\$)</b>                    |                   | <b>3,500.00</b>   |                   |               |
| <b>(\$\$)</b>                                                | 6,137.70          | 3,500.00          | 2,637.70          | 42.98         |
| <b>+ GST 7.00/7.00% (\$\$)</b>                               | 429.64            | 245.00            | 184.64            | 42.98         |
| <b>Nett Amount (\$\$)</b>                                    | <b>6,567.34</b>   | <b>3,745.00</b>   | <b>2,822.34</b>   | <b>42.98</b>  |
| <b>+ Car Rental (6.0 x \$S100.00/day + 7.00% GST) (\$\$)</b> |                   | 642.00            |                   |               |
| <b>+ Doc/Search Fee (\$\$)</b>                               |                   | 7.49              |                   |               |
| <b>Nett Liability (\$\$)</b>                                 |                   | <b>4,394.49</b>   |                   |               |

### INSPECTION

|                     |                              |                                                                                                            |
|---------------------|------------------------------|------------------------------------------------------------------------------------------------------------|
| Date of Assignment: | 18/09/2020 Present Location: | Mova Automotive Pte Ltd (Bukit Merah)                                                                      |
| Date Inspected:     | 18/09/2020 Inspected At:     | Mova Automotive Pte Ltd (Bukit Merah)<br>Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3<br>Singapore 159722 |

Estimated Period of Repair: 5.0 days

---

**Adjuster:** CHEN TSUE YEE

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                                |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 08 Oct 2020)                  |
| <b>Parts:</b>        | 143                                                                                                                                                                          | TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                              |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SLD6835E)                                                                                                                                    |                                                                |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                |

### Recommended Parts

| No. | Qty | Part No. | Particulars            | Condition     | Repairer's | Amount     |
|-----|-----|----------|------------------------|---------------|------------|------------|
| 1   | 1   | NA       | *BADGE MODEL           | Necessary     | 62.00 FL   | *62.00 FL  |
| 2   | 1   | NA       | *BOOTLID               | Repair        | 793.00 FL  | *- FL      |
| 3   | 1   | NA       | *BOOTLID LOCK          | Not Necessary | 399.00 FL  | *- FL      |
| 4   | 1   | NA       | *BOOTLID SEAL          | Torn          | 185.00 FL  | *185.00 FL |
| 5   | 1   | NA       | *CLIP FASTENING        | Necessary     | 50.00 FL   | *30.00 FL  |
| 6   | 1   | NA       | *INNER END PANEL TRIM  | Crushed       | 242.00 FL  | *242.00 FL |
| 7   | 1   | NA       | *KEYLESS GO AERIAL     | Not Necessary | 192.00 FL  | *- FL      |
| 8   | 1   | NA       | *L/FASTENING CLIP      | Not Necessary | 50.00 FL   | *- FL      |
| 9   | 1   | NA       | *L/R BUMPER BRACKET    | Broken        | 120.00 FL  | *120.00 FL |
| 10  | 1   | NA       | *L/R IMPACT DAMPER     | Not Necessary | 75.00 FL   | *- FL      |
| 11  | 1   | NA       | *L/R OUTER LAMP        | Cut           | 391.00 FL  | *391.00 FL |
| 12  | 1   | NA       | *L/R UPP BUMPER BRKT   | Not Necessary | 80.00 FL   | *- FL      |
| 13  | 1   | NA       | *LUGG COMPART CARPET   | Not Necessary | 295.00 FL  | *- FL      |
| 14  | 1   | NA       | *R/R BUMPER BRACKET    | Broken        | 120.00 FL  | *120.00 FL |
| 15  | 1   | NA       | *R/R IMPACT DAMPER     | Not Necessary | 75.00 FL   | *- FL      |
| 16  | 1   | NA       | *R/R OUTER LAMP        | Cut           | 391.00 FL  | *391.00 FL |
| 17  | 1   | NA       | *R/R UPP BUMPER BRKT   | Not Necessary | 80.00 FL   | *- FL      |
| 18  | 1   | NA       | *REAR BUMPER           | Dented        | 556.00 FL  | *556.00 FL |
| 19  | 1   | NA       | *REAR BUMPER SUPPORT   | Dented        | 395.00 FL  | *395.00 FL |
| 20  | 1   | NA       | *REAR MANUFACT BADGE   | Necessary     | 62.00 FL   | *62.00 FL  |
| 21  | 1   | NA       | *REAR PANEL            | Dented        | 670.00 FL  | *670.00 FL |
| 22  | 1   | NA       | *VERSION BADGE         | Necessary     | 62.00 FL   | *62.00 FL  |
| 23  | 1   | NA       | *SUNDRY PARTS<br>(NPA) | Not Necessary | 0.00 FL    | *- FL      |
| 24  | 1   | NA       | *AUDATEX FEE SN        | Necessary     | 40.00 FS   | *40.00 FS  |
| 25  | 1   | NA       | *BODY JOINT SEALANT SN | Necessary     | 50.00 FS   | *30.00 FS  |
| 26  | 1   | NA       | *MERIMEN FEE SN        | Necessary     | 11.00 FS   | *11.00 FS  |
| 27  | 1   | NA       | *REAR NUMBER PLATE SN  | Not Necessary | 40.00 FS   | *- FS      |
| 28  | 1   | NA       | *REVERSE SENSOR SN     | Broken        | 280.00 FS  | *200.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                 |                 |
|------------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>5,766.00</b> | <b>3,567.00</b> |
| <b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b> | 1,336.25        | 821.50          |
| <b>Total Parts (\$\$)</b>                                  | <b>4,429.75</b> | <b>2,745.50</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

| No                         | Qty | Particulars          | Repairer's   | Amount       |
|----------------------------|-----|----------------------|--------------|--------------|
| <b>Miscellaneous Items</b> |     |                      |              |              |
| 1                          | 1   | OD/TP Case (Insurer) | 11.00        | 11.00        |
| <b>Sub Total (\$\$)</b>    |     |                      | <b>11.00</b> | <b>11.00</b> |

## Recommended Labour

| No                              | Particulars                   | Lab.Type | Repairer's      | Amount          |
|---------------------------------|-------------------------------|----------|-----------------|-----------------|
| <b>Paintwork Labour</b>         |                               |          |                 |                 |
| 1                               | Total Paint Labour            | New      | 645.00          | 650.00          |
| 2                               | Total Paint Materials         | New      | 281.95          | 263.42          |
| <b>Labour Items</b>             |                               |          |                 |                 |
| 3                               | Total Panel/Mechanical Labour | New      | 770.00          | 750.00          |
| <b>Gross Labour Cost (\$\$)</b> |                               |          | <b>1,696.95</b> | <b>1,663.42</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >