

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20010039/ESF3E2

Date: 25/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900168832
Claimant Vehicle No : SLU2213L	Insured Vehicle No :	SMP5497D
Date of Loss: 16/09/2020	Nature of Claim: TP	Claim No: 0328444513SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU2213L	Engine No:	2ZR6837006
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 (A)	Chassis No:	ZVW508026548
Reg. Date:	27/11/2017 (Man. Year: 2016)	Odometer:	287880 km
Colour:	Yellow		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/50 R15	Rear Tyre Size:	195/50 R15
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	18/09/2020	
Date Inspected:	21/09/2020 Inspected At:	Kok Wang Car Grooming (HQ) 1 SOON LEE STREET #06-40 PIONEER CENTRE Singapore 627605
Estimated Period of Repair:	4.0 days	

Adjuster: CHEN TSUE YEE

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*- F
2	1		*REAR BUMPER LAMP (LH)	* Check	0.00 F	*- F
3	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
4	2		*REAR BUMPER SIDE RETAINER	Broken	0.00 F	*- F
5	1		*REAR BUMPER REINFORCEMENT	* Check	0.00 F	*- F
6	1		*REAR BUMPER SPONGE	* Check	0.00 F	*- F
7	1		*REAR BUMPER LOWER COVER	* Check	0.00 F	*- F
8	1		*REAR BUMPER LOWER SPOILER	Cut	0.00 F	*- F
9	1		*REVERSE SENSOR	Broken	0.00 F	*- F
10	1		*REAR END PANEL	Repair	0.00 F	*- F
11	1		*REAR LH TAILLAMP	* Check	0.00 F	*- F
12	1		*TAILGATE	Repair	0.00 F	*- F
13	1		*TAILGATE GARNISH	Broken	0.00 F	*- F
14	1		*TAILGATE LOCK	Bent	0.00 F	*- F
15	1		*TAILGATE RUBBER	* Check	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >