

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20010043/EPA3Q2

Date: 05/11/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SML5209R	Insured Vehicle No :	SHD4283H
Date of Loss: 17/09/2020	Nature of Claim: TP	Claim No: MCT20090264

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML5209R		
Make & Model:	VOLKSWAGEN GOLF GTI, 2.0 TSI (A)	Engine No:	CHH304843
Reg. Date:	24/05/2019 (Man. Year: 2019)	Chassis No:	WVWZZZAUZKW101056
Colour:	White	Odometer:	31159 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,374.84	1,374.84	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,760.00	2,120.00	1,640.00	43.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	5,134.84	3,494.84	1,640.00	31.94
+ GST 7.00/7.00% (\$\$)	359.44	244.64	114.80	31.94
Nett Amount (\$\$)	5,494.28	3,739.48	1,754.80	31.94
+ Car Rental (3.0 x S\$120.00/day) (\$\$)		360.00		
+ Doc/Search Fee (\$\$)		7.45		
+ Other Costs (\$\$)		80.00		
Nett Liability (\$\$)		4,186.93		

INSPECTION

Date of Assignment:	18/09/2020	
Date Inspected:	25/09/2020 Inspected At:	VOLKSWAGEN GROUP SINGAPORE PTE LTD 247 Alexandra Road Singapore 159934

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Oct 2020)
Parts:	144	VOLKSWAGEN GOLF GTI 2.0 TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SML5209R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FOR BUMPER PRIMED	Dented	1,165.55 FS	*1,165.55 FS
2	1		*SENSOR BRACKET	Necessary	12.48 FS	*12.48 FS
3	1		*SENSOR BRACKET	Necessary	12.13 FS	*12.13 FS
4	1		*SENSOR BRACKET	Necessary	12.13 FS	*12.13 FS
5	1		*SENSOR BRACKET	Necessary	12.60 FS	*12.60 FS
6	1		*SENSOR BRACKET	Necessary	12.13 FS	*12.13 FS
7	1		*SENSOR BRACKET	Necessary	12.48 FS	*12.48 FS
8	1		*BONDING AGENT FOR PLASTIC	Necessary	59.40 FS	*59.40 FS
9	1		*2K-PLASTIC ADHESIVE	Necessary	75.94 FS	*75.94 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	1,374.84	1,374.84
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
2	LABOUR	New	1,680.00	840.00
3	SPRAY PAINTING	New	1,600.00	800.00
Gross Labour Cost (\$\$)			3,760.00	2,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >