

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20010044/AES3Q2

Date: 12/04/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800127400
Claimant Vehicle No :	SMP1373D	Insured Vehicle No :	GBE3625C
Date of Loss:	15/09/2020	Nature of Claim:	TP
		Claim No:	6583894874SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP1373D		
Make & Model:	RENAULT SCENIC IV, 1.5 D L DCI SR EU6 (A)	Engine No:	K9KF649D060080
Reg. Date:	11/09/2019 (Man. Year: 2019)	Chassis No:	VF1RFA00562895251
Colour:	Black	Odometer:	79949 km
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R20	Rear Tyre Size:	195/55 R20
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,959.00	4,881.22	7,077.78	59.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,070.00	1,330.00	1,740.00	56.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	15,029.00	6,211.22	8,817.78	58.67
Approved Total (Overridden) (\$\$)		4,950.00		
(\$\$)	15,029.00	4,950.00	10,079.00	67.06
+ GST 7.00/7.00% (\$\$)	1,052.03	346.50	705.53	67.06
Nett Amount (\$\$)	16,081.03	5,296.50	10,784.53	67.06
+ Loss of Use (5.0 x S\$60.00/day) (\$\$)		300.00		
Nett Liability (\$\$)		5,596.50		

INSPECTION

Date of Assignment:	17/09/2020		
Date Inspected:	17/09/2020	Inspected At:	1st Autoworks Pte Ltd (HQ) 23 Kaki Bukit Ave 4, #04-01 Singapore 415933
Estimated Period of Repair:	5.0 days		

4/12/2021

Adjuster Report

Adjuster: ADRIAN LING

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER UPPER	Cut	2,210.80 F	*1,800.50 FL
2	1		*REAR BUMPER LOWER	Not Necessary	1,280.30 F	*- FL
3	20		*REAR BUMPER CLIPS	Necessary	130.00 F	*30.00 FL
4	1		*LHR BUMPER BRACKET	Not Necessary	528.30 F	*- FL
5	1		*LHR TAILLAMP	Not Necessary	1,240.70 F	*- FL
6	1		*LHR FENDER	Dented	2,980.40 F	*2,655.00 FL
7	1		*LHR FENDER LINER	Not Necessary	728.10 F	*- FL
8	3		*LHR FENDER LINER CLIPS	Not Necessary	19.50 F	*- FL
9	1		*LHR QUARTER GLASS W MOULDING & CHROME	Not Necessary	1,210.30 F	*- FL
10	1		*LHR SHOCK ABSORBER	Not Necessary	780.60 F	*- FL
11	1		*LH REAR QUARTER GLASS SEALANT	Necessary	100.00 FS	*40.00 FS
12	1		*LH REAR QUARTER GLASS SOLAR FILM	Not Necessary	120.00 FS	*- FS
13	1		*LH REAR WHEEL TYRE	Cut	250.00 FS	*200.00 FS
14	1		*LH REAR WHEEL RIM	Cut	380.00 FS	*380.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	11,959.00	5,105.50
- List Item Discount on L Items 0.00/5.00% (S\$)	0.00	224.28
Total Parts (S\$)	11,959.00	4,881.22

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION ,TO PANEL BEATING ,RESHAPE ,STRAIGHTEN ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	1,200.00	600.00
2	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA	New	1,000.00	400.00
3	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS ,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	30.00	30.00
4	REMOVE AND REFIX SEAT CUSHION /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIRS	New	250.00	80.00
5	REMOVE AND REPLACE LHR UNDER CARRIAGE PARTS	New	250.00	0.00
6	TO CONDUCT 4 WHEEL ALIGNMENT	New	120.00	80.00
7	TO REMOVE AND REFIT FUEL TANK TO FACILITATE ACCIDENT REPAIR	New	100.00	80.00
8	TO REMOVE AND REFIT REAR QUARTER GLASS DUE TO REPLACEMENT OF REAR FENDER	New	120.00	60.00
Gross Labour Cost (\$\$)			3,070.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >