

## AUTOMOBILE ASSESSMENT REPORT

TO: ZHANG PENG  
C/O: V-TECH AUTO SERVICE  
NO.1 SOON LEE STREET#06-04/05  
PIONEER CENTRE  
SINGAPORE 627605

Our Reference: 0720/VT589  
Date: 30-Jul-2020

### ASSESSMENT OF VEHICLE NO. SME 7147 J

DATE OF LOSS: 14-Jul-2020

We have carried out a physical assessment at V-TECH AUTO SERVICE,  
No. 1 Soon Lee Street #06-04/05 Pioneer Centre Singapore 627605, according to your instruction  
15-Jul-2020 and are pleased to submit our report herewith.

### 1. VEHICLE PARTICULARS

Registration No.: SME 7147 J  
Make & Model: HYUNDAI ELANTRA AD 1.6 GLS AT (AMS)  
Year of Registration: 2018  
Engine Capacity: 1591  
Chassis No.: KMHD841CMJU741630  
Engine No.: G4FGJU251528  
Colour: SILVER  
Mileage (km): 32101

### 2. VEHICLE CONDITION

Body Paint: GOOD  
Steering: SERVICEABLE  
Foot Brake: SERVICEABLE  
Parking Brake: SERVICEABLE  
Modification: NIL

### 3. TYRE PARTICULARS & CONDITION


Front  
RH Make/Size/Thread: NEXEN 195/65 R15 – 80%  
LH Make/Size/Thread: NEXEN 195/65 R15 – 80%  
  
Rear  
RH Make/Size/Thread: NEXEN 195/65 R15 – 80%  
LH Make/Size/Thread: NEXEN 195/65 R15 – 80%

#### 4. DESCRIPTION OF DAMAGE

At the time of the inspection, the vehicle sustained damages to the FRONT and REAR portion.

#### 5. REMARKS

Market Value:	Na
Salvage Value:	Na
Repair Limit:	Na
Estimated Amount:	\$16,955.32
Adjusted Amount:	\$11,025.56
Repair Sum:	\$9,200.00
Estimated Repair Days:	8 days



Pursuant to your instruction, we have **NOT AUTHORISED** repair.

The assessment was conducted on a **"Without Prejudice"** basis.

If we are not notified of anything to the contrary within **14 days** from the date hereof, this report shall be treated as correct.

#### Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by Aeon Auto Consultants LLP for any reliance on this report by any third party.

**ASSESSMENT REPORT FOR VEHICLE NO. SME 7147 J**

**PARTS (LIST ITEMS)**

Qty	Description	Condition	Workshop's Estimate	Our Assessment
1	FRONT BONNET	Repair	1,740.70	-
2	FRONT BONNET SIDE GUIDE RUBBER STOPPER L/R	Reuse	30.00	-
1	FRONT BONNET MECHANISM LOCK	Bent	129.90	129.90
1	FRONT GRILLE	Cracked	460.20	460.20
1	FRONT GRILLE 'LOGO' EMBLEM	Necessary	52.40	52.40
2	FRONT HEADLAMP L/R	Cracked	2,396.00	2,396.00
2	FRONT HEADLAMP LOWER BRACKET L/R	Bent	148.20	148.20
1	FRONT BUMPER	Cracked	528.60	528.60
1	FRONT BUMPER INNER SPONGE	Cracked	117.10	117.10
1	FRONT BUMPER SIDE RETAINER L/R	Bent	84.20	84.20
1	FRONT BUMPER UPPER COVER	Cracked	92.50	92.50
1	FRONT BUMPER UPPER SEAL RUBBER	Necessary	47.20	47.20
1	FRONT BUMPER NUMBER PLATE BRACKET GARNISH	Cracked	38.00	38.00
2	FRONT BUMPER SIDE GARNISH L/R	Cracked	268.40	268.40
1	FRONT BUMPER REINFORCEMENT	Bent	695.80	695.80
1	FRONT BUMPER TOW HOOK COVER	Cracked	29.00	29.00
1	FRONT BUMPER LOWER LID GARNISH	Cracked	272.50	272.50
1	FRONT SUPPORT PANEL	Repair	949.30	-
2	FRONT SUPPORT PANEL AIR GUIDE GARNISH L/R	Cracked	98.20	98.20
1	REAR BOOTLID	Repair	1,782.00	-
2	REAR BOOTLID REFLECTOR L/R	Repair	1,328.00	-
2	REAR BOOTLID INNER RUBBER GUIDE STOPPER L/R	Reuse	76.00	-
1	REAR BOOTLID LOCK STRIKER	Bent	28.60	28.60
1	REAR BOOTLID MECHANISM LOCK	Bent	161.00	161.00
1	REAR BOOTLID WEATHER STRIP	Repair	115.00	-
2	REAR TAILLAMP L/R	Cracked	1,752.00	1,752.00
1	REAR BUMPER	Cracked	560.40	560.40
1	REAR BUMPER TOP BRACKET L/R	Bent	96.00	96.00
1	REAR BUMPER REINFORCEMENT	Cracked	330.00	330.00
2	REAR BUMPER SIDE RETAINER L/R	Bent	88.60	88.60
2	REAR BUMPER REFLECTOR L/R	Cracked	196.00	196.00
1	REAR BUMPER LOWER LID	Cracked	335.10	335.10
1	REAR END PANEL INNER TOP GARNISH	Cut	69.80	69.80
1	REAR END PANEL	Repair	580.00	-
1	REAR FLOOR PANEL TOP BOARD COVER	Repair	498.70	-
			16,175.40	9,075.70
Less 20% discount			3,235.08	1,815.14
Parts Total:			12,940.32	7,260.56

**ASSESSMENT REPORT FOR VEHICLE NO. SME 7147 J**

**SPECIAL NETT ITEMS**

1	FRONT GRILLE CLIPS - SET	Necessary	40.00	40.00
1	FRONT BUMPER UPPER COVER CLIPS - SET	Necessary	50.00	50.00
1	FRONT BUMPER CLIPS - SET	Necessary	50.00	50.00
1	FRONT BUMPER NUMBER PLATE	Bent	25.00	25.00
1	FRONT BUMPER NUMBER PLATE HOLDER	Cracked	50.00	50.00
1	REAR BOOTLID INNER TRIM BOARD CLIPS - SET	Necessary	50.00	50.00
2	REAR TAILLAMP CLIPS L/R - SET	Necessary	100.00	100.00
1	REAR BUMPER CLIPS - SET	Necessary	100.00	100.00
1	REAR BUMPER REVERSE SENSOR - SET	Cracked	350.00	350.00
1	REAR END PANEL INNER TOP GARNISH CLIPS - SET	Necessary	50.00	50.00
Special Nett Total :			<u>865.00</u>	<u>865.00</u>

**LABOUR**


S/N	Description	Workshop's Estimate	Our Assessment
1	To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.	130.00	120.0
2	To remove, reinstall top trim upholstery, cushion seat, trim garnish, trim liner carpet.	100.00	80.0
3	To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,200.00	1,100.0
4	To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1,600.00	1,500.0
5	To apply anti-rust chemical on repaired and replaced panel.	120.00	100.0
Labour Total :		<u>3,150.00</u>	<u>2,900.0</u>
<b>TOTAL (PARTS &amp; LABOUR) \$</b>		<u>16,955.32</u>	<u>11,025.5</u>

The workshop has agreed to undertake the repair on a Lump Sum basis.

The final adjusted Lump Sum contract amount is

**\$9,200.00**

**(SINGAPORE DOLLARS NINE THOUSAND TWO HUNDRED ONLY)**



Amas Ong  
Automobile Assessor