Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20010064/AVF3Q2

Date: 18/02/2021

Engine No:

Odometer:

**REFERENCE** 

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMPCSNA00096702001

Claimant Vehicle No:

SMP4249K

Insured Vehicle No:

ES9120T

Date of Loss:

15/09/2020

Nature of Claim:

TP

Claim No:

SNM20D203385C02

27091030614129

82340 km

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

SMP4249K Reg No:

Make & Model: MERCEDES-BENZ CLA180, 1.6 (R18 BI) (A) Reg. Date:

18/06/2015 (Man. Year: 2015) Chassis No: WDD1173422N190142

Colour:

**Engine Capacity:** 1595 cc Market Value/New Car

Price:

N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification: No

**CONDITION OF TYRES** 

Front Tyre Size: 225/40 R18 225/40 R18 Rear Tyre Size: Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,762.00	6,148.80	613.20	9.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,680.00	1,080.00	600.00	35.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,442.00	7,228.80	1,213.20	14.37
Approved Total (Overridden) (S\$)		5,800.00		
(S\$)	8,442.00	5,800.00	2,642.00	31.30
+ GST 7.00/7.00% (S\$)	590.94	406.00	184.94	31.30
Nett Amount (S\$)	9,032.94	6,206.00	2,826.94	31.30

**INSPECTION** 

Date of Assignment: 19/09/2020

Date Inspected: 18/09/2020 Inspected At: Kang Car Repairers Pte Ltd (HQ) NO.1 KAKI BUKIT AVE 6 #02-06

AUTOBAY @ KAKI BUKIT

Singapore 17883

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING Manager: VERON CHEN Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

# **REPAIR DETAILS**

Reference				
Part Source:	: MRM-SG	Version: 1.0 (Last Synchronised: 18 Feb 2021)		
Parts:	143	MERCEDES-BENZ CLA180 1.6 (R18 BI) (A) (Catalogue:Merimen Singapore 1.0)		
Labour:	Repairer's	(Price-denominated Standard List)		
Print Code:	(Unsubmitted, no print-code for SMP4249K)			
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page			
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *				

# **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT FENDER RH	Distorted	746.00 FL	*746.00 FL
2	1		*FRT FENDER COWLING RH	Deformed	216.00 FL	*216.00 FL
3	1		*FRT FENDER RETAINER RH	Necessary	56.00 FL	*56.00 FL
4	1		*FRT BUMPER	Deformed	1,551.00 FL	*1,551.00 FL
5	1		*FRT BUMPER PARKING SENSOR	Not Necessary	287.00 FL	*- FL
6	1		*FRT BUMPER INNER SIDE RETAINER RH	Necessary	190.00 FL	*190.00 FL
7	1		*FRT BUMPER WIPER SPRAY COVER RH	Not Necessary	78.00 FL	*- FL
8	1		*HEADLAMP RH	Cracked	2,873.00 FL	*2,873.00 FL
9	1		*FRT SPORTS RIM RH	Cut	1,244.70 FS	*1,000.00 FS
10	1		*SET FRT FENDER COWLING CLIPS RH	Necessary	60.00 FS	*40.00 FS
11	1		*SET FRT BUMPER CLIPS	Necessary	60.00 FS	*40.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
				Sub Total (S\$)	7,361.70	6,712.00
	- List Item Discount on L Items 10.00/10.00% (S\$)			599.70	563.20	
				Total Parts (S\$)	6,762.00	6,148.80
Report was unsubmitted during this print-out.						1

Adjuster Report Page 4 of 4

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

#### **Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE AND REPLACE THE DAMAGED PARTS,KNOCK OUT ACCIDENT DENTED PORTIONS A CUTTING/WELDING WORKS	New .ND	750.00	500.00
2	TO SPRAY PAINTING	New	700.00	500.00
3	TO SPRAY UNDERSEAL	New	80.00	0.00
4	TO CHECK WIRING	New	50.00	30.00
5	TO REMOVE AND REPLACE PARKING SENSOR	New	100.00	50.00
	Gross Lal	oour Cost (S\$)	1,680.00	1,080.00
	Report was unsubmitted d	uring this print-out.		

< END OF ESTIMATES >