Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG20010065/UVF3E2

Date: 30/09/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 1000979970

Claimant Vehicle No: GW2716B

Date of Loss: 19/09/2020 Nature of Claim: TP Claim No: 247845

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: YM8758E

Make & Model: ISUZU NNR85UH4A, 3.0 D (M) Engine No: 4JJ1642396

Reg. Date: 04/07/2008 (Man. Year: 2008) Chassis No: JAANNR85H87100289

Colour: White Odometer: 831587 km

Engine Capacity: 2999 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 7.00-R16 Rear Tyre Size: 195 R15 (D)
Front Left Side: Condor 5 mm Rear Left Side: Condor 5/5 mm
Front Right Side: Condor 5 mm Rear Right Side: Condor 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,351.00	2,033.43	6,317.57	75.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,730.00	1,110.00	620.00	35.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,081.00	3,143.43	6,937.57	68.82
Approved Total (Overridden) (S\$)		2,500.00		
(S\$)	10,081.00	2,500.00	7,581.00	75.20
+ GST 7.00/7.00% (S\$)	705.67	175.00	530.67	75.20
Nett Amount (S\$)	10,786.67	2,675.00	8,111.67	75.20

INSPECTION

Date of Assignment: 23/09/2020

Date Inspected: 21/09/2020 Inspected At: Fastech Auto Pte Ltd (HQ)

1 Kaki Bukit Ave 6, #01-46/48/50 Autobay

Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster Report Page 2 of 4

Adjuster: MARCUS CHUA Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference				
Part Source:		(Last Synchronised: 29 Sep 2020)		
Parts:	N/A	ISUZU NNR85UH4A 3.0 D (M) (Model not available in database)		
Labour:	Repairer's	(Price-denominated Standard List)		
Print Code:	Code: (Unsubmitted, no print-code for YM8758E)			
Validity:	ity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page			
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.				

Recommended Parts

Qty	Part No.	Particulars	Condition	Repairer's	Amount
1		*TAILGATE	Badly Dented	3,800.00 F	*1,650.00 FL
1		*TAILGATE LOWER MEMBER	Repair	988.00 F	*- FL
1		*TAILGATE LOCK PANEL O/S	Repair	68.00 F	*- FL
1		*TAILGATE LOCK LOWER L PANEL	Repair	220.00 F	*- FL
1		*TAILLAMP O/S	Cracked	355.00 F	*248.15 FL
1		*TAILGATE 60KM/H STICKER	Necessary	20.00 FS	*10.00 FS
1		*TAILGATE 23 PAX STICKER	Necessary	20.00 FS	*10.00 FS
1		*TAILGATE LOWER WOODEN	Serviceable	880.00 FS	*- FS
1		*REAR STEP WOODEN	Cracked	500.00 FS	*400.00 FS
1		*REAR CHASSIS WOODEN O/S	Not Necessary	1,500.00 FS	*- FS
nchise	part. S=SpcN	ett. L=ListItemDisc.	_		
			Sub Total (S\$)	8,351.00	2,318.15
		- List Item Discount on I	L Items 0.00/15.00% (S\$)_	0.00	284.72
			Total Parts (S\$)	8,351.00	2,033.43
	1 1 1 1 1 1 1 1 1 1	1 1 1	1 *TAILGATE 1 *TAILGATE LOWER MEMBER 1 *TAILGATE LOCK PANEL O/S 1 *TAILGATE LOCK LOWER L PANEL 1 *TAILLAMP O/S 1 *TAILGATE 60KM/H STICKER 1 *TAILGATE 23 PAX STICKER 1 *TAILGATE LOWER WOODEN 1 *REAR STEP WOODEN 1 *REAR CHASSIS WOODEN O/S 1 this part. S=SpcNett. L=ListItemDisc.	1 *TAILGATE Badly Dented 1 *TAILGATE LOWER MEMBER Repair 1 *TAILGATE LOCK PANEL O/S Repair 1 *TAILGATE LOCK LOWER L PANEL Repair 1 *TAILLAMP O/S Cracked 1 *TAILGATE 60KM/H STICKER Necessary 1 *TAILGATE 23 PAX STICKER Necessary 1 *TAILGATE LOWER WOODEN Serviceable 1 *REAR STEP WOODEN Cracked 1 *REAR CHASSIS WOODEN O/S Not Necessary 1 *TAILGATE LOWER WOODEN Cracked 1 *REAR CHASSIS WOODEN O/S Not Necessary 1 *TAILGATE LOWER WOODEN O/S NOT Necessary	1 *TAILGATE Badly Dented 3,800.00 F 1 *TAILGATE LOWER MEMBER Repair 988.00 F 1 *TAILGATE LOCK PANEL O/S Repair 68.00 F 1 *TAILGATE LOCK LOWER L PANEL Repair 220.00 F 1 *TAILLAMP O/S Cracked 355.00 F 1 *TAILGATE 60KM/H STICKER Necessary 20.00 FS 1 *TAILGATE 23 PAX STICKER Necessary 20.00 FS 1 *TAILGATE LOWER WOODEN Serviceable 880.00 FS 1 *REAR STEP WOODEN Cracked 500.00 FS 1 *REAR CHASSIS WOODEN O/S Not Necessary 1,500.00 FS 1 *REAR CHASSIS WOODEN O/S Not Necessary 1,500.00 FS 1 *List Item Discount on L Items 0.00/15.00% (\$\$) 0.00

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CHECK WIRING	New	50.00	20.00
2	TO SPRAY RUST PROOFING	New	80.00	40.00
3	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	800.00	550.00
4	TO PUTTY & SPRAY PAINTING	New	800.00	500.00
	Gross Labour Cost (S\$)		1,730.00	1,110.00
	Report was unsubmitted du	ing this print-out.		

< END OF ESTIMATES >