

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI20010067/UQF3E2**Date:** 05/07/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSN19353319000

Claimant Vehicle No : FBA2892A **Insured Vehicle No :** SLZ5744A

Date of Loss: 30/08/2020 Nature of Claim: TP Claim No: SNM20D203142/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBA2892A**

Make & Model: KTM 950 ADVENTURE, 942cc Engine No: 0460003719

Reg. Date: 17/03/2006 (Man. Year: 2005) Chassis No: VBKVA44034M904412

Colour: Black Odometer: 1065318 km

Engine Capacity: 942 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 90-90-21 Rear Tyre Size: 150-70-18

Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,263.00	7,324.90	9,938.10	57.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	680.00	450.00	230.00	33.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,943.00	7,774.90	10,168.10	56.67
Approved Total (Overridden) (S\$)		6,200.00		
Nett Amount (S\$)	17,943.00	6,200.00	11,743.00	65.45

INSPECTION

Date of Assignment: 18/09/2020

Date Inspected: 21/09/2020 Inspected At: Dirt Wheel Motor Trading (HQ)
Blk 9004 Tampines Street 93, #01-100
Singapore 528838

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 05 Jul 2021)	
Parts:	N/A	KTM 950 ADVENTURE 942cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBA2892A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEAD LAMP PROTECTOR (P.P) (NPA)	Cracked	0.00 F	*- FL
2	1		*SET HAND GUARD (KTM)	Cut	286.00 F	*286.00 FL
3	1		*SET GRIP (KTM/P.P) OPEN	Torn	55.00 F	*55.00 FL
4	1		*THROTTLE TUBE	Torn	33.00 F	*33.00 FL
5	1		*MIRROR (R)	Cut	102.00 F	*102.00 FL
6	1		*HANDLE BAR	Bent	492.00 F	*492.00 FL
7	1		*TANK SPOILER (R)	Cut	616.00 F	*616.00 FL
8	1		*TANK SPOILER SCREW	Necessary	3.00 F	*3.00 FL
9	1		*TANK SPOILER BUSHING	Necessary	8.00 F	*8.00 FL
10	1		*TANK (R)	Cut	2,782.00 F	*2,200.00 FL
11	1		*TANK SLIDER (R)	Cut	13.00 F	*13.00 FL
12	1		*FRONT FENDER	Repair	478.00 F	*- FL
13	1		*FRONT RIM	Cut	831.00 F	*831.00 FL
14	1		*CLUTCH COVER / SMALL	Cut	268.00 F	*268.00 FL
15	1		*CLUTCH COVER MOULDING	Necessary	20.00 F	*20.00 FL
16	4		*ENGINE OIL (50%)	Necessary	120.00 FS	*60.00 FS
17	1		*BRAKE PEDAL STEP (P.P)	Bent	68.00 F	*68.00 FL
18	1		*FOOTREST / FRONT / RH	Cut	78.00 F	*78.00 FL
19	1		*FOOTREST BRACKET / REAR / (R)	Cut	247.00 F	*247.00 FL
20	1		*FOOTREST PLATE	Bent	13.00 F	*13.00 FL
21	1		*FOOTREST / REAR / (R)	Bent	133.00 F	*133.00 FL
22	1		*SIDE COVER / REAR / (R)	Cut	581.00 F	*581.00 FL
23	1		*AKRAPORIC EXHAUST (LOCAL REPAIR)	Dented	3,926.00 FS	*100.00 FS
24	1		*TOP BOX	Cut	780.00 F	*780.00 FL
25	1		*SIGNAL LIGHT / REAR / (R)	Cut	69.00 F	*69.00 FL
26	1		*TANK SPOILER (L)	Cut	616.00 F	*616.00 FL
27	1		*WIND SCREEN	Cracked	221.00 F	*221.00 FL
28	1		*REAR HANDLE GRIP	Serviceable	95.00 F	*- FL
29	1		*TANK TOP COVER	Repair	107.00 F	*- FL
30	1		*TANK (L)	Repair	2,782.00 F	*- FL
31	1		*BRAKE PEDAL	Bent	228.00 F	*228.00 FL
32	1		*METER	Not Necessary	1,212.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	17,263.00	8,121.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	796.10
Total Parts (\$\$)	17,263.00	7,324.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR WITH RIM ALIGNMENT	New	680.00	450.00
Gross Labour Cost (\$\$)			680.00	450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >